

Figure - 开发 Dev #110639

开发 Dev # 110122 (New): 【MK】 管理总票
开发 Dev # 110125 (New): 【MK】 【BSP】 管理总票
开发 Dev # 110638 (解决 Resolved): 【MK】 【008】 【BOOT】 主任务
【MK】 【008】 【BOOT】 【TC-RID: 1201-0100801】 启动相关设置
2022-07-25 11:01 - CD TPM-申艳艳

Status:	完成 Closed	Start date:	2022-07-25
Priority:	Normal	Due date:	2022-08-01
Assignee:	CD BSP-唐金泽	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
请填写信息： ■需求列表： https://thundersoft.feishu.cn/sheets/shtcnqaFyklnSnMcKWlulCI3xnc L7 1.使用QFIL工具能进行刷机 2.dut设备能进入launcher 3.内存和flash显示容量与SPEC一致 1.adb shell命令可用 2.dumpsys meminfo或者root用户下执行procrank ■提出URL：必填 ■自测case：必填 ■注意点：需要测试注意的前提条件			

History

- #1 - 2022-07-25 12:07 - CD TPM-申艳艳
- Parent task set to #110638
- #2 - 2022-07-25 12:14 - CD TPM-申艳艳
- Description updated
- #3 - 2022-08-02 13:16 - SZ TPM-罗云进
- Due date set to 2022-08-01
- Status changed from New to 解决 Resolved
- % Done changed from 0 to 100
- #4 - 2022-08-02 14:23 - SZ TPM-罗云进
- Assignee changed from SZ TPM-罗云进 to SZ 系统-张丽果
- #5 - 2022-08-04 21:24 - CD TPM-申艳艳
- Subject changed from 【MK】 【008】 【BOOT】 【TC-RID: 0301-0100801】 启动相关设置 to 【MK】 【008】 【BOOT】 【TC-RID: 1201-0100801】 启动相关设置
- #6 - 2022-09-20 18:40 - CD BSP-杜磊
- Status changed from 解决 Resolved to 进行中 In Progress
- #7 - 2022-09-21 11:39 - CD BSP-杜磊
- Status changed from 进行中 In Progress to 解决 Resolved
- #8 - 2022-09-22 19:41 - SZ TPM-罗云进

- Status changed from 解决 Resolved to 完成 Closed

#9 - 2022-11-16 13:34 - CD BSP-唐金泽

- Assignee changed from SZ 系统-张丽果 to CD BSP-唐金泽

合入，去除PMIC 8150B芯片的代码；
https://dev.thundercomm.com/gerrit/c/general/boot_images/+/163170

Visional_RC PMIC: Compatible with PMIC-RM¹

- 1.No PMIC does not affect bootup;
- 2.Using pmic-id to identify different device trees;
- 3.PM8250-gpio10 use for USB check, instead of KEY-VUP;

Test Result: 1.The PMIC board is boot normally and USB normal;
2.Remove the PMIC boardis boot normally and USB normal;

#10 - 2022-12-06 20:06 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
167747	general/boot_images	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangjz1204@thundersoft.com
BSP:XBL: Exchange Power Key debounce time 1200->500msexchange Power Key debounce time 1200->500msTC-RID: 1201-0100801IssueID: TS-R-DF-110639Change-Id: If66dcbf84deff4a9d01df299fd540f1a867e17c7			

#11 - 2022-12-06 20:06 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
167639	general/boot_images	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangjz1204@thundersoft.com
Revert System: bug fix boot failureThis reverts commit f5d167027ca618da26e364c689db465d494b765e.Reason for revert: Fix with suitable method to Optimize boot timeTC-RID: 1201-0100801IssueID: TS-R-DF-110639Change-Id: I6fb087daea1fa9687d6651fa07bc6a51930b566f			

#12 - 2022-12-07 15:04 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
168242	general/boot_images	Pre_figure_turbox-c2130c-la1.1-vendor-ftm-dvt1	tangjz1204@thundersoft.com

Revert System: bug fix boot failureThis reverts commit f5d167027ca618da26e364c689db465d494b765e.Reason for revert: Fix with suitable method to Optimize boot timeTC-RID: 1201-0100801IssueID: TS-R-DF-110639Change-Id: I6fb087daea1fa9687d6651fa07bc6a51930b566f(cherry picked from commit 0214e2ed975ac00b8115f39582ce343209999795)

#13 - 2022-12-07 15:05 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
168243	general/boot_images	Pre_figure_turbox-c2130c-la1.1-vendor-ftm-dvt1	tangjz1204@thundersoft.com
BSP:XBL: Exchange Power Key debounce time 1200->500msexchange Power Key debounce time 1200->500msTC-RID: 1201-0100801IssueID: TS-R-DF-110639Change-Id: If66dcfb84deff4a9d01df299fd540f1a867e17c7(cherry picked from commit 202d501be0ba74fab4891a63ac378ded65eb0a52)			

#14 - 2022-12-22 20:53 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
163170	general/boot_images	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangjz1204@thundersoft.com
Visional_RC PMIC: Compatible with PMIC-RM11.No PMIC does not affect bootup;2.Using pmic-id to identify different device trees;3.PM8250-gpio10 use for USB check, instead of KEY-VUP;Test Result: 1.The PMIC board is boot normally and USB normal; 2.Remove the PMIC boardis boot normally and USB normal;TC-RID: 1201-0100801IssueID: TS-R-DF-110639Change-Id: Iae6aac377c16b0d45787797d5683cc48a77c1d06(cherry picked from commit 909221424f1f098bb9948e7b76899e25365f9679)			

#15 - 2022-12-22 20:53 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
163500	general/boot_images	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangjz1204@thundersoft.com

System: bug fix boot failure1. Remove kdpwr s3 set;2. set CBL pull down;Test Result:reboot normally.TC-RID: 1201-0100801IssueID:
TS-R-DF-110639Change-Id: I5641d1316e2b82919bc33ce40e4ba1039eab1e3f