

Figure - 开发 Dev #110641

开发 Dev # 110122 (New): 【MK】 管理总票
开发 Dev # 110125 (New): 【MK】 【BSP】 管理总票
开发 Dev # 110638 (解决 Resolved): 【MK】 【008】 【BOOT】 主任务
【MK】 【008】 【BOOT】 【TC-RID: 1201-0100804】 fasboot功能设置
2022-07-25 12:11 - CD TPM-申艳艳

Status:	完成 Closed	Start date:	2022-07-25
Priority:	Normal	Due date:	2022-08-01
Assignee:	SZ 系统-张丽果	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
请填写信息： ■需求列表： https://thundersoft.feishu.cn/sheets/shtcnqaFyklNSnMcKWlulCI3xnc L11 使用fastboot进行刷机 ■提出URL：必填 ■自测case：必填 ■注意点：需要测试注意的前提条件			

History

- #1 - 2022-07-25 12:15 - CD TPM-申艳艳
- Description updated
- #2 - 2022-08-02 13:18 - SZ TPM-罗云进
- Due date set to 2022-08-01
- Status changed from New to 解决 Resolved
- % Done changed from 0 to 100
- #3 - 2022-08-02 14:24 - SZ TPM-罗云进
- Assignee changed from SZ TPM-罗云进 to SZ 系统-张丽果
- #4 - 2022-08-04 21:23 - CD TPM-申艳艳
- Subject changed from 【MK】 【008】 【BOOT】 【TC-RID: 0301-0100804】 fasboot功能设置 to 【MK】 【008】 【BOOT】 【TC-RID: 1201-0100804】 fasboot功能设置
- #5 - 2022-09-22 19:42 - SZ TPM-罗云进
- Status changed from 解决 Resolved to 完成 Closed
- #6 - 2022-12-22 20:52 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
161764	general/turbox/tools/build_script/devi ce	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	tangjz1204@thundersoft.com
BSP:BOOT: Fix turbox_flash.sh to Fastboot Fail(1/2)fix turbox_flash to fastboot failTC-RID: 1201-0100804IssueID: TS-R-DF-110641Change-Id: If754bf72c265cedf8cf14a3724fc121288adeb06			

Gerrit Merge Information :

ID	Project	Branch	Uploader
161767	general/turbox/tools/build_script/platform	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangjz1204@thundersoft.com
BSP:BOOT: Fix turbox_flash.sh to Fastboot Fail(2/2)fix turbox_flash to fastboot failTC-RID: 1201-0100804IssueID: TS-R-DF-110641Change-Id: If4b7cfe756029f711c133d84659d2f7628d1fb90			