

Figure - 开发 Dev #110642

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110125 (New): 【MK】【BSP】管理总票

开发 Dev # 110638 (解决 Resolved): 【MK】【008】【BOOT】主任务

【MK】【008】【BOOT】【TC-RID: 0301-0100805】recovery功能设置

2022-07-25 12:13 - CD TPM-申艳艳

Status:	解决 Resolved	Start date:	2022-07-25
Priority:	Normal	Due date:	
Assignee:	移动测试一组_CDTS 刘强	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_update_20221130		
Description			
请填写信息：			
■ 需求列表:			
https://thundersoft.feishu.cn/sheets/shtcnqaFykINsnMcKWLuICl3xnc L13			
删除recovery功能			
■ 提出URL：必填			
■ 自测case：必填			
■ 注意点：需要测试注意的前提条件			
Related issues:			
Related to Figure - Bug # 113946: 【AF】【EVT】【设置】恢复出厂设置功能无效		CLOSED	2022-11-14 2022-11-21

History

- #1 - 2022-08-02 14:24 - SZ TPM-罗云进
- Assignee changed from SZ TPM-罗云进到 SZ 系统-张丽果
- #2 - 2022-09-21 11:43 - CD BSP-杜磊
- Assignee changed from SZ 系统-张丽果到 CD BSP-丁武伟
- #3 - 2022-11-07 21:04 - CD BSP-唐金泽
- Status changed from New to 进行中 In Progress
- Assignee changed from CD BSP-丁武伟到 CD BSP-唐金泽
- Target version set to VX1_MCE_FSE_V3.0_update_20221130
- 强制不进入 recovery 模式；
- #4 - 2022-11-08 21:13 - CD BSP-唐金泽
- Status changed from 进行中 In Progress to 解决 Resolved
- % Done changed from 0 to 90
- <https://dev.thundercomm.com/gerrit/c/general/abl/tianocore/edk2/+160864>
- 修改patch，禁止进入recovery模式，强制赋值recovery标志位=1。
- #5 - 2022-11-08 21:13 - CD BSP-唐金泽
- 强制赋值recovery标志位=0，写错了

#6 - 2022-11-10 09:54 - CD BSP-唐金泽

- Status changed from 解决 Resolved to 完成 Closed

- % Done changed from 90 to 100

#7 - 2022-11-18 17:05 - CD BSP-唐金泽

背景：

recovery 功能影响：

1.用户界面 “ 恢复出厂设置 ” 功能，依赖recovery模式；

2.POWERWASH，依赖recovery模式；

反馈至客户后，2022-11-18 中午11：47和客户（黄骏）会议沟通，客户口头承诺，只要满足：

1.recovery 用户进入接口被限制（已达成，adb reboot recovery用户无法使用，按键加开机组合项目未暴露按键）；

2.recovery 没有用户界面（已达成，UEFI阶段没有显示界面）；

那么可以恢复recovery功能。

提交：

<https://dev.thundercomm.com/gerrit/c/general/abl/tianocore/edk2/+163856>

验证：

本地已验证通过。

启用Recovery后，将修复无法恢复出厂设置bug；

研发同学可以调试进入fastbootd模式。

#8 - 2022-12-22 20:50 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
160864	general/abl/tianocore/edk2	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangjz1204@thundersoft.com
BSP:BOOT: Force Denied to Enter Recovery ModeForce denied to enter recovery mode by FiugreTC-RID: 0301-0100805IssueID: TS-R-DF-110642Change-Id: la3a162cd9c8402a29c9492598d2fe2b5d67e1622			

#9 - 2022-12-22 20:53 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
163856	general/abl/tianocore/edk2	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangjz1204@thundersoft.com
Revert "BSP:BOOT: Force Denied to Enter Recovery Mode" This reverts commit e6384620aeab90a3d46fc6e44288ce66be93df9.Reason for revert: bug TS-R-DF-113946 and customer confirmedTC-RID: 0301-0100805IssueID: TS-R-DF-110642Change-Id: I01934ce7553d73e6117a5c1d152367ed78fa6934			

#10 - 2023-01-06 15:52 - CD BSP-杜磊

- Status changed from 完成 Closed to 进行中 In Progress

#11 - 2023-01-06 15:52 - CD BSP-杜磊

- Assignee changed from CD BSP-唐金泽 to CD BSP-杜磊
- % Done changed from 100 to 80

#12 - 2023-01-07 14:28 - CD BSP-杜磊

本地测试验证OK，代码提交需要申请分支后才能提交

#13 - 2023-01-10 13:41 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
175228	general/platform/bootable/recovery	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dulei0503@thundersoft.com
BSP:Display: Turn off panel in recovery modeTurn off panel in recovery modeTC-RID: 0301-0100805IssueID: TS-R-DF-110642Change-Id: I67adf5b0e33df72a919c11af22227ff878a7c4cb			

#14 - 2023-02-16 17:34 - CD BSP-杜磊

- Status changed from 进行中 In Progress to 解决 Resolved
- Assignee changed from CD BSP-杜磊 to 移动测试一组_CDTS 刘强
- % Done changed from 80 to 100