

Figure - 开发 Dev #110659

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110125 (New): 【MK】【BSP】管理总票

开发 Dev # 110657 (进行中 In Progress): 【MK】【004】【TP】主任务

【MK】【004】【TP】【TC-RID: 1201-0100405】TP坐标值校准

2022-07-25 13:02 - CD TPM-申艳艳

Status:	解决 Resolved	Start date:	2022-07-25
Priority:	Normal	Due date:	
Assignee:	CD BSP-余霄	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
请填写信息：			
■ 需求列表:			
https://thundersoft.feishu.cn/sheets/shtcnqaFykINSnMcKWLuICl3xnc L39			
TP坐标值校准			
■ 提出URL：必填			
■ 自测case：必填			
■ 注意点：需要测试注意的前提条件			

History

#1 - 2022-08-02 14:20 - SZ TPM-罗云进

- Assignee changed from SZ TPM-罗云进 to SZ BSP-徐季源

#2 - 2022-08-04 21:28 - CD TPM-申艳艳

- Subject changed from 【MK】【004】【TP】【TC-RID: 0301-0100405】TP坐标值校准 to 【MK】【004】【TP】【TC-RID: 1201-0100405】TP坐标值校准

#3 - 2022-09-05 09:52 - SZ BSP-徐季源

- Assignee changed from SZ BSP-徐季源 to CD BSP-唐金泽

#4 - 2022-09-08 22:59 - CD BSP-唐金泽

- Assignee changed from CD BSP-唐金泽 to CD BSP-余霄

#5 - 2022-10-27 21:57 - CD BSP-唐金泽

- Status changed from New to 进行中 In Progress

- % Done changed from 0 to 50

MCE_VX1优化已完成

VC1效果问题，依赖客户更新样品效果

#6 - 2022-11-17 19:04 - CD BSP-余霄

- Status changed from 进行中 In Progress to 解决 Resolved

- % Done changed from 50 to 100

VC1固件已升级且合入版本当中，开机自动升级，同时不会对快速样件产生影响。

<https://dev.thundercomm.com/gerriit/c/general/vendor/thundercomm/products/figure/+/161343>

#7 - 2022-12-22 20:51 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
161343	general/vendor/thundercomm/produ ts/figure	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	xiao.yu@thundersoft.com
BSP:TP: Update Firmware to FC63CD1.Fix touch jitter problem2.Optimize the coordinates of the left touch pointTC-RID: 1201-0100401IssueID: TS-R-DF-110659Change-Id: I306b5d71ed3c9e3967fca492b1d19f3a30d255c7			

#8 - 2023-01-16 14:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
174001	general/vendor/thundercomm/produ ts/figure	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	xiao.yu@thundersoft.com
BSP:TP: Update vc1 touchscreen firmware to 1B6EACAdd Curve Compensation ParametersTC-RID: 1201-0100401IssueID: TS-R-DF-110659Change-Id: Ic530409b22de6d3e94a5eb131b7d5b229da4b3c7			

#9 - 2023-01-16 14:35 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
161348	general/clo/la/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	xiao.yu@thundersoft.com
BSP:TP: Update touch driver configurationUpdate touch driver configurationTC-RID: 1201-0100401IssueID: TS-R-DF-110659Change-Id: Ia2cb5271d00d8a82dbddfbef2f24ec8437ff39fc			

#10 - 2023-06-26 17:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209638	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	xiao.yu@thundersoft.com
BSP:TP: Fix dsi max96755 lock and tp check reduceTp check reduceTC-RID: 1201-0100401IssueID: TS-R-DF-110659, IOVDEV-35807Change-Id: I0ed0b9dcccdef57ab835876f7b4da9fb5a6e8554			

#11 - 2023-06-26 17:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209622	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com
BSP:TP: Update vc1 touchscreen firmware to 8852d1Fix abnormal reporting issuesTC-RID: 1201-0100401IssueID: TS-R-DF-110659, IOVDEV-35807Change-Id: Idbb58ca5268f75b2f1cf6f7febe3eb131124a4ba			

#12 - 2023-06-26 18:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209797	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxi0510@thundersoft.com
BSP:TP: Fix dsi max96755 lock and tp check reduceTp check reduceTC-RID: 1201-0100401IssueID: TS-R-DF-110659, IOVDEV-35807Change-Id: I0ed0b9dcccdef57ab835876f7b4da9fb5a6e8554(cherry picked from commit a9a5924764481c0ebc6e87535ab9ef33743082db)			

#13 - 2023-06-26 18:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209798	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxi0510@thundersoft.com
BSP:TP: Update vc1 touchscreen firmware to 8852d1Fix abnormal reporting issuesTC-RID: 1201-0100401IssueID: TS-R-DF-110659, IOVDEV-35807Change-Id: Idbb58ca5268f75b2f1cf6f7febe3eb131124a4ba(cherry picked from commit d3eebba9080f78e7beba9dc98462a14e42675f3b)			

#14 - 2023-06-28 20:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210914	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com
BSP:TP: Add sensitivity update functionFix the issue of not being able to update sensitivity parametersduring the first upgradeTC-RID: 1201-0100401IssueID: TS-R-DF-110659, IOVDEV-10981Change-Id: Id894b82528dddcdb2d9a10cc78b428a9ecab4b0a9			

#15 - 2023-06-28 21:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210850	general/vendor/thundercomm/produ ts/figure	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	wangxl0510@thundersoft.com
Revert BSP:TP: Update vc1 touchscreen firmware to 8852d1This reverts commit d3eebba9080f78e7beba9dc98462a14e42675f3b.Reason for revert: Old screen not adaptTC-RID: 1201-0100401IssueID: TS-R-DF-110659, IOVDEV-35807Change-Id: I077ca9319cb7d7dd30f1e3af6b72c6681ec354e0			

#16 - 2023-06-30 16:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210857	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendo r-release_sorp	wangxl0510@thundersoft.com
BSP:TP: Add sensitivity update functionFix the issue of not being able to update sensitivity parametersduring the first upgradeTC-RID: 1201-0100401IssueID: TS-R-DF-110659, IOVDEV-10981Change-Id: Id894b82528dddc2d9a10cc78b428a9ecab4b0a9(cherry picked from commit 3350a81c0dad63ea70d413c3c2cd283b750e336)			

#17 - 2023-06-30 16:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210851	general/vendor/thundercomm/produ ts/figure	Pre_figure_turbox-c2130c-la1.1-vendo r-release_sorp	wangxl0510@thundersoft.com
Revert BSP:TP: Update vc1 touchscreen firmware to 8852d1This reverts commit d3eebba9080f78e7beba9dc98462a14e42675f3b.Reason for revert: Old screen not adaptTC-RID: 1201-0100401IssueID: TS-R-DF-110659, IOVDEV-35807Change-Id: I077ca9319cb7d7dd30f1e3af6b72c6681ec354e0			

#18 - 2023-06-30 23:11 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
211632	general/vendor/thundercomm/produ ts/figure	Pre_figure_turbox-c2130c-la1.1-vendo r-release_sorp	wangxl0510@thundersoft.com

BSP:TP: Update vc1 touchscreen firmware to 910821Fix abnormal reporting issuesTC-RID: 1201-0100401IssueID: TS-R-DF-110659, IOVDEV-35807Change-Id: l1e4c113c9356f4dff3ca32be16f77300f3819455

#19 - 2023-07-03 15:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
211902	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
Revert BSP:TP: Update vc1 touchscreen firmware to 910821This reverts commit 47f23eccc00c31f92a688cc88e403bf852cc6df5.Reason for revert: <use old firmware>TC-RID: 1201-0100401IssueID: TS-R-DF-110659, IOVDEV-35807Change-Id: lb2bf8b329d8ab3dce0deba766406790c482078db			

#20 - 2023-07-21 22:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
211435	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com
BSP:TP: Update vc1 touchscreen firmware to 910821Fix abnormal reporting issuesTC-RID: 1201-0100401IssueID: TS-R-DF-110659, IOVDEV-35807Change-Id: l1e4c113c9356f4dff3ca32be16f77300f3819455			

#21 - 2023-07-21 22:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216826	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
Revert Revert BSP:TP: Update vc1 touchscreen firmware to 910821This reverts commit ce9fbfd4379bc9511dc4677b53dfd59ac9d778b3.Reason for revert: <use new tp for 0126>TC-RID: 1201-0100401IssueID: TS-R-DF-110659, IOVDEV-35807Change-Id: l7606db5589f071779b2c1184001ff7c0ad89ce52			

#22 - 2023-08-21 15:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
304840	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com

BSP:TP: Increase transparent transmission detectionIncrease transparent transmission detection when panel offTC-RID: 1201-0100401IssueID: TS-R-DF-110659,
IOVDEV-14742Change-Id: I90f1876bea96daebe399ecb9b238a6abd1d18813

#23 - 2023-08-22 18:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
305339	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
BSP:TP: Increase transparent transmission detectionIncrease transparent transmission detection when panel offTC-RID: 1201-0100401IssueID: TS-R-DF-110659, IOVDEV-14742Change-Id: I90f1876bea96daebe399ecb9b238a6abd1d18813(cherry picked from commit ade91e4ccb7d8fbe55a041d98d84709bb0d76ed8)			