

Figure - 开发 Dev #110663

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110125 (New): 【MK】【BSP】管理总票

开发 Dev # 110660 (New): 【MK】【027】【MCU】主任务

【MK】【027】【MCU】【TC-RID: 1201-0102703】电源控制

2022-07-25 13:09 - CD TPM-申艳艳

Status:	New	Start date:	2022-07-25
Priority:	Normal	Due date:	
Assignee:	CD BSP-陈杰	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:			

Description

请填写信息：

■ 需求列表:

<https://thundersoft.feishu.cn/sheets/shtcnqaFykINSnMcKWLuICl3xnc> L53

电源控制

■ 提出URL：必填

■ 自测case：必填

■ 注意点：需要测试注意的前提条件

History

#1 - 2022-08-02 15:00 - SZ TPM-罗云进

- Category changed from 714 to 709

- Assignee changed from SZ TPM-罗云进到 SZ BSP-徐季源

#2 - 2022-08-04 21:30 - CD TPM-申艳艳

- Subject changed from 【MK】【029】【MCU】【TC-RID: 0301-0102903】电源控制到 【MK】【029】【MCU】【TC-RID: 1201-0102703】电源控制

#3 - 2022-08-04 21:33 - CD TPM-申艳艳

- Subject changed from 【MK】【029】【MCU】【TC-RID: 1201-0102703】电源控制到 【MK】【027】【MCU】【TC-RID: 1201-0102703】电源控制

#4 - 2022-09-13 09:52 - SZ BSP-徐季源

- Assignee changed from SZ BSP-徐季源到 CD BSP-陈杰

#5 - 2022-09-28 16:36 - CD BSP-陈杰

- % Done changed from 0 to 100

目前已经完成上下电时序，电压保护功能。

#6 - 2022-12-22 20:38 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
152609	Pre_figure/mcu	Pre_figure_turbox-c2130c-la1.1-vendor-dev	jie.chen@thundersoft.com

BSP:MCU: MCU code buring up, storage, and feature integrationThis commit protects the following functions:1. Buring up of MCU code2. Solve the power-on and power-on sequence bug3. Increase the voltage protection function4. MCU firmware upgrade functionTC-RID: 1201-0102701TC-RID: 1201-0102703TC-RID: 1201-0102704IssueID: TS-R-BUG-111416IssueID: TS-R-BUG-111734IssueID: TS-R-BUG-111732IssueID: TS-R-BUG-112002IssueID: TS-R-DF-111421IssueID: TS-R-DF-112099IssueID: TS-R-DF-110660IssueID: TS-R-DF-110663IssueID: TS-R-DF-110664Change-Id: Iacb3bbd40b9278405f21f5d34d741dfe08c3c4ff

#7 - 2022-12-22 20:39 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152787	general/vendor/tc/mcu	Pre_figure_turbox-c2130c-la1.1-vendor-dev	jje.chen@thundersoft.com

BSP: MCU: Add firmware for MCU programming and upgradeThe firmware version information is V0.0.1, which is the initial version. Implementation function:1. Increase the power-on sequence2. Increase the voltage protection function3. Add version informationTC-RID: 1201-0102701TC-RID: 1201-0102703TC-RID: 1201-0102704IssueID: TS-R-BUG-111416IssueID: TS-R-BUG-111734IssueID: TS-R-BUG-111732IssueID: TS-R-BUG-112002IssueID: TS-R-DF-111421IssueID: TS-R-DF-112099IssueID: TS-R-DF-110660IssueID: TS-R-DF-110663IssueID: TS-R-DF-110664Change-Id: I047b1483f36d87a7a080b1470eb836cbc620a06e

#8 - 2022-12-22 20:42 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154928	Pre_figure/mcu	Pre_figure_turbox-c2130c-la1.1-vendor	jje.chen@thundersoft.com

BSP:MCU: Functional integration version of the MCUThis version contains the following functions:1.Improve the overvoltage protection function and increase the over-voltage protection communication with the MMU;2.Improve the function of power-on and power-up sequence, and fix the problem that the boot screen is not displayed;3.increase the can communication through, currently only open the can's transceiver, there is no integration of other can's functions.TC-RID: 1201-0102701TC-RID: 1201-0102703TC-RID: 1201-0102704IssueID: TS-R-BUG-111416IssueID: TS-R-BUG-111734IssueID: TS-R-BUG-111732IssueID: TS-R-BUG-112002IssueID: TS-R-DF-111421IssueID: TS-R-DF-112099IssueID: TS-R-DF-110660IssueID: TS-R-DF-110663IssueID: TS-R-DF-110664Change-Id: I0c7022c0c6e09e54f1b390deb1fb0df27ece4a38