

Status:	CLOSED	Start date:	2022-08-11
Priority:	Urgent	Due date:	
Assignee:	SZ BSP-徐季源	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	2022.08.07
Resolution:	--	Degrated:	--
Severity:	Major	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	Bring Up Test	Root cause:	
Description			
MCU晶振Y2未起振			

History

- #1 - 2022-08-22 14:26 - SZ HW Test-曾小文
- Assignee set to SZ BSP- 徐季源
- 已解决的BUG请走正常流程关闭即可，不要把指派人删除！
- #2 - 2022-08-23 16:25 - SZ HW Test-曾小文
- Subject changed from MCU晶振Y2未起振 to 【Figure】【EVT】【SI】MCU晶振Y2未起振
- #3 - 2022-08-26 09:43 - SZ BSP-徐季源
- Status changed from New to RESOLVED
- % Done changed from 0 to 100
- 晶振未启震的原因是clock source没有选择外部晶振而是内部晶振
- #4 - 2022-09-05 11:09 - 项目二组_SD3 曾小文
- Status changed from RESOLVED to VERIFIED
- #5 - 2022-09-05 11:10 - 项目二组_SD3 曾小文
- Status changed from VERIFIED to CLOSED
- 修改MCU软件后复测PASS
- #6 - 2022-09-14 11:25 - CD TPM-申艳艳
- Category set to BSP