

Figure - Bug #111274

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110875 (New): BSP-BVT测试-TP

【BSP】 【EVT】 【TP】 【必现】 TP使用一段时间后卡顿滞后明显，无法正常操控

2022-08-16 15:39 - SZTS_TEST 邹涛

Status:	CLOSED	Start date:	2022-08-16
Priority:	High	Due date:	
Assignee:	SZTS_TEST 邹涛	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V1.0_update_20220925	Found Version:	0.0.0.20220816_alpha_private
Need_Info:		Degrated:	
Resolution:		Verified Version:	
Severity:	Critical	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	Bring Up Test		
Description			
前置条件：			
1、 DUT处于开机状态且TP功能正常			
2、 开发者模式内开启坐标和轨迹			
操作步骤：			
1、 开机状态下正常使用TP，一段时间后查看TP灵敏度			
实际结果			
1、 TP使用一段时间后，卡顿滞后明显；无法正常操控			
预期结果：			
1、 TP使用过程中不会发生卡顿和滞后，反应灵敏			

History

#1 - 2022-08-16 15:58 - SZTS_TEST 邹涛

- Tracker changed from 测试 Test-IT to Bug
- Severity set to Critical
- Reproducibility set to Every time
- Test Type set to Bring Up Test
- Found Version set to 0.0.0.20220816_alpha_private

#2 - 2022-08-31 11:16 - CD TPM-申艳艳

- Assignee changed from SZ BSP-徐季源 to CD BSP-唐金泽

Hi 金泽,

之前修改的只是临时方案，只是把trace关了，需要重新调查

<https://dev.thundercomm.com/gerrit/c/general/device/qcom/common/+/142236>

#3 - 2022-08-31 15:58 - CD BSP-唐金泽

- Assignee changed from CD BSP-唐金泽 to CD BSP-余霄

后续TP性能优化的部分，请余霄进行跟进吧

#4 - 2022-09-14 10:40 - CD BSP-唐金泽

- Status changed from New to RESOLVED
- Assignee changed from CD BSP-余霄 to SZTS_TEST 邹涛

请邹涛再行验证

#5 - 2022-09-14 14:40 - SZTS_TEST 邹涛

- Status changed from RESOLVED to VERIFIED

VX1 0904号release版本已经验证该bug已修复，关闭该bug

#6 - 2022-09-14 14:41 - SZTS_TEST 邹涛

- Status changed from VERIFIED to CLOSED

#7 - 2022-09-15 18:42 - CDTS-TEST 周婷

- Target version changed from 591 to VX1_MCE_FSE_V1.0_update_20220925