Figure - Bug #111426

【Figure】【EVT】【ENET】以太网和部分路由器不兼容

2022-08-24 10:35 - SZ HW Test-曾小文

Status: CLOSED Start date: 2022-08-24

Priority: High Due date:

Assignee: SZ HW Test-曾小文 % Done: 0% Category: BSP Estimated time: 0.00 hour

Target version:

Need_Info: -- Found Version: 2022.08.19

Resolution: -- Degrated: --

Severity:MajorVerified Version:Reproducibility:Every timeFixed Version:Test Type:Release TestRoot cause:

Description

EMC测试时,发现以太网和部分路由器不兼容,不能ping通网络,但是路由器功能正常。

该路由器型号:品牌:FAST(友佳联),型号:FW325R

History

#1 - 2022-09-06 14:56 - SZ BSP-刘世江

- Status changed from New to NEED_INFO

是否能提供该路由器品牌:FAST(友佳联),型号:FW325R?

BSP的路由器未复现此问题。

#2 - 2022-09-14 10:24 - SZ TPM-罗云进

- Assignee changed from SZ BSP-刘世江 to CD BSP-唐金泽

#3 - 2022-09-14 11:11 - CD TPM-申艳艳

- Category set to BSP

#4 - 2022-09-14 13:24 - SZ HW Test-曾小文

- Status changed from NEED_INFO to RESOLVED

设备VLAN网段是192.168.1.1,和路由器网段192.168.1.1冲突,后续设备网段改成10.0.0.1

#5 - 2022-09-14 13:24 - SZ HW Test-曾小文

- Status changed from RESOLVED to VERIFIED

#6 - 2022-09-14 13:24 - SZ HW Test-曾小文

- Status changed from VERIFIED to CLOSED

#7 - 2023-03-30 13:49 - CD BSP-**唐金泽**

- Assignee changed from CD BSP- 唐金泽 to SZ HW Test- 曾小文

2025-07-04 1/1