

Figure - Bug #111436

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110877 (New): BSP-BVT测试-MCU

【BSP】【EVT】【MCU】【必现】MCU升级完成后，未自动掉电重启

2022-08-24 20:17 - SZTS_TEST 邹涛

Status:	CLOSED	Start date:	2022-08-24
Priority:	High	Due date:	
Assignee:	SZ BSP-徐季源	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0.0.0.20220824_alpha_private_userdebug
Resolution:	--	Degrated:	--
Severity:	Major	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	Bring Up Test	Root cause:	
Description			
前置条件： 1、MCU和SOC端串口通信已调通 2、板子为新的硬件改动过的 3、mcu的bin文件已经push到对应目录 操作步骤： 1、手动安装McuUpdate.apk 2、启动McuUpgrade，点击绑定串口服务后等待5s，再次点击发送请求升级指令 3、shell内执行logcat grep -iE "UPG- uart"查看升级log 实际结果： 1、mcu升级完成后，不会自动掉电重启 预期结果： 1、mcu升级完成后，可以自动掉电重启			

History

#1 - 2022-08-24 20:35 - SZTS_TEST 邹涛

- Priority changed from Normal to High

#2 - 2022-08-29 10:09 - SZ BSP-徐季源

- Status changed from New to RESOLVED

- % Done changed from 0 to 100

现版本使 865 关机（例如，adb reboot ）可以触发 MCU 重启。

#3 - 2022-08-30 17:50 - SZTS_TEST 邹涛

0.0.0.20220830_alpha_private_userdebug 版本验证问题已经修复

#4 - 2022-08-30 17:51 - SZTS_TEST 邹涛

- Status changed from RESOLVED to VERIFIED

#5 - 2022-08-30 17:51 - SZTS_TEST 邹涛
- Status changed from VERIFIED to CLOSED

#6 - 2022-09-14 11:56 - CD TPM-申艳艳
- Category set to BSP

Files			
logcat.txt	68.6 KB	2022-08-24	SZTS_TEST 邹涛