

Figure - Bug #111489

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110877 (New): BSP-BVT测试-MCU

【BSP】【EVT】【MCU】【偶现一次】DUT处于开机状态下，断开电源开关后再次打开电源电源开关，板子无法正常启动；

2022-08-26 17:36 - SZTS_TEST 邹涛

Status:	CLOSED	Start date:	2022-08-26
Priority:	High	Due date:	
Assignee:	SZTS_TEST 邹涛	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:		Found Version:	0.0.0.20220825_alpha_private_userdebug
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Critical	Fixed Version:	
Reproducibility:	Rarely	Root cause:	
Test Type:	Bring Up Test		
Description			
前置条件：			
1、 DUT各模块功能正常且处于开机状态			
操作步骤：			
1、 关闭直流电源开关			
2、 再次打开直流电源开关，查看板子和屏幕状态			
实际结果：			
1、 板子无法正常启动，电流显示9ma			
2、 重新用E1烧录MCU后，板子可以正常启动			
预期结果：			
1、 板子可以正常启动			

History

- #1 - 2022-09-01 11:09 - SZ BSP-徐季源
- Status changed from New to NEED_INFO
- Assignee changed from SZ BSP- 徐季源 to SZTS_TEST 邹涛

只出现过一次的问题，研发这边是没法解的。给的流程，只有断电和上电两步，研发也有很多开发任务，不可能花时间去这种概率极低的压力测试。至少测试那边应该测试出一种复现概率超过十分之一的方法

- #2 - 2022-09-14 11:51 - CD TPM-申艳艳
- Category set to BSP

- #3 - 2022-10-13 10:50 - SZTS_TEST 邹涛

release分支1011号userdebug版本，验证断开/打开电源开关30次，板子可以正常启动，无异常；后续版本继续压测

- #4 - 2022-10-21 11:26 - SZTS_TEST 邹涛

release分支1014号userdebug版本验证，断开/打开电源开关30次，未复现该问题。已跟踪三个版本，先关闭该bug

#5 - 2022-10-21 11:27 - SZTS_TEST 邹涛

- Status changed from NEED_INFO to RESOLVED

#6 - 2022-10-21 11:27 - SZTS_TEST 邹涛

- Status changed from RESOLVED to VERIFIED

#7 - 2022-10-21 11:29 - SZTS_TEST 邹涛

- Status changed from VERIFIED to CLOSED