

Figure - Bug #112176

测试 Test-IT # 110867 (New): V1.0测试功能汇总
测试 Test-IT # 110875 (New): BSP-BVT测试-TP

【BSP】 【EVT】 【TP】 VC1的屏幕容易发生误触， 点击无效， 反应不灵敏等现象

2022-09-27 19:22 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-09-27
Priority:	High	Due date:	
Assignee:	CDTS_TEST 刘勇	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:	依赖客户及其供应商问题List	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20220927
Need_Info:	--	Degrated:	--
Resolution:	DUPLICATE	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.20220927
Severity:	Critical	Fixed Version:	
Reproducibility:	Every time	Root cause:	关联BUG https://share.thundersoft.com/redmine/
Test Type:	IT		

Description
【前提条件】 1、设备已开机
【测试步骤】 1、设备连接PC，执行adb reboot命令重启设备 2、重启至桌面后，手指在屏幕上进行操作
【预期结果】 2、设备重启后，手指可以在屏幕上进行点击、滑动等操作，TP正常
【实际结果】 2、设备重启后，手指在屏幕上点击时容易出现误触，点击无效，反应不灵敏等现象
【复现率】 50%
【Log】 Log见附件

History

#1 - 2022-09-27 19:23 - CD TEST-方永红
- Category set to BSP
- Target version set to 依赖客户及其供应商问题List

#2 - 2022-10-19 11:15 - CD BSP-余霄
- Status changed from New to ASSIGNED

正在与供应商沟通

#3 - 2022-10-21 10:39 - CD BSP-余霄
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD BSP-余霄 to CDTS_TEST 王成

确认目前所使用的样机为快速样机，非正式样机，待正式样机后再进行测试。

#4 - 2022-10-28 10:08 - CDTS_TEST 王成

- Status changed from RESOLVED to NEED_INFO

#5 - 2022-11-07 21:00 - CDTS_TEST 王成

- Assignee changed from CDTS_TEST 王成 to CD BSP-余霄

#6 - 2022-11-08 15:17 - CD BSP-余霄

- Status changed from NEED_INFO to RESOLVED

- Assignee changed from CD BSP-余霄 to CDTS_TEST 王成

同此BUG：

<https://share.thundersoft.com/redmine/issues/112726>

#7 - 2022-11-10 10:45 - CDTS_TEST 刘勇

- Assignee changed from CDTS_TEST 王成 to CDTS_TEST 刘勇

#8 - 2022-11-10 16:22 - CD BSP-余霄

- Root cause set to 供应商更新固件

#9 - 2022-11-10 16:26 - CDTS_TEST 刘勇

测试更新，待代码合并后，使用明天（20221111）的版本测试

#10 - 2022-11-10 17:41 - CD BSP-余霄

- Resolution changed from -- to DUPLICATE

#11 - 2022-11-17 17:08 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202211160534

11.17

根据上述测试步骤

VC1屏幕触控、坐标识别等问题有明显改善，满足日常操作

先关闭

#12 - 2022-11-17 17:08 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

- % Done changed from 0 to 100

#13 - 2022-11-17 17:17 - CD BSP-余霄

- Root cause changed from 供应商更新固件 to 关联BUG

<https://share.thundersoft.com/redmine/issues/112726>

误触，点击无效等	36.4 KB	2022-09-27	CD TEST-方永红
----------	---------	------------	-------------