

Figure - 开发 Dev #112372

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110125 (New): 【MK】【BSP】管理总票

开发 Dev # 110638 (解决 Resolved): 【MK】【008】【BOOT】主任务

【MK】【008】【BOOT】【TC-RID: 1201-0100801】Security boot / AVB的prv key替换google key / 平台应用签名使用华人的Subject信息生成的

2022-10-08 14:43 - CD FW-王伟

Status:	进行中 In Progress	Start date:	2022-11-02
Priority:	Normal	Due date:	2022-11-26
Assignee:	CD BSP-唐金泽	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_update_20221130		
Description			
在需求票： https://share.thundersoft.com/redmine/issues/112193			
关于security boot有如下描述：			
4. Security boot，OEM不能unlock，需要更换签名，将谷歌avb签名更换 -> 这个需要BSP实现，建立一个开发票给BSP			
请关注，谢谢			
Related issues:			
Related to Figure - 需求 Requirement # 112193: 【Locked需求】La...		完成 Closed	2022-09-28
Related to Figure - 需求 Requirement # 113980: 【BSP】【Securi...		New	2022-11-15
Related to Figure - 需求 Requirement # 113979: 【BSP】【Securi...		New	2022-11-15

History

#1 - 2022-10-25 12:24 - CD BSP-杜磊

- Assignee changed from CD BSP-杜磊 to CD BSP-唐金泽

#2 - 2022-10-27 20:50 - CD BSP-唐金泽

- Due date set to 2022-11-26

- Status changed from New to 未着手 Not Started

- Target version changed from VX1_MCE_FSE_V3.0_20221030 to VX1_MCE_FSE_V3.0_update_20221130

- Start date changed from 2022-10-08 to 2022-10-28

- Parent task changed from #110125 to #110638

#3 - 2022-10-27 20:56 - CD BSP-唐金泽

- Subject changed from [BSP][MK]Security boot，OEM不能unlock，需要更换签名，将谷歌avb签名更换 to 【MK】【008】【BOOT】【TC-RID: 1201-0100801】Security boot / AVB的prv key替换google key / 平台应用签名使用华人的Subject信息生成的

1.Security boot

2.AVB的prv key替换google key

3.平台应用签名使用华人的Subject信息生成的

#4 - 2022-11-10 09:53 - CD BSP-唐金泽

- Status changed from 未着手 Not Started to 进行中 In Progress

- Start date changed from 2022-10-28 to 2022-11-02

11月2号，启动secure boot相关动作

