

Status:	CLOSED	Start date:	2022-11-04
Priority:	Normal	Due date:	
Assignee:	移动测试一组_CDTS 刘强	% Done:	100%
Category:	依赖软件规避的bug	Estimated time:	0.00 hour
Target version:	MCE_V4.0update_20221215(原VC1_FSE_Vdec1219)	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.userdebug.01.00.0
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	Release Test		
Description			
测试结果请参考附件			

History

- #1 - 2022-11-07 18:18 - IOT-SP-TEST 刘颖
- Target version set to 依赖硬件的bugList
- #2 - 2022-11-07 19:03 - SZ-硬件二组_SD3 王苗
- Status changed from New to ASSIGNED
- Assignee changed from SZ-硬件二组_SD3 王苗 to IOT-SP-TEST 刘颖
- 已经提供1000M与100M测试报告，请软件先检查下100M寄存器配置。
- #3 - 2022-11-08 14:44 - IOT-SP-TEST 刘颖
- Assignee changed from IOT-SP-TEST 刘颖 to CD_BSP 彭文亮
- #4 - 2022-11-08 14:44 - IOT-SP-TEST 刘颖
- Category changed from EE to 依赖软件规避的bug
- #5 - 2022-11-15 15:02 - CD_BSP 彭文亮
- % Done changed from 0 to 60
- LINK UP/SQI/VCT测试，经过近2周的研究、分析、测试和讨论。均已经进行进行了针对性修复。编译包。等待实验室进行结果的验证。
- #6 - 2022-12-12 10:35 - CD BSP-唐金泽
- Target version changed from 依赖硬件的bugList to MCE_V4.0update_20221215(原VC1_FSE_Vdec1219)
- 测试机构已验证，通过，@文亮，请考虑如何合入dev分支版本。
- #7 - 2022-12-13 11:27 - CD_BSP 彭文亮
- % Done changed from 60 to 70

目前正在整理代码，进行验证中。

#8 - 2023-01-03 16:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
167212	Pre_figure/mcu	Pre_figure_turbox-c2130c-la1.1-vendor-dev	jie.chen@thundersoft.com
BSP: MCU:Added MCU notification MPU networking functionUsed to pass the network connection test, it is necessary to strictly control the network connection time and add a timing function on the MCU side.Bin version: V0.0.6TC-RID: 1201-0102704IssueID: TS-R-DF-113713Change-Id: Ib66489af16bb81609f2405b660687b37336809fe			

#9 - 2023-01-03 16:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
167377	general/platform/vendor/thundercomm/uart	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangjz1204@thundersoft.com
BSP:UART: Enable PHY linkup When get MCU Messageenable phy linkup when get mcu messageTC-RID: 1201-0400603IssueID: TS-R-DF-113713Change-Id: Iff0a9db910a95acc9fde745c25d0bda7fa540554			

#10 - 2023-01-03 16:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
167850	general/platform/vendor/thundercomm/uart	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangjz1204@thundersoft.com
BSP:UART: Exchange Uart Service priorityexchange uart service priorityTC-RID: 1201-0400603IssueID: TS-R-DF-113713Change-Id: I9476ef67ce0267ccf453e5a259bc76676bddabb			

#11 - 2023-01-03 16:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
166247	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wenliang.peng@thundersoft.com

BSP:Ethernet: for 100M IOP testInitial: Items(linkup02, linkup03, sqi02)test fail.After modification: All items can pass the test.We recommend using the perf version for IOP testing.TC-RID: 0301-0400601IssueID: TS-R-DF-113713Change-Id: Ie28af1e44e36b66cb28d3def0119be68c1e9ab05

#12 - 2023-01-11 14:25 - CD BSP-杜磊

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD_BSP 彭文亮 to CDTS_TEST 王成
- % Done changed from 70 to 100

#13 - 2023-01-17 15:18 - CDTS_TEST 王成

- Assignee changed from CDTS_TEST 王成 to 移动测试一组_CDTS 刘强

#14 - 2023-01-29 11:26 - 移动测试一组_CDTS 刘强

- Status changed from RESOLVED to VERIFIED

由于硬件IOP测试已经通过
软件检测连接以太网盒子后可以正常上网浏览网页
且DTC Ethernet盒子网络移除时会诊断报以下日志：
01-01 08:05:28.227 0 0 E DTC_ETH,link_delay_work_func: 3003, SQI=0, link=0
恢复链接后，报错日志消失

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.D.userdebug.01.00.X101.202301191306

#15 - 2023-01-29 11:26 - 移动测试一组_CDTS 刘强

- Status changed from VERIFIED to CLOSED

Files			
ChuangDa_IOP测试结果汇总-2022.11.4.xlsx	8.91 KB	2022-11-04	SZ HW Test-曾小文
ChuangDa_Figure_100BASE-T1_IOP_TEST_11.4.zip	7.64 MB	2022-11-04	SZ HW Test-曾小文