

Figure - Bug #114766

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT2】【设置】点击开发者模式中的“无线调试”时， settings应用闪退

2022-12-23 11:41 - CD Test赵飞

Status:	CLOSED	Start date:	2022-12-23
Priority:	Normal	Due date:	
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V5.0_20221230	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2022-12-23
Reproducibility:	Every time	Root cause:	Activity 强制转换异常导致的崩溃。
Test Type:	ST		

Description
【测试版本】 FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202212230238
【前提条件】 1、设备已开机
【测试步骤】 1、进入设置，打开开发者模式 2、进入开发者模式页面，点击“无线调试”
【预期结果】 2、“无线调试”开关正常被打开
【实际结果】 3、Settings闪退
【日志】 logcat日志见附件

History

#1 - 2022-12-23 17:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
172024	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Settings: Fix wifi debug crash problem.TC-RID: 1201-0201810IssueID: TS-R-BUG-114766Change-Id: I126485bc32ff313a4c23cef9e566beea24c347a			

#2 - 2022-12-23 17:47 - CDFW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CDFW-廖涛 to CD Test赵飞

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2022-12-23
- Root cause set to Activity 强制转换异常导致的崩溃。

■ Current conclusion

已修复。

■ My analysis

Activity 强制转换异常导致的崩溃，已使用正确的类型。

■ Next action

测试验证。

#3 - 2022-12-27 15:41 - CD Test赵飞

- Status changed from RESOLVED to VERIFIED
- % Done changed from 100 to 80

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202212240330
验证结果：PASS
点击“无线调试”开关，可以正常打开开关，无crash发生

#4 - 2022-12-27 15:41 - CD Test赵飞

- Status changed from VERIFIED to CLOSED
- % Done changed from 80 to 100

Files

logcat.txt	7.5 MB	2022-12-23	CD Test赵飞
------------	--------	------------	-----------