

Figure - Bug #115127

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT2】【设置】管理屏幕键盘中打开输入法开关时的弹框提示需要移除

2023-01-06 15:10 - CD Test赵飞

Status:	CLOSED	Start date:	2023-01-06
Priority:	Normal	Due date:	
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-01-09
Reproducibility:	Every time	Root cause:	AOSP 本身的提示方式
Test Type:	ST		

Description
【前提条件】 1、设备已开机 【测试步骤】 1、打开设置 - 系统 - 语言与输入法 - 屏幕键盘 - 管理屏幕键盘 2、关闭 “ 百度输入法 ” 开关 3、再次打开 “ 百度输入法 ” 开关 【预期结果】 3、百度输入法 ” 开关正常被打开，无弹框提示 【实际结果】 3、打开 “ 百度输入法 ” 开关时有弹框提示 【备注】 设备不支屏幕锁定，也不是手机，所以建议取消此弹框提示

History

#1 - 2023-01-09 13:55 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
174833	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Settingslibs: Add custom boot warning show control function.TC-RID: 1201-0201813IssueID: TS-R-BUG-115127Change-Id: Ie75928c041507eff9417d919570a31b06eee4b31			

#2 - 2023-01-09 13:57 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD Test赵飞
- % Done changed from 0 to 100

- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-01-09
- Root cause set to AOSP 本身的提示方式

■ Current conclusion

已处理。

■ My analysis

AOSP 本身有的提示，因设备不支持锁屏，所以不展示该提示。

■ Next action

测试验证。

#3 - 2023-01-13 10:12 - CD Test赵飞

- Status changed from RESOLVED to VERIFIED

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202301110536

验证结果：PASS

提示弹框已移除

#4 - 2023-01-13 10:12 - CD Test赵飞

- Status changed from VERIFIED to CLOSED

Files

screenshot.png	289 KB	2023-01-06	CD Test赵飞
----------------	--------	------------	-----------