

Figure - 开发 Dev #115369

开发 Dev # 110122 (New): 【MK】 管理总票

开发 Dev # 110126 (New): 【MK】 【AF】 管理总票

开发 Dev # 112454 (完成 Closed): 【MK】 【FW】 【UART】 【TC-RID: 1201-0207301】

【MK】 【FW】 【UART】 【TC-RID: 1201-0207301】 添加MCU过压欠压的DTC诊断日志

2023-01-16 19:33 - CD TPM-王祥林

Status:	完成 Closed	Start date:	2023-01-16
Priority:	Normal	Due date:	
Assignee:	CD FW-程天颖	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Description			

History

#1 - 2023-01-16 19:38 - CD TPM-王祥林

- Subject changed from 【MK】 【FW】 【DTC】 【TC-RID: 1201-0207301】 添加过压欠压的DTC诊断日志 to 【MK】 【FW】 【MCU】 【TC-RID: 1201-0207301】 添加过压欠压的DTC诊断日志

#2 - 2023-01-16 19:40 - CD TPM-王祥林

- Subject changed from 【MK】 【FW】 【MCU】 【TC-RID: 1201-0207301】 添加过压欠压的DTC诊断日志 to 【MK】 【FW】 【UART】 【TC-RID: 1201-0207301】 添加MCU过压欠压的DTC诊断日志
- Assignee changed from CD TPM- 王祥林 to CD FW-程天颖
- Parent task changed from #112093 to #112454

#3 - 2023-01-18 13:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
177091	general/platform/vendor/thundercomm/apps/TCService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:MCU:Add DTC LogTC-RID: 1201-0207301IssueID: TS-R-BUG-115369Change-Id: I239797773fe98af0ced31b4dc1a5be0d007ab7b1			

#4 - 2023-01-18 14:02 - CD FW-程天颖

- Category set to CD-FW
- Status changed from New to 完成 Closed
- % Done changed from 0 to 50

■ Current conclusion

已添加相关的DTC，提交已入库

■ My analysis

由于到高电压和低电压都是收到的同一个信息请求开启过压保护，所以高电压和低电压无法区分，还需要确定一下，后续是否区分。

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/TCService/+/177091>

#5 - 2023-01-18 14:03 - CD FW-程天颖

- Status changed from 完成 Closed to 进行中 In Progress

#6 - 2023-01-19 16:36 - CDFW-程天颖
- Status changed from 进行中 In Progress to 完成 Closed
- % Done changed from 50 to 100

已确定不用区分