

Figure - Bug #115686

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【控制中心】音乐播放器的进度条尺寸，与UI效果图不一致

2023-02-01 15:03 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-01
Priority:	Normal	Due date:	2023-02-08
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Reproducibility:	Every time	Fixed Version:	2023-02-03
Test Type:	ST	Root cause:	UI 适配问题导致。
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、播放音乐			
2、打开控制中心			
3、查看音乐播放器的进度条			
【预期结果】			
3、进度条的尺寸与ui效果图一致			
【实际结果】			
3、音乐播放器的进度条尺寸，与UI效果图不一致			

History

- #1 - 2023-02-01 17:19 - CD FW 曹覃刚
- Due date set to 2023-02-08
 - Assignee changed from CD FW 曹覃刚 to CD FW-廖涛

#2 - 2023-02-03 09:59 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
179043	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF: SystemUI: Modify music controller seekbar height.TC-RID: 1201-0201903IssueID: TS-R-BUG-115686Change-Id: I4d65bc789d9b5e46e785f717a16adc84662cc679			

- #3 - 2023-02-03 10:06 - CD FW-廖涛
- Status changed from New to RESOLVED
 - Assignee changed from CD FW-廖涛 to CD TEST-方永红

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-03
- Root cause set to UI 适配问题导致。

■ Current conclusion
已处理。

■ My analysis
UI 适配问题导致。

■ Next action
测试验证。

#4 - 2023-02-06 11:41 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202302050304

2.6
验证通过

#5 - 2023-02-06 11:41 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
1500.png	148 KB	2023-02-01	CD TEST-方永红