

Figure - Bug #115797

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】 【EVT】 【设置】 设置中二三四级列表选项按压状态颜色与UI效果图有偏差

2023-02-02 16:07 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-02
Priority:	Normal	Due date:	2023-02-06
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0071.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-02-03
Reproducibility:	Every time	Root cause:	UI 适配遗漏。
Test Type:	ST		

Description
【前提条件】 1、设备已开机
【测试步骤】（以操作设置为例） 1.进入设置-显示 2、长按操作模式
【预期结果】 2、操作模式的按压状态颜色与ui图上的一致
【实际结果】 2、按压状态颜色与UI效果图有偏差

History

#1 - 2023-02-02 19:30 - CD FW 曹覃刚

- Due date set to 2023-02-06

#2 - 2023-02-03 18:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
179306	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Modify item selectable background style.TC-RID: 1201-0201813IssueID: TS-R-BUG-115797Change-Id: I9ef4ef6b6138e8c8b90d80bdca6700d01dc2a5a1			

#3 - 2023-02-03 18:45 - CD FW-廖涛

- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to CD TEST-方永红

- % Done changed from 0 to 100

- Resolution changed from -- to FIXED

- Degrated changed from -- to No

- Fixed Version set to 2023-02-03
- Root cause set to UI 适配遗漏。

■ Current conclusion
已处理。

■ My analysis
UI 适配遗漏。

■ Next action
测试验证。

#4 - 2023-02-06 11:17 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

2.6
按压状态颜色于ui效果一致
验证通过

#5 - 2023-02-06 11:18 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
1552.png	237 KB	2023-02-02	CD TEST-方永红