

Figure - Bug #116000

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT2】【蓝牙】蓝牙配对弹框样式与UI设计不符

2023-02-07 18:56 - CD Test赵飞

Status:	CLOSED	Start date:	2023-02-07
Priority:	Normal	Due date:	2023-02-10
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0072.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-02-15
Reproducibility:	Every time	Root cause:	对话框样式未适配 UI。
Test Type:	ST		

Description
【前提条件】 1、设备已开机 2、准备一个蓝牙耳机 【测试步骤】 1、进入设置 - 已连接的设备 - 与新设备配对 2、点击搜索到的蓝牙设备名称 【预期结果】 2、弹出蓝牙配对弹框，弹框式样符合UI设计 【实际结果】 2、弹出蓝牙配对弹框，但弹框样式与UI设计不符 【日志】 截图见附件

History

#1 - 2023-02-07 19:25 - CD FW-廖涛

- Status changed from New to ASSIGNED

- Assignee changed from CD FW 曹覃刚 to CD FW-廖涛

#2 - 2023-02-08 20:08 - CD FW 曹覃刚

- Due date set to 2023-02-10

#3 - 2023-02-11 16:22 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
180983	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix bluetooth pair dialog style.TC-RID: 1201-0201813IssueID: TS-R-BUG-116000Change-Id: I5044186e1c40f5f25065797cac55a7da440d85f7			

#4 - 2023-02-11 16:23 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to CD Test赵飞
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-11
- Root cause set to 对话框样式未适配 UI。

■ Current conclusion

已处理，代码已入库。

■ My analysis

对话框样式未适配 UI。

■ Next action

测试验证。

#5 - 2023-02-14 14:36 - CD Test赵飞

- File Screenshot_20230214-043606.png added
- Status changed from RESOLVED to ASSIGNED
- Assignee changed from CD Test赵飞 to CD FW-廖涛

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0074.X101

蓝牙配对弹框UI已适配，但弹框中的文言在以下两种情况下会显示不全，请修复：

- 1、蓝牙设备名称太长时
- 2、系统字体设置为最大时

#6 - 2023-02-15 09:52 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
181751	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-1a1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix bluetooth pair dialog title display problem.TC-RID: 1201-0201813IssueID: TS-R-BUG-116000Change-Id: If40f0716cdfef4bec32ccc7b96bf356389cc853e			

#7 - 2023-02-15 09:55 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to CD Test赵飞
- Fixed Version changed from 2023-02-11 to 2023-02-15

■ Current conclusion

标题显示问题已处理，代码已入库。

■ My analysis

标题展示兼容问题。

■ Next action

测试验证。

#8 - 2023-02-16 11:18 - CD Test赵飞

- Status changed from RESOLVED to VERIFIED

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0075.X101

验证结果：PASS

文言太长时，超出的文言用“...”代替显示

#9 - 2023-02-16 11:19 - CD Test赵飞

- Status changed from VERIFIED to CLOSED

Files

Screenshot_20230207-124836.png	339 KB	2023-02-07	CD Test赵飞
0_17_Setting_1_2_蓝牙_配对弹框.png	597 KB	2023-02-07	CD Test赵飞
Screenshot_20230214-043606.png	443 KB	2023-02-14	CD Test赵飞