

Figure - Bug #116136

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【设置】设置中部分按钮看不清楚

2023-02-09 17:36 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-09
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0073.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0074.X
Severity:	Normal	Fixed Version:	2023-02-10
Reproducibility:	Every time	Root cause:	按钮样式未适配新 UI 导致。
Test Type:	ST		
Description			
1、系统-重置选项-确认重置按钮			
2、开发者模式-显示通知渠道警告-下方的重置通知的重要级别按钮			

History

#1 - 2023-02-10 18:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
180803	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix action button style problem.TC-RID: 1201-0201813IssueID: TS-R-BUG-116136Change-Id: Iffcf70894308290f37b14076764c7ae3918a9686			

#2 - 2023-02-10 19:02 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST- 方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-10
- Root cause set to 按钮样式未适配新 UI 导致。

■ Current conclusion

已处理，代码已入库。

■ My analysis

按钮样式未适配新 UI 导致。

■ Next action

测试验证。

#3 - 2023-02-14 18:34 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0074.X101

2.14

验证通过

#4 - 2023-02-14 18:34 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
1700.png	224 KB	2023-02-09	CD TEST-方永红
1701.png	251 KB	2023-02-09	CD TEST-方永红