Figure - Bug #117018

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【设置】护眼模式的时间设置弹框-切换为键盘输入模式,时间数字显示不完整

2023-03-18 14:43 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-18	
Priority:	Normal	Due date:		
Assignee:	CD TEST-方永红	% Done:	100%	
Category:	CD-FW	Estimated time:	0.00 hour	
Target version:				
Need_Info:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101	(X101)
Resolution:	FIXED	Degrated:	No	
Severity:	Normal	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101	(X101)
Reproducibility:	Every time	Fixed Version:	2023-03-20	
Test Type:	ST	Root cause:	时间输入框宽度过小导致。	
D :				

Description

【前提条件】

设备已开机

【测试步骤】

- 1、打开设置-显示-护眼模式页面
- 2、选择在设定的时间打开
- 3、在弹出的时间设置弹窗中选择键盘输入

【预期结果】

3、时间设置弹窗显示一切正常

【实际结果】

3、时间数字显示不完整

History

#1 - 2023-03-20 14:38 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader				
188549	general/platform/packages/apps/Settin	Pre_figure_turbox-c2130c-la1.1-qssi12	tao.liao@thundersoft.com				
	gs	-dev					
AF:Settings: Fix TimePicker edittext width problem.TC-RID: 1201-0201806IssueID: TS-R-BUG-117018Change-Id:							
Ic690b5db85685d8b0263bd71280f8ca339a58f81							

#2 - 2023-03-20 14:39 - CD FW-廖涛

- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-20

- Root cause set to 时间输入框宽度过小导致。

Current conclusion 已处理,代码已入库。

My analysis 时间输入框宽度过小导致。调整输入框宽度到合适的宽度解决。

Next action

测试验证。

#3 - 2023-03-22 10:27 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101).202303220131

3.22 验证通过

#4 - 2023-03-22 10:27 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

1442.png

145 KB

2023-03-18

CD TEST-方永红