

Figure - Bug #117064

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【控制中心】【VC1&VX1】控制中心编辑页面组件右上角的增减按钮位置与UI图有差距

2023-03-21 15:34 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-21
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0084.C101(X
Need_Info:	TEST	Degrated:	--
Resolution:	INVALID	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		

Description	
【前提条件】	
1、设备正常启动	
【测试步骤】	
1、进入控制中心编辑页面	
【预期结果】	
1、组件右上角的增减按钮位置与UI图设计一致	
【实际结果】	
1、组件右上角的增减按钮位置与UI图有差距（见截图）	
【复现率】	
3/3	

History

#1 - 2023-03-21 16:58 - CD FW 曹覃刚
- Status changed from New to NEED_INFO
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
- Need_Info changed from -- to TEST

Hi, 永红

控制中心UI适配投入时间为03/21,请使用03/22的版本测试，十分感谢

#2 - 2023-03-22 11:23 - CD TEST-方永红
- Status changed from NEED_INFO to RESOLVED
- Resolution changed from -- to INVALID

3.22

不复现

#3 - 2023-03-22 11:23 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

#4 - 2023-03-22 11:24 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
1534.png	43.2 KB	2023-03-21	CD TEST-方永红