

Figure - Bug #117094

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【屏幕录制】【VC1】录屏弹窗页面显示与UI图有偏差

2023-03-22 19:02 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-22
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101)
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102(X102)
Reproducibility:	Every time	Fixed Version:	2023-03-24
Test Type:	ST	Root cause:	ui位置偏移

Description	
【前提条件】	
1、设备正常启动	
【测试步骤】	
1、打开控制中心	
2、点击屏幕录制	
3、查看录屏弹窗	
【预期结果】	
3、录屏弹窗页面显示与UI图无明显差别	
【实际结果】	
3、录屏弹窗页面显示与UI图有偏差（见截图）	

History

#1 - 2023-03-24 15:37 - CD FW-程天颖

- Status changed from New to ASSIGNED

- Root cause set to ui位置偏移

#2 - 2023-03-24 18:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
189530	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:SystemUI: Fix Screen record UITC-RID: 1201-0201905IssueID: TS-R-BUG-117094Change-Id: I9c3c8c9e420b05c30fb9c8c62e9afca65e8cd50b			

#3 - 2023-03-24 18:48 - CD FW-程天颖

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD FW-程天颖 to CD TEST-方永红

- % Done changed from 0 to 100

- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-24

■ Current conclusion

vc1与vx1都测试过,截图与ui设计切图重合对比过了,没有问题

■ My analysis

ui位置偏移

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+189530>

#4 - 2023-03-27 13:51 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102(X102).202303260013

3.27

验证通过

#5 - 2023-03-27 13:52 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

20230322-185959.jpg	198 KB	2023-03-22	CD TEST-方永红
---------------------	--------	------------	-------------