

Figure - Bug #117095

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【屏幕录制】【VC1&VX1】录屏结束后弹出的提示与UI设计有偏差

2023-03-22 19:16 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-22
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101)
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-03-28
Reproducibility:	Every time	Root cause:	UI样式问题
Test Type:	ST		

Description
【前提条件】 1、设备正常启动 【测试步骤】 1、录屏 2、结束录屏 3、查看提示 【预期结果】 3、提示弹框与UI设计基本一致 【实际结果】 3、录屏结束后弹出的提示与UI设计有偏差

History

#1 - 2023-03-24 15:38 - CD FW-程天颖

- Status changed from New to ASSIGNED

#2 - 2023-03-27 19:58 - CD FW-程天颖

- Root cause set to UI样式问题

#3 - 2023-03-28 09:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
189813	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:SystemUI: Fix Toast UITC-RID: 1201-0207401IssueID: TS-R-BUG-117095Change-Id: I4f3952640ef2339ab24b4669489cdde9d2def617			

#4 - 2023-03-28 10:00 - CD FW-程天颖

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD FW-程天颖 to CD TEST-方永红
- % Done changed from 0 to 100
- Degrated changed from -- to No
- Fixed Version set to 2023-03-28

■ Current conclusion

bug已解决,提交已入库

■ My analysis

样式位置与UI设计不一致

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+189813>

#5 - 2023-03-28 10:01 - CD FW-程天颖

- Resolution changed from -- to FIXED

#6 - 2023-04-03 18:53 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

4.3

验证通过

#7 - 2023-04-03 18:53 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

Snipaste_2023-03-22_19-08-55.png	487 KB	2023-03-22	CD TEST-方永红
----------------------------------	--------	------------	-------------