

Figure - Bug #117236

【BSP】 【VC1】 【Touch】 TP更新固件后TP无响应

2023-03-29 18:29 - CD BSP-杜磊

Status:	CLOSED	Start date:	2023-03-29
Priority:	Normal	Due date:	
Assignee:	移动测试一组_CDTS 刘强	% Done:	70%
Category:	BSP	Estimated time:	0.00 hour
Target version:	VC1_FSE_0090_20230411	Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0086
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	升级完后，reset动作未生效
Test Type:	ST		
Description			
TP更新不同固件后，出现TP无法使用			

History

#1 - 2023-03-29 18:37 - CD BSP-杜磊

- Status changed from New to RESOLVED
- Assignee changed from CD BSP-杜磊 to 移动测试一组_CDTS 刘强
- % Done changed from 0 to 70
- Root cause set to 升级完后，reset动作未生效

Hi, 刘强,

请使用3/30的VB版本进行验证

ftp://cdiot@192.168.87.46/Pre_figure/VerifyBuild/Pre_figure_turbox-c2130c-la1.1-qssi12-dev/20230329/202303292109-3130/FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102%28X102%29.202303292109.zip

验证方法：

刷之前老的版本，再刷VB版本，验证TP升级后是否能正常触摸。

Thanks.

#2 - 2023-03-30 18:43 - 移动测试一组_CDTS 刘强

vb版本验证通过

烧写12月工厂版本全擦

再烧写0086 user不全擦

开机后显示正常，TP可用

#3 - 2023-03-31 18:28 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
190776	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dulei0503@thundersoft.com

BSP:TP: Fix VC1 tp can't work after upgrade FWTouch's interrupt must be enabled after updating FWTC-RID: 1201-0100401IssueID:
TS-R-DF-117236Change-Id: 1779ed15a7952940edede52728883b0ab95086184

#4 - 2023-04-03 14:51 - 移动测试一组_CDTS 刘强

- Status changed from *RESOLVED* to *VERIFIED*

验证版本：FlatBuild_HH_MCE_FSE.M.D.userdebug.01.00.C102.202304020018

验证结果：验证通过

烧写12月工厂版本全擦

再烧写FlatBuild_HH_MCE_FSE.M.D.userdebug.01.00.C102.202304020018不全擦

开机后显示正常，TP可用

#5 - 2023-04-03 14:52 - 移动测试一组_CDTS 刘强

- Status changed from *VERIFIED* to *CLOSED*