

Figure - Bug #117568

【PVC1-1081】 【FSE-M】 【OTA升级】 FSE-M OTA升级在未进入升级条时失败

2023-04-19 16:17 - 物联网测试组_TSCD 王维

Status:	CLOSED	Start date:	2023-04-19
Priority:	Normal	Due date:	
Assignee:	物联网测试组_TSCD 王维	% Done:	90%
Category:	BSP	Estimated time:	0.00 hour
Target version:		Found Version:	FSE-M base版本：01.00.0086.C102
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		

Description
问题描述：
FSE-M OTA升级在未进入升级条时失败
FSE-M base版本：01.00.0086.C102
FSE-M target版本：01.00.0086.C102
IDCM版本：0066
CGW版本：01.06.0061.A107
SDK版本：1.0.9
时间戳：2023-04-07 09:29:48
VIN:HRYTTESTVINMGM279
【备注】
安卓原生系统与以太网诊断服务偶发同时对以太网控制模式寄存器0x8034进行异步刷写，导致出现异常，从而引起传输功能异常；
对控制模式寄存器0x8034修改值为正常值后，电路板基本能回复正常。将优化以太网诊断方案。
01.00.0094.C103版本回归 （4/25）

History

#1 - 2023-04-20 13:52 - CD BSP 叶鹏

- File 111.jpg added
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD BSP 叶鹏 to 物联网测试组_TSCD 王维
- % Done changed from 0 to 90

和客户沟通，该问题已经定位到是网络丢包导致刷写失败，不用我们处理

#2 - 2023-04-20 14:05 - 物联网测试组_TSCD 王维

- Status changed from *RESOLVED* to *VERIFIED*

#3 - 2023-04-20 14:05 - 物联网测试组_TSCD 王维

- Status changed from *VERIFIED* to *CLOSED*

Files

4.12FSE-M压测记录.txt等.zip	79.5 KB	2023-04-19	物联网测试组_TSCD 王维
111.jpg	21.6 KB	2023-04-20	CD BSP 叶鹏