

Figure - Bug #117573

测试 Test-IT # 111062 (New): V3.0功能测试

测试 Test-IT # 111069 (New): AF-V3.0--Launcher/SystemUI-小窗模式入口

【AF】【EVT3】【小窗模式】应用宝，点击安装按钮，无法跳转至设置-安装权限开启页面

2023-04-19 16:44 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-04-19
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	窗口定制	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Resolution:	FIXED	Degrated:	No
Severity:	Major	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Reproducibility:	Every time	Fixed Version:	2023-04-21
Test Type:	ST	Root cause:	设置通过小窗的方式启动导致崩溃，已修改，使设
Description			
【测试步骤】			
1.使用应用宝安装应用			
【预期结果】			
1、弹出相应弹窗并跳转至设置页面			
【实际结果】			
1、无法跳转至设置-安装权限开启页面			
重复操作，出现”设置屡次停止使用“的提示			

History

#1 - 2023-04-19 20:01 - CD FW 曹覃刚
- Status changed from New to ASSIGNED

当前状况

今日新起问题，明天开始更新进度

下一步计划

继续解析

#2 - 2023-04-19 20:48 - CD FW 曹覃刚
- Assignee changed from CD FW-鲁凯峰 to CD FW 曹覃刚

#3 - 2023-04-20 17:44 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194857	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com

#4 - 2023-04-20 17:49 - CD FW 曹覃刚

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW 曹覃刚 to CD TEST- 方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-04-21
- Root cause set to 设置通过小窗的方式启动导致崩溃，已修改，使设置不能以小窗的方式启动

#5 - 2023-04-21 10:14 - CD TEST-方永红

- File Phone-STS40X190078 2023-04-21 10-13-34.mp4 added
- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103).202304210449

4.21

验证通过

#6 - 2023-04-21 10:14 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
1640.txt	6.57 MB	2023-04-19	CD TEST-方永红
Phone-STS40X190078 2023-04-19 16-40-31.mp4	16.3 MB	2023-04-19	CD TEST-方永红
Phone-STS40X190078 2023-04-21 10-13-34.mp4	18.4 MB	2023-04-21	CD TEST-方永红