

Figure - Bug #117740

【IOVDEV-25051】【VC1】【0094】【台架】【EE环境】【副屏】【设置】蓝牙与已连接设备断开连接之后再次连接失败

2023-05-04 11:22 - CDTS_Test 吴诗雨

Status:	CLOSED	Start date:	2023-05-04
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	01.00.0094.c103
Resolution:	DUPLICATE	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
【问题出现时间】：20230427 09：55 【前提条件】：车机上电，蓝牙已开启 【操作步骤】 1.与中控蓝牙已连接 2.中控下电 3.中控再次上电 【实际结果】 1.与中控蓝牙连接成功 2.与中控蓝牙断开连接 3.与中控蓝牙连接失败，并一直在尝试连接 【期望结果】 1.与中控蓝牙连接成功 2.与中控蓝牙断开连接 3.自动与中控蓝牙连接成功，并保持连接状态 【备注】： 【影响版本】：01.00.0094.c103 【硬件版本号】：			
Related issues:			
Related to Figure - Bug # 117746: 【IOVDEV-25072】【VC1】【009...		CLOSED	2023-05-04

History

- #1 - 2023-05-04 14:00 - CDTS_Test 吴诗雨
- Priority changed from Normal to High
- #2 - 2023-05-04 14:47 - CD FW-廖涛
- Assignee changed from CD FW-廖涛 to CD FW-程天颖
- #3 - 2023-05-04 14:50 - CD FW-程天颖

- Status changed from New to ASSIGNED

#4 - 2023-05-04 16:15 - CD FW-程天颖

- Assignee changed from CD FW-程天颖 to CD LC 陶洪普

Hi,洪普：

副屏蓝牙不应该显示中控设备，需要底层进行屏蔽，请帮忙分析一下

#5 - 2023-05-04 22:43 - CD LC 陶洪普

- Assignee changed from CD LC 陶洪普 to CD TPM-王祥林

Hi

如电话中同步的，

副屏蓝牙不应该显示中控设备，需要底层进行屏蔽

需要提供中控蓝牙设备特征（比如：规定前缀MAC等）
请帮与客户中控开发同事确定蓝牙屏蔽特征（区分标识）
谢谢！

#6 - 2023-05-05 00:00 - CD TPM-王祥林

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD TPM-王祥林 to CDTS_Test 吴诗雨

- Resolution changed from -- to DUPLICATE

根据客户要求，中控蓝牙需要被副屏屏蔽掉，不能搜索到。因此这个问题的前提条件就不存在了。请关闭此问题，统一用117743来跟踪。

#7 - 2023-05-05 09:47 - CDTS_Test 吴诗雨

- Priority changed from High to Normal

#8 - 2023-05-05 10:47 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

117743跟踪

#9 - 2023-05-05 10:48 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files			
0427.txt	3.68 MB	2023-05-04	CDTS_Test 吴诗雨
video.mp4	730 KB	2023-05-04	CDTS_Test 吴诗雨