

Figure - Bug #117866

Bug # 117768 (CLOSED): 【BSP】【EVT3】【VC1】【ST】【Display】0095版本热插拔后，会偶现黑屏现象

【BSP】【EVT1】【ST】【Display】VX1板子冷插拔后，出现黑屏现象

2023-05-11 09:25 - 移动测试一组_CDTs 刘强

Status:	CLOSED	Start date:	2023-05-11
Priority:	Normal	Due date:	
Assignee:	移动测试一组_CDTs 刘强	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0095-0098
Resolution:	FIXED	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	由于使能了UEFI阶段的开机显示，需在kernel中判

Description	
【前提条件】	
None	
【测试步骤】	
1. 烧写0098版本	
2. 在开机过程中，插入显示传输线	
3. 多次重复观察现象	
【预期结果】	
3. 显示正常，且可以恢复	
【实际结果】	
3 会出现黑屏现象	

History

- #1 - 2023-05-11 10:03 - CD BSP-杜磊
- Status changed from New to ASSIGNED
- % Done changed from 0 to 50
- Resolution changed from -- to FIXED
- Root cause set to 由于使能了UEFI阶段的开机显示，需在kernel中判断UEFI阶段是否有进行初始化
- #2 - 2023-05-11 20:07 - CD BSP-杜磊
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD BSP- 杜磊 to 移动测试一组_CDTs 刘强
- % Done changed from 50 to 100

https://dev.thundercomm.com/gerri/q/topic:FIGURE_LCD_COLD_PLUG

- #3 - 2023-05-16 14:38 - 移动测试一组_CDTs 刘强
- Status changed from RESOLVED to VERIFIED

0100版本插拔未出现黑屏，关闭issue，有其他原因出现黑屏，由以下bug跟踪

<https://share.thundersoft.com/redmine/issues/117953>

<https://share.thundersoft.com/redmine/issues/117954>

遗留问题恢复插拔后恢复比较慢的问题，与研发沟通VX设备暂不关注

#4 - 2023-05-16 14:38 - 移动测试一组_CDTS 刘强

- Status changed from VERIFIED to CLOSED