

Status:	CLOSED	Start date:	2023-05-25
Priority:	High	Due date:	
Assignee:	CDTS_TEST 王成	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	95
Resolution:	DUPLICATE	Degrated:	--
Severity:	Major	Verified Version:	
Reproducibility:	Frequently	Fixed Version:	
Test Type:	User Experience	Root cause:	
Description			
【问题描述】：16个ECU组包升级9次，安装成功5次，安装失败4次中FSE-M安装失败3次。 【前置条件】：车辆上电 【软件/网络环境】：EE环境 【IDCM版本信息】：03020079C101 【SDK版本信息】：1.0.15.2 【云端升级活动】：386-0520-组包1 【云端升级任务】：da86bcf48bbc44f19593a103bfff101b 【提报人】：柳雨梵 【操作步骤】：车辆上电，进入设置，系统，检测到新版本并下载安装包，点击立即升级 【预期结果/行为】：进入立即升级流程并安装成功 【实际结果/行为】：升级9次，成功5次，失败4次。 【问题发生频率】：偶现 【实车VIN】：LJD8BB3F0P0000386 【发生日期 & 时间】：2023-05-25 11:23:18 【log路径】:数采已上云、HHTU log见附件 【数采仪】：0300073			

History

- #1 - 2023-05-27 16:40 - CD TPM-王祥林
- Assignee changed from CD BSP 叶鹏 to CD TPM-王祥林
- #2 - 2023-05-27 16:43 - CD TPM-王祥林
- Assignee changed from CD TPM-王祥林 to CD_BSP 彭文亮

此问题和这个是相同的原因，目前已经找到原因，临时方案已经通过CANOE刷写验证。下一步等正式方案合入。
<https://share.thundersoft.com/redmine/issues/117329>

- #3 - 2023-06-12 11:22 - CD TPM-王祥林
- Status changed from New to RESOLVED
- Assignee changed from CD_BSP 彭文亮 to CDTS_TEST 王成
- Resolution changed from -- to DUPLICATE

在117329上跟踪，此票关闭。

#4 - 2023-06-25 17:35 - CDTS_TEST 王成

- Subject changed from IOVPVC1-1557 【组包升级】【OTA升级】16个ECU组包升级9次，安装成功5次，安装失败4次中FSE-M安装失败3次 to IOVPVC1-1557 【组包升级】【OTA升级】16个ECU组包升级9次，安装成功5次，安装失败4次中FSE-M安装失败3次-CANOE刷写失败，与117329并票
- Status changed from RESOLVED to VERIFIED

#5 - 2023-06-25 17:35 - CDTS_TEST 王成

- Status changed from VERIFIED to CLOSED

Files			
新库16组包-FAIL.txt	803 KB	2023-05-25	CDTS-TEST 周婷