

Figure - Bug #118271

【PVC1-1557】【组包升级】【OTA升级】16个ECU组包升级7次，安装成功5次，安装失败2次中FSE-M安装失败1次

2023-05-26 15:06 - CDTS_TEST 王成

Status:	CLOSED	Start date:	2023-05-26
Priority:	Normal	Due date:	
Assignee:	CD_BSP 彭文亮	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0095
Resolution:	--	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Frequently	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
问题描述】：16个ECU组包升级7次，安装成功5次，安装失败2次中FSE-M安装失败1次。 【前置条件】：车辆上电 【软件/网络环境】：EE环境 【IDCM版本】：03020079C101 【SDK版本】：1.0.15.1 【云端升级活动】：386-0520-组包1 【云端taskID】：da86bcf48bbc44f19593a103bfff101b 【提报人】：柳雨梵 【操作步骤】：车辆上电，进入设置，系统，检测到新版本并下载安装包，点击立即升级 【预期结果/行为】：进入立即升级流程并安装成功 【实际结果/行为】：升级7次，成功5次，失败2次。 【问题发生频率】：偶现 【实车VIN】：LJD8BB3F0P0000386 【发生日期 & 时间】：2023-05-25 11:23:18 【log路径】：数采已上云、HHTU log见附件			

History			
#1 - 2023-05-26 17:23 - CDTS_TEST 王成			
- Status changed from New to RESOLVED			
与118233重复			
#2 - 2023-05-26 17:23 - CDTS_TEST 王成			
- Status changed from RESOLVED to VERIFIED			
#3 - 2023-05-26 17:23 - CDTS_TEST 王成			
- Status changed from VERIFIED to CLOSED			
Files			
PVC1-1557 新库16组包-FAIL.txt	803 KB	2023-05-26	CDTS_TEST 王成