

Status:	CLOSED	Start date:	2023-06-06
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0106
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Rarely	Fixed Version:	2023-06-06
Test Type:	ST	Root cause:	确认按钮样式不完善。
Description			
【环境信息】EE环境 【问题出现时间】：20230606 15：04 【前提条件】：副屏上电；中控、功放已连接；副屏、中控时间一致，蓝牙耳机已连接 【操作步骤】 1.点击连接中的蓝牙耳机设备名称 2.点击修改设备名称 3.点击输入20个中文字符 4.点击重命名 【实际结果】 1.设备名称无法保存 【期望结果】 1.设备名称保存成功 【备注】： 偶现问题 第一次遇到 第283次开机 开机时长：4：16：23 蓝牙设备型号：安卓蓝牙耳机设备 中控VIN号：HRYTTESTVINMGM817 【中控版本号】：03.02.0088.c103.02_NO 【副屏版本号】：01.00.0106.c104			

ID	Project	Branch	Uploader
205293	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Adapter dialog button style.TC-RID: 1201-0201813IssueID: TS-R-BUG-118582Change-Id: I24c96b98e2721cdfb9a3a352e133e46a44bcd317			

#3 - 2023-06-06 21:06 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-06-06
- Root cause set to 确认按钮样式不完善。

■ Current conclusion

已处理，代码已入库。

■ My analysis

按钮不可用和可用状态显示没有做区分导致，已处理样式。

■ Next action

测试验证。

#4 - 2023-06-08 15:26 - SZTS_TEST 邹涛

- Status changed from RESOLVED to VERIFIED

在FlatBuild_HH_MCE_FSE.M.D.user.01.00.C104.202306080125验证20次未复现

#5 - 2023-06-08 20:15 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED