

Figure - Bug #118745

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT2】【设置】下拉控制中心，长按位置信息进入设置，上划进入recent界面有两个设置

2023-06-12 16:45 - CDTs_Test 吴诗雨

Status:	CLOSED	Start date:	2023-06-12
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C104(X104)
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-06-12
Reproducibility:	Every time	Root cause:	Settings 页面中转处理不完善导致。
Test Type:	ST		

Description
【前提条件】
1、设备正常启动
2、控制中心中添加位置信息组件
【测试步骤】
1、下拉控制中心
2、长按位置信息打开设置
3、上划进入recent界面，查看设置数量
【预期结果】
3、只有一个设置卡片
【实际结果】
3、有两个设置卡片

History

#1 - 2023-06-12 20:22 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
206518	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Remove task of SettingsActivity.TC-RID: 1201-0201813IssueID: TS-R-BUG-118745Change-Id: I9c1bba3edd4b434472ee2a5cc010b09a553f8f7d			

#2 - 2023-06-12 20:23 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CDTs_Test 吴诗雨
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-06-12

- Root cause set to Settings 页面中转处理不完善导致。

■ Current conclusion

已处理，代码已入库。

■ My analysis

Settings 页面中转处理不完善导致。

■ Next action

测试验证。

#3 - 2023-06-13 16:25 - SZTS_TEST 邹涛

- Status changed from RESOLVED to VERIFIED

在FlatBuild_HH_MCE_FSE.M.R.user.01.00.0110.C104版本验证通过

#4 - 2023-06-25 13:58 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED