

Status:	CLOSED	Start date:	2023-07-10
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	01.00.0120.C106(X106)
Resolution:	--	Degrated:	--
Severity:	Critical	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
【测试版本】 01.00.0120.C106			
【测试步骤】 设备上电后6 7秒插入屏幕投屏线，设备冻屏，断电重启恢复			

History

- #1 - 2023-07-12 10:33 - CD BSP-余霄
- Status changed from New to RESOLVED
 - Assignee changed from CD BSP-余霄 to CD TEST-方永红
 - % Done changed from 0 to 100

修改链接：
<https://dev.thundercomm.com/gerrit/c/general/kernel/msm-4.19/+213974>

验证版本：
/Figure/VerifyBuild/Pre_figure_turbox-c2130c-la1.1-qssi12-dev/20230711/202307112158-1229

自验证：

上电UEFI流程跑完插入GMSL，显示OK、touch OK

上电atmel驱动跑完插入GMSL，显示OK、touch OK

上电到进入系统桌面插入GMSL，显示OK、touch OK

热插拔验证，显示OK、touch OK

#2 - 2023-07-12 13:48 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
213974	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com
BSP:TP: Fix ATMEL cold plug and hot plug problemsFix ATMEL cold plug and hot plug problemsTC-RID: 1201-0100401IssueID: TS-R-DF-119017Change-Id:			

#3 - 2023-07-13 21:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
214145	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
BSP:TP: Fix ATMEL cold plug and hot plug problemsFix ATMEL cold plug and hot plug problemsTC-RID: 1201-0100401IssueID: TS-R-DF-119017Change-Id: Ib85a9b1105c846cfef204228194a47010b930054(cherry picked from commit 4d2c315d5fd9885dbdf2663a2d6bd12f1ab2a251)			

#4 - 2023-07-14 17:46 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

0713DB验证20次未复现

0122验证10次未复现

#5 - 2023-07-14 17:46 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED