

Status:	RESOLVED	Start date:	2023-10-14
Priority:	Normal	Due date:	
Assignee:	CD LC邓帅	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	9.10
Resolution:	--	Degrated:	--
Severity:	Critical	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	CT	Root cause:	
Description			

History

#1 - 2023-10-14 22:32 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
318612	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xin.yang_a@thundersoft.com
LC:BT:Set Set the Bluetooth broadcast power to -25TC-RID: 0301-0400103IssueID: TS-R-BUG-119497, VCH-183Change-Id: I9e4cfd10b8250381ca307681e58e0455eb7f8e39			

#2 - 2023-10-16 19:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
319955	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xin.yang_a@thundersoft.com
LC:HiCar:Set the Bluetooth broadcast power to -28TC-RID: 0301-0400103IssueID: TS-R-BUG-119497, VCH-183Change-Id: I7d84ba160203e6e3fa2fe9f736d450a8285add99			

#3 - 2023-10-20 21:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
321363	general/device/qcom/qssi	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
LC:HiCar:Set parameter for wireless connectivity.TC-RID: 0301-0400103IssueID: TS-R-BUG-119497, VCH-109Change-Id: I265f157054aa62824642afe20bac1dd312a17e72			

#4 - 2023-10-21 09:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
321053	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
LC:HiCar:Set the Bluetooth broadcast power to -34TC-RID: 0301-0400103IssueID: TS-R-BUG-119497, VCH-183Change-Id: I4fdccb0b58c8e67f77ebd280f56edd8a8b87d0e6			

#5 - 2023-10-21 15:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
321516	general/device/qcom/qssi	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
LC:HiCar:Set parameter for wireless connectivity.Close wifi during hicar connect, else it will connect failed.TC-RID: 0301-0400103IssueID: TS-R-BUG-119497, VCH-183Change-Id: Iaa200374f24621872d597e8317a5d50aac2b6f54			

#6 - 2023-10-27 02:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323321	general/device/qcom/qssi	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:HiCar:Set parameter for wireless connectivity.TC-RID: 0301-0400103IssueID: TS-R-BUG-119497, VCH-109Change-Id: I265f157054aa62824642afe20bac1dd312a17e72(cherry picked from commit 0006207e914e6a0e6a54029a717f45d8675de1e3)			

#7 - 2023-10-27 02:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323322	general/device/qcom/qssi	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:HiCar:Set parameter for wireless connectivity.Close wifi during hicar connect, else it will connect failed.TC-RID: 0301-0400103IssueID: TS-R-BUG-119497, VCH-183Change-Id: Iaa200374f24621872d597e8317a5d50aac2b6f54(cherry picked from commit 57f500a2b0c36eb9dba838ac2cc2f34494f34c13)			