Figure - Bug #117942

IOVDEV-25481   BSP   EVT3

2023-05-15 20:33 -   _CDTS

Status:	CLOSED		Start date:	2023-05-15
Priority:	Normal		Due date:	
Assignee:	_CDTS		% Done:	100%
Category:	BSP		Estimated time:	0.00 hour
Target version:				
Need_Info:	--		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Resolution:	--		Degrated:	--
Severity:	Normal		Verified Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0101.C103(X
Reproducibility:	Every time		Fixed Version:	
Test Type:	Release Test		Root cause:	TP powerkey, TP

Description

Related issues:

Related to Figure - Bug # 117763: IOVDEV-25481 VC1 007...	CLOSED	2023-05-05

History

#1 - 2023-05-16 09:54 - CD FW

- Category changed from CD-FW to BSP

- Status changed from New to ASSIGNED

- Assignee changed from CD APP-   to CD BSP-

Hi

         #117763

#2 - 2023-05-17 15:46 - CD BSP-

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD BSP-   to   _CDTS

- % Done changed from 0 to 100

- Root cause set to   TP   powerkey,   TP   app

https://dev.thundercomm.com/gerrit/c/general/kernel/msm-4.19/+/199224

        DB   close

#3 - 2023-05-18 10:30 -   _TSCD

- Status changed from RESOLVED to VERIFIED

- Verified Version set to FlatBuild_HH_MCE_FSE.M.R.user.01.00.0101.C103(X103)

#4 - 2023-05-18 10:30-   _T.SCD
- Status changed from VERIFIED to CLOSED