Figure - Bug #117947

IOVDEV-27611

2023-05-15 21:38 - CD TEST-

Status:	CLOSED	Start date:	2023-05-15
Priority:	Normal	Due date:	
Assignee:	CD TEST-	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C 103(X103)
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0101.C 103(X
Reproducibility:	Every time	Fixed Version:	2023-05-17
Test Type:	ST	Root cause:	GMT+0 Europe/London

Description

History

#1 - 2023-05-16 17:42 - CD FW-

- *Status changed from New to ASSIGNED*

- *Root cause set to   GMT+0   Europe/London   GMT+1*

#2 - 2023-05-16 21:05 - CD FW-

Current conclusion

My analysis

GMT+0   Europe/London   GMT+1

Next action

GMT+0

#3 - 2023-05-17 19:38 - CD FW-

- *Status changed from ASSIGNED to RESOLVED*

- *Assignee changed from CD FW-   to CD TEST-*

- *% Done changed from 0 to 100*

- *Resolution changed from -- to FIXED*

- *Degrated changed from -- to No*

- *Fixed Version set to 2023-05-17*

Current conclusion

bug

My analysis

GMT+0   Europe/London   GMT+1

Submit URL

https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/VehicleControl/+/200783

#4 - 2023-05-18 10:48 - CD TEST-

5.18

#5 - 2023-05-18 14:53 - CD TEST-

- *Status changed from RESOLVED to VERIFIED*

- *Verified Version set to FlatBuild_HH_MCE_FSE.M.R.user:01.00.0101.C103(X103)*

5.18

#6 - 2023-05-18 14:53 - CD TEST-

- *Status changed from VERIFIED to CLOSED*

Files

20230515-213608.jpg	220 KB	2023-05-15	CD TEST-