

Figure - 开发 Dev #110644

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110125 (New): 【MK】【BSP】管理总票

开发 Dev # 110643 (进行中 In Progress): 【MK】【006】【Ethernet】主任务

【MK】【006】【Ethernet】【TC-RID: 1201-0400601】以太网卡bring up

2022-07-25 12:24 - CD TPM-申艳艳

Status:	完成 Closed	Start date:	2022-07-25
Priority:	Normal	Due date:	2022-08-10
Assignee:	SZTS_TEST 邹涛	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:			
Description			
请填写信息：			
■ 需求列表:			
https://thundersoft.feishu.cn/sheets/shtcnqaFykINsnMcKWLuICl3xnc L15			
以太网卡bring up			
■ 提出URL：必填			
■ 自测case：必填			
■ 注意点：需要测试注意的前提条件			

History

- #1 - 2022-08-01 15:13 - SZ TPM-罗云进
- Due date set to 2022-08-10
 - Category changed from 714 to 707
 - Assignee changed from SZ TPM-罗云进到 SZ BSP-刘世江
- #2 - 2022-08-04 16:13 - CD TPM-申艳艳
- Subject changed from 【MK】【006】【Ethernet】【TC-RID: 0301-04000601】以太网卡bring up to 【MK】【006】【Ethernet】【TC-RID: 0301-0400601】以太网卡bring up
- #3 - 2022-08-04 21:25 - CD TPM-申艳艳
- Subject changed from 【MK】【006】【Ethernet】【TC-RID: 0301-0400601】以太网卡bring up to 【MK】【006】【Ethernet】【TC-RID: 1201-0400601】以太网卡bring up
- #4 - 2022-08-05 13:45 - SZ BSP-刘世江
- Status changed from New to 进行中 In Progress
 - % Done changed from 0 to 90
- 已完成bringup目标：可ping通www.baidu.com
- 8/5:已自测完成，可使用 ping www.baidu.com 命令ping通。
- 验证方法：
1. 开机，连接转换器及网线到TP-LINK路由器（需要确保路由器的网络无问题）
 2. ifconfig eth0查看是否分配IP，如果未分配IP，可能是转换器连接线路不稳定，重新插拔。
 3. ping www.baidu.com
- #5 - 2022-08-05 13:52 - SZ BSP-刘世江

- Assignee changed from SZ BSP-刘世江 to SZ TPM-罗云进

#6 - 2022-08-19 13:11 - SZ TPM-罗云进

- Assignee changed from SZ TPM-罗云进 to SZTS_TEST 邹涛

- % Done changed from 90 to 100

#7 - 2022-08-19 20:10 - SZTS_TEST 邹涛

- Status changed from 进行中 In Progress to 完成 Closed

#8 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
140963	general/platform/vendor/qcom/kona	Pre_figure_turbox-c2130c-la1.1-vendor-dev	shijiang.liu@thundercomm.com
BSP:Ethernet: Bringup [2/3]add tools to vendor/binTC-RID: 0301-0400601IssueID: TS-R-DF-110644Change-Id: Idee2bcdcc20d5d87937c89676cda53ec1ed6932f			

#9 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
140965	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	shijiang.liu@thundercomm.com
BSP:Ethernet: Bringup [1/3]1. change boot option of pcie12. add dts node about gpio of phy and LanTC-RID: 0301-0400601IssueID: TS-R-DF-110644Change-Id: I66a07aadd7a8054c58e9b0a8e20c6ff9b61a3a39			

#10 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
140989	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	shijiang.liu@thundercomm.com
BSP:Ethernet: Bringup [3/3]1. add phy chip driver marvell-88x2112.c2. close CONFIG_DEBUG_ATOMIC_SLEEP for fix crash3. add the power-on timing of the mac chip in mac driverTC-RID: 0301-0400601IssueID: TS-R-DF-110644Change-Id: I415d6819841979700b5eb5f5da473f2ee4dffcd9			

#11 - 2022-12-22 20:24 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader

143147	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	huangpf1028@thundersoft.com
LC:Ethernet: enable Android kernel VLAN supportEnable kernel VLAN supportTC-RID: 1201-0400601IssueID: TC-R-DF-110644Change-Id: Id60f332db9f26e89ecea6078eedebc62f68f78a6			

#12 - 2022-12-22 20:24 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143454	general/platform/vendor/thundercom/ethernet	Pre_figure_turbox-c2130c-la1.1-vendor-dev	huangpf1028@thundersoft.com
LC:Ethernet: Add ethernet configAdd ethernet configTC-RID: 1201-0400601IssueID: TC-R-DF-110644Change-Id: I656439a6b83e1dc8880a89c7a2f233429dcd09b4			

#13 - 2022-12-22 20:24 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143498	general/platform/vendor/qcom/kona	Pre_figure_turbox-c2130c-la1.1-vendor-dev	huangpf1028@thundersoft.com
LC:Ethernet: Add etheret buildAdd etheret buildTC-RID: 1201-0400601IssueID: TC-R-DF-110644Change-Id: I241f079a662ca62fb49b5b40dbb09466f47cd922			

#14 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143705	general/platform/external/iproute2	Pre_figure_turbox-c2130c-la1.1-vendor-dev	huangpf1028@thundersoft.com
LC:Ethernet: Add ip to compile in vendor partitionAdd ip to compile in vendor partitionTC-RID: 1201-0400601IssueID: TC-R-DF-110644Change-Id: I284175dd096d73f8763cfe59edce561421bbb3ae			

#15 - 2022-12-22 20:29 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147046	general/platform/vendor/thundercom/ethernet	Pre_figure_turbox-c2130c-la1.1-vendor-dev	huangpf1028@thundersoft.com

LC:Ethernet: Fix vlanidfix vlanidTC-RID: 1201-0400601IssueID: TS-R-DF-110644Change-Id: I2d9b7ef57801ef63b3c73b3fb2fec768ae1ad2a4