

Figure - 开发 Dev #110650

开发 Dev # 110122 (New): 【MK】管理总票
开发 Dev # 110125 (New): 【MK】【BSP】管理总票
开发 Dev # 110647 (进行中 In Progress): 【MK】【011】【Audio】主任务
【MK】【011】【Audio】【TC-RID: 1201-0101103】AD2428 Driver移植
2022-07-25 12:40 - CD TPM-申艳艳

Status:	取消 Canceled	Start date:	2022-07-25
Priority:	Normal	Due date:	
Assignee:	CD BSP-唐金泽	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
请填写信息：			
■ 需求列表:			
https://thundersoft.feishu.cn/sheets/shtcnqaFykINsnMcKWLuICl3xnc L25			
SmartPA Driver相关配置			
■ 提出URL：必填			
■ 自测case：必填			
■ 注意点：需要测试注意的前提条件			

History

- #1 - 2022-07-25 12:40 - CD TPM-申艳艳
- Parent task set to #110647
- #2 - 2022-08-01 16:15 - SZ TPM-罗云进
- Category changed from 714 to 703
- Assignee changed from SZ TPM-罗云进 to SZ SW-Audio-盛举
- #3 - 2022-08-02 16:40 - SZ SW-Audio-盛举
- Subject changed from 【MK】【011】【Audio】【TC-RID: 0301-0101103】SmartPA Driver相关配置 to 【MK】【011】【Audio】【TC-RID: 0301-0101103】AD2428 Driver移植
- #4 - 2022-08-04 21:26 - CD TPM-申艳艳
- Subject changed from 【MK】【011】【Audio】【TC-RID: 0301-0101103】AD2428 Driver移植 to 【MK】【011】【Audio】【TC-RID: 1201-0101103】AD2428 Driver移植
- #5 - 2022-08-05 13:47 - SZ SW-Audio-盛举
- Status changed from New to 进行中 In Progress
- % Done changed from 0 to 60
- #6 - 2022-09-22 19:44 - SZ TPM-罗云进
- Assignee changed from SZ SW-Audio-盛举 to CD BSP-杜磊
- #7 - 2022-10-28 16:12 - CD BSP-唐金泽
- Category set to BSP
- Assignee changed from CD BSP-杜磊 to CD BSP-夏实
- #8 - 2022-10-31 16:40 - CD BSP-夏实

AD2428驱动移植,上电配置：

<http://10.0.232.3/gerrit/c/general/LINUX/android/vendor/qcom/proprietary/+/140557>
<http://10.0.232.3/gerrit/c/general/LINUX/android/vendor/qcom/proprietary/+/141120>

#9 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141118	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	shengju0304@thundersoft.com
Audio: Bring up AD2428 chip(1/2)Add AD2428 driverTest Result:Normal communication with AD2428 chip through I2C.TC-RID: 0301-0101103IssueID: TS-R-DF-110650Change-Id: Ib3deb7eba8f2dd1f43eb120e383a1432215dbc93			

#10 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141120	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	shengju0304@thundersoft.com
Audio: Bring up AD2428 chip(2/2)Add AD2428 device in devicetreeTest Result:Normal communication with AD2428 chip through I2C.Change-Id: I68e97e529f5da9a4bd5983194cd75c49ad4a56a5TC-RID: 0301-0101103IssueID: TS-R-DF-110650			

#11 - 2023-05-16 15:15 - CD BSP-唐金泽

- Status changed from 进行中 In Progress to 取消 Canceled
- Assignee changed from CD BSP-夏实 to CD BSP-唐金泽
- % Done changed from 60 to 100