

Figure - 开发 Dev #110653

开发 Dev # 110122 (New): 【MK】 管理总票
开发 Dev # 110125 (New): 【MK】 【BSP】 管理总票
开发 Dev # 110647 (进行中 In Progress): 【MK】 【011】 【Audio】 主任务
【MK】 【011】 【Audio】 【TC-RID: 1201-0101106】 Audio Hal相关修改
2022-07-25 12:43 - CD TPM-申艳艳

Status:	New	Start date:	2022-07-25
Priority:	Normal	Due date:	2022-08-10
Assignee:	CD BSP-夏实	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
请填写信息： ■需求列表： https://thundersoft.feishu.cn/sheets/shtcnqaFyklnSnMcKWlulCI3xnc L31 Audio Hal相关修改 ■提出URL：必填 ■自测case：必填 ■注意点：需要测试注意的前提条件			

History

- #1 - 2022-08-01 15:46 - SZ TPM-罗云进
- Due date set to 2022-08-10
- #2 - 2022-08-01 15:56 - SZ TPM-罗云进
- Category changed from 714 to 703
- Assignee changed from SZ TPM-罗云进 to SZ SW-Audio-盛举
- #3 - 2022-08-04 21:27 - CD TPM-申艳艳
- Subject changed from 【MK】 【011】 【Audio】 【TC-RID: 0301-0101106】 Audio Hal相关修改 to 【MK】 【011】 【Audio】 【TC-RID: 1201-0101106】 Audio Hal相关修改
- #4 - 2022-09-22 19:45 - SZ TPM-罗云进
- Assignee changed from SZ SW-Audio-盛举 to CD BSP-杜磊
- #5 - 2022-10-28 16:13 - CD BSP-唐金泽
- Category set to BSP
- Assignee changed from CD BSP-杜磊 to CD BSP-夏实
- #6 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
143535	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-dev	shengju0304@thundersoft.com

BSP: Audio: Modify playback and record pathConfig audio path in XML file according to HW design.Test Result:Play music normally when use Music App to test.TC-RID: 1201-0101106IssueID: TS-R-DF-110653Change-Id: Ib1475b44388efff2aa8233cf5ec2855147cf9f8e

#7 - 2023-01-03 22:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
172706	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangjz1204@thundersoft.com
BSP:AUDIO: Change Audio config 2 channel in mixer_paths.xmlChange Audio config 2 channel in mixer_paths.xmlTC-RID: 1201-0101106IssueID: TS-R-DF-110653Change-Id: I8c182f1ea8f85a98f9137498c487c606e376d2d1			