

Figure - 开发 Dev #110655

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110125 (New): 【MK】【BSP】管理总票

开发 Dev # 110654 (进行中 In Progress): 【MK】【005】【LCD】主任务

【MK】【005】【LCD】【TC-RID: 1201-0100501】初始化LCD设置

2022-07-25 12:52 - CD TPM-申艳艳

Status:	解决 Resolved	Start date:	2022-09-09
Priority:	High	Due date:	2022-09-12
Assignee:	CD BSP-余霄	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
请填写信息： ■ 需求列表： https://thundersoft.feishu.cn/sheets/shtcnqaFykINSnMcKWLuICl3xnc L33 点亮显示屏 ■ 提出URL：必填 ■ 自测case：必填 ■ 注意点：需要测试注意的前提条件			
Subtasks:			
开发 Dev # 111848: 【MK】【005】【LCD】【TC-RID: 1201-0100501】VC1-FSE-BU			完成 Closed

History

- #1 - 2022-07-25 12:54 - CD TPM-申艳艳
- Parent task changed from #110646 to #110654
- #2 - 2022-08-02 14:15 - SZ TPM-罗云进
- Due date set to 2022-08-10
- Status changed from New to 进行中 In Progress
- Assignee changed from SZ TPM-罗云进到 软件二组_SD3 朱彦斌
- #3 - 2022-08-02 14:16 - SZ TPM-罗云进
- Category changed from 714 to BSP
- #4 - 2022-08-04 21:28 - CD TPM-申艳艳
- Subject changed from 【MK】【005】【LCD】【TC-RID: 0301-0100501】初始化LCD设置to 【MK】【005】【LCD】【TC-RID: 1201-0100501】初始化LCD设置
- #5 - 2022-09-09 13:55 - CD BSP-余霄
- Due date changed from 2022-08-10 to 2022-09-12
- Status changed from 进行中 In Progress to 保留中 Pending
- Assignee changed from 软件二组_SD3 朱彦斌到 CD BSP-余霄
- % Done changed from 0 to 80
- #6 - 2022-09-09 13:56 - CD BSP-余霄
- % Done changed from 80 to 50
- #7 - 2022-09-21 12:29 - CD BSP-余霄
- Status changed from 保留中 Pending to 解决 Resolved

VC1屏幕已点亮，相关PATCH已入库

<https://dev.thundercomm.com/gerrit/c/general/kernel/msm-4.19/+/147791>
<https://dev.thundercomm.com/gerrit/c/general/LINUX/android/vendor/qcom/proprietary/+/148123>

目前正在调试背光与兼容

#8 - 2022-10-09 10:27 - CD BSP-余霄

VX1 EVT2 Bringup相关PATCH
<https://dev.thundercomm.com/gerrit/c/general/LINUX/android/vendor/qcom/proprietary/+/154041>

#9 - 2022-10-12 18:01 - CD BSP-余霄

VC1 EVT2 Bringup相关PATCH
<https://dev.thundercomm.com/gerrit/c/general/LINUX/android/vendor/qcom/proprietary/+/154523>

#10 - 2022-12-22 20:20 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
140601	general/trustzone_images	Pre_figure_turbox-c2130c-la1.1-vendor-dev	yanbin.zhu@thundercomm.com
BSP:LCD: Change QUPV3_0_SE0 to I2C for MAX96755Change QUPV3_0_SE0 from SPI to I2C based on HW designTC-RID: 0301-0100501IssueID: TS-R-DF-110655Change-Id: I3290238c7d7a92f664edae4c954573932064c0a0			

#11 - 2022-12-22 20:20 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
140602	general/aop_proc	Pre_figure_turbox-c2130c-la1.1-vendor-dev	yanbin.zhu@thundercomm.com
BSP:LCD: Change L1F ON PM8009 to NPM modeChange L1F to NPM mode for power supply of max96755 IOTC-RID: 0301-0100501IssueID: TS-R-DF-110655Change-Id: Ibdcf9809541c060af5a96538d8928d0d99130b6d			

#12 - 2022-12-22 20:20 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
140603	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	yanbin.zhu@thundercomm.com

BSP:LCD: Add DRM Notifier for wake and sleep(2/2)Add DRM notifier block for device boot, sleep and wakeTC-RID: 0301-0100501IssueID:
TS-R-DF-110655Change-Id: Id935706675253f0abc2418f53d840eb155132c3c

#13 - 2022-12-22 20:20 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
140604	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	yanbin.zhu@thundercomm.com
BSP:LCD: Bringup MAX96755 for Display1. Add driver for MAX96755/752 and keep panel's MCU awake2. Init MAX96755G/F and MAX96752F to enable video transmissionthrough GMSL LINKTC-RID: 0301-0100501IssueID: TS-R-DF-110655Change-Id: Id09e7683c2316cffce1b2a0638c31d5e281798f6			

#14 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
140610	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	yanbin.zhu@thundercomm.com
BSP:LCD: Configure Truly Panel as primary display1. Add a new panel "hx82101-hx8692-truly" based on spec2. Configure the new panel as primary displayTC-RID: 0301-0100501IssueID: TS-R-DF-110655Change-Id: I7844b999ba13e537f23e7d108bc8ca805ab3fcff			

#15 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
140611	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	yanbin.zhu@thundercomm.com
BSP:LCD: Add MAX96755 in DevicetreeAdd MAX96755 in dtsi for driver parsingTC-RID: 0301-0100501IssueID: TS-R-DF-110655Change-Id: I85c08a695e5ed899fcc640d8f2fa9724f38097a2			

#16 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
140614	general/platform/vendor/opensource/display-drivers	Pre_figure_turbox-c2130c-la1.1-vendor-dev	yanbin.zhu@thundercomm.com

BSP:LCD: Add DRM Notifier for wake and sleep(1/2)Add DRM notifier block for device boot, sleep and wakeTC-RID: 0301-0100501IssueID: TS-R-DF-110655Change-Id: I399b71b4375520d3be95b71448da7fa095a7f55c

#17 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141869	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	yanbin.zhu@thundercomm.com
BSP:LCD: Configure GPIO Of MAX96755/752 for TPConfigure GPIO2 Of both MAX96755 and MAX96752 for TP IRQConfigure GPIO9 Of MAX96755 and GPIO8 Of MAX96752 for TP ResetTC-RID: 0301-0100501IssueID: TS-R-DF-110655Change-Id: If3fde4e2107118ad2bc4ee2c338a3ac7e5743fa7			

#18 - 2022-12-22 20:34 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150254	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com
BSP:LCD: MCE display adapts to boardidMCE display adapts to boardidTC-RID: 1201-0100501IssueID: TS-R-DF-110655Change-Id: I7aa3e1925954bc1662f5bf9889de4848366db178			

#19 - 2022-12-22 20:34 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150256	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com
BSP:LCD: FSE display adapts to boardidFSE display adapts to boardidTC-RID: 1201-0100501IssueID: TS-R-DF-110655Change-Id: Iaf8916160a3bc08b5763c921e3e419f412c9c9ef			

#20 - 2022-12-22 20:34 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150325	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com

BSP:LCD: MAX96755 adapts to boardidMAX96755 adapts to boardidTC-RID: 1201-0100501IssueID: TS-R-DF-110655Change-Id: I39346d40e512b2040c61db440b1d5b2ac7568f8f

#21 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154041	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiaodong.li@thundersoft.com
BSP:DTSI: Add Display Config to EVT2 DTSIadd display config to evt2 dtsiTC-RID: 1201-0100501IssueID: TS-R-DF-110655Change-Id: If83b7204ff3be24a3373d46fdee0bbc5e2f9a146			

#22 - 2022-12-22 20:41 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154523	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com
BSP:LCD: Add Display Config to EVT2 DTSIAdd display config to VC1 evt2 dtsiTC-RID: 1201-0100501IssueID: TS-R-DF-110655Change-Id: Idb68db42247a19ec22cc1114151df90ed3f20fb5			

#23 - 2022-12-22 20:43 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155320	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-ftm	xiao.yu@thundersoft.com
BSP:LCD: Add Display Config to EVT2 DTSIAdd display config to VC1 evt2 dtsiTC-RID: 1201-0100501IssueID: TS-R-DF-110655Change-Id: Idb68db42247a19ec22cc1114151df90ed3f20fb5(cherry picked from commit cc1621d2e75ae03bfead45bbe55727e1cc5628da)			

#24 - 2022-12-22 20:43 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155321	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-ftm	xiao.yu@thundersoft.com

BSP:DTSI: Add Display Config to EVT2 DTSIadd display config to evt2 dtsiTC-RID: 1201-0100501IssueID: TS-R-DF-110655Change-Id: If83b7204ff3be24a3373d46fdee0bbc5e2f9a146(cherry picked from commit 2a8ae93cf438cbc8604ef14dde613d4af00d8bd2)

#25 - 2022-12-22 20:50 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160726	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com
BSP:LCD: Add Display Config to DVT PVT and MP DTSIAdd display config to DVT PVT and MP dtsiTC-RID: 1201-0100501IssueID: TS-R-DF-110655Change-Id: I9902e19ee66c449ea7d012ae55b9fd846a4bba1a			