

Figure - 开发 Dev #110658

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110125 (New): 【MK】【BSP】管理总票

开发 Dev # 110657 (进行中 In Progress): 【MK】【004】【TP】主任务

【MK】【004】【TP】【TC-RID: 1201-0100401】初始化TP设置

2022-07-25 13:01 - CD TPM-申艳艳

Status:	解决 Resolved	Start date:	2022-07-25
Priority:	Normal	Due date:	
Assignee:	CD BSP-余霄	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
请填写信息：			
■ 需求列表:			
https://thundersoft.feishu.cn/sheets/shtcnqaFykINsnMcKWLuICl3xnc L37			
bring up TP			
■ 提出URL：必填			
■ 自测case：必填			
■ 注意点：需要测试注意的前提条件			

History
#1 - 2022-08-02 14:19 - SZ TPM-罗云进
- Assignee changed from SZ TPM-罗云进 to SZ BSP-徐季源
#2 - 2022-08-02 17:56 - SZ BSP-徐季源
- Status changed from New to 进行中 In Progress
#3 - 2022-08-02 18:29 - SZ BSP-徐季源
i2cdetect 检测不到任何设备，需要确认 MAX96735 是否要彦斌提交了才能用
#4 - 2022-08-03 18:49 - SZ BSP-徐季源
i2cdump能检测到了，但是驱动probe失败了
#5 - 2022-08-04 21:28 - CD TPM-申艳艳
- Subject changed from 【MK】【004】【TP】【TC-RID: 0301-0100401】初始化TP设置 to 【MK】【004】【TP】【TC-RID: 1201-0100401】初始化TP设置
#6 - 2022-08-05 18:50 - SZ BSP-徐季源
通过测量屏端的 pin，发现 RESET 信号还是不通，还需要彦斌再研究 MAX96755 的寄存器配置。
#7 - 2022-09-05 09:51 - SZ BSP-徐季源
- Assignee changed from SZ BSP-徐季源 to CD BSP-唐金泽
#8 - 2022-09-08 22:59 - CD BSP-唐金泽
- Assignee changed from CD BSP-唐金泽 to CD BSP-余霄

#9 - 2022-09-21 12:31 - CD BSP-余霄

- Status changed from 进行中 In Progress to 解决 Resolved

VC1 TOUCH 功能已实现，并且无回勾、手势等问题，但是部分区域上边坐标异常，固件还需进行调整

#10 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141918	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	jiyuan.xu@thundercomm.com
BSP: TP: CYAT817 bringup (1/2)Porting driver of Cypress TrueTouch Gen7 CYAT817TC-RID: 1201-0100401IssueID: TS-R-DF-110658Change-Id: Iad0c415c72c323a7a25457e65487fe05d968d322			

#11 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141920	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	jiyuan.xu@thundercomm.com
BSP: TP: CYAT817 bringup (2/2)Porting driver of Cypress TrueTouch Gen7 CYAT817TC-RID: 1201-0100401IssueID: TS-R-DF-110658Change-Id: Ib9d508a19daf6834c7f1f779c22c144e7e4c218bd			

#12 - 2022-12-22 20:23 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142236	general/device/qcom/common	Pre_figure_turbox-c2130c-la1.1-vendor-dev	jiyuan.xu@thundercomm.com
BSP: Platform: Temporarily comment the traceThe trace is enabled, and cause CPU to be slow on interrupts.Normally the trace should not be enabled, we currently don't knowwhy it is enabled, so we temporarily comment the ralted codes.TC-RID: 1201-0100401IssueID: TS-R-DF-110658Change-Id: If381702c1263618e4927edebc62a3aaff38c53e8			

#13 - 2022-12-22 20:23 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142684	general/quic/la/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	jiyuan.xu@thundercomm.com

		r-dev	
BSP: TP: Close Debug message for CYAT8171. Remove DEBUG and VDEBUG configTC-RID: 1201-0100401IssueID: TS-R-DF-110658Change-Id: la63894391fa645dc7bb46c4bafa1320fc1c1b0b			

#14 - 2022-12-22 20:27 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145638	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiaodong.li@thundersoft.com
BSP: TP: CYAT817 bringupComplete single click wakeup screen developmentTC-RID: 1201-0100401IssueID: TS-R-DF-110658Change-Id: I7be2ea37636177d0dbdd4e540ad07f6fd61648f3			

#15 - 2022-12-22 20:33 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150011	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com
BSP:TP: Bringup FSE Atmel touchscreenAdd Atmel mxt driver for touch screen.TC-RID: 1201-0100401IssueID: TS-R-DF-110658Change-Id: I4ee969b2ce1f5fa9da7500b21439643fa89a1c10			

#16 - 2022-12-22 20:34 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150244	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com
BSP:TP: MCE touchscreen adapts to boardidMCE touchscreen adapts to boardidTC-RID: 1201-0100401IssueID: TS-R-DF-110658Change-Id: I8bf878fdac5779316542506e900328deb69d599e			

#17 - 2022-12-22 20:34 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150255	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com

BSP:TP: Bringup FSE Atmel touchscreenBringup FSE VC1 Atmel touchscreenTC-RID: 1201-0100401IssueID: TS-R-DF-110658Change-Id:
lababc0949c8d4c2f29f5eb54c743ba015a3cde3e