

Figure - 开发 Dev #110672

开发 Dev # 110122 (New): 【MK】 管理总票

开发 Dev # 110125 (New): 【MK】 【BSP】 管理总票

【MK】 【003】 【stability】 【TC-RID: 1200-0800307】 系统稳定性

2022-07-25 13:31 - CD TPM-申艳艳

Status:	New	Start date:	2023-05-08
Priority:	Normal	Due date:	
Assignee:	CD SYSTEM-胡兵	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
请填写信息：			
■需求列表:			
https://thundersoft.feishu.cn/sheets/shtcnqaFyklNSnMcKWLulCI3xnc L67			
解决系统crash等问题			
■提出URL：必填			
■自测case：必填			
■注意点：需要测试注意的前提条件			
Subtasks:			
开发 Dev # 117826: 【MK】 【003】 【stability】 【TC-RID: 1200-0800307】 异常恢复机制			New
开发 Dev # 117827: 【MK】 【003】 【stability】 【TC-RID: 1200-0800307】 MPU...			解决 Resolved
开发 Dev # 117828: 【MK】 【003】 【stability】 【TC-RID: 1200-0800307】 开机动...			解决 Resolved
开发 Dev # 117829: 【MK】 【003】 【stability】 【TC-RID: 1200-0800307】 存储空...			完成 Closed
开发 Dev # 117830: 【MK】 【003】 【stability】 【TC-RID: 1200-0800307】 下电无...			解决 Resolved
开发 Dev # 117831: 【MK】 【003】 【stability】 【TC-RID: 1200-0800307】 使用过...			完成 Closed

History

#1 - 2022-08-02 15:03 - SZ TPM-罗云进

- Assignee changed from SZ TPM-罗云进 to SZ 系统-张丽果

#2 - 2022-08-04 21:37 - CD TPM-申艳艳

- Subject changed from 【MK】 【016】 【stability】 【TC-RID: 0300-0101601】 实现基本功能 to 【MK】 【003】 【stability】 【TC-RID: 1200-0800307】 系统稳定性

#3 - 2022-09-21 11:42 - CD BSP-杜磊

- Assignee changed from SZ 系统-张丽果 to CD SYSTEM-胡兵

#4 - 2023-07-04 11:33 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210398	general/platform/system/hardware/interfaces	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xu.xia@thundersoft.com
SYSTEM: Stability: Acquire_ Wake_ Lock hangcauses the card to get stuck and not feeding the dog increases the logTC-RID: 1200-0800307IssueID: TS-R-DF-110672, IOVDEV-32876Change-Id: I4885e89007aaf7fcf68890ff98f19cf8dae475bf			

#5 - 2023-07-04 11:33 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210395	general/platform/hardware/libhardwar e_legacy	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	xu.xia@thundersoft.com
SYSTEM: Stability: Acquire_ Wake_ Lock hangcauses the card to get stuck and not feeding the dog increases the logTC-RID: 1200-0800307IssueID: TS-R-DF-110672, IOVDEV-32876Change-Id: I3a78939fbbb6c149ccadd02c22c687b0dd0deb6e			

#6 - 2023-07-10 19:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213611	general/platform/hardware/libhardwar e_legacy	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
SYSTEM: Stability: Acquire_ Wake_ Lock hangcauses the card to get stuck and not feeding the dog increases the logTC-RID: 1200-0800307IssueID: TS-R-DF-110672, IOVDEV-32876Change-Id: I3a78939fbbb6c149ccadd02c22c687b0dd0deb6e(cherry picked from commit a0cbff86c31f21678b9d97ff16bc9fe02842bb02)			

#7 - 2023-07-10 19:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213612	general/platform/system/hardware/inte rfaces	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
SYSTEM:Stability: Acquire_ Wake_ Lock hangcauses the card to get stuck and not feeding the dog increases the logTC-RID: 1200-0800307IssueID: TS-R-DF-110672, IOVDEV-32876Change-Id: I4885e89007aaf7fcf68890ff98f19cf8dae475bf(cherry picked from commit c5e151739e0eb3c48b5dd7a58303f2039aba7dd1)			

#8 - 2023-09-04 19:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
309523	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
FW:Stability:MediaDevice sorting encountered pointerTC-RID: 1200-0800307IssueID: TS-R-DF-110672,IOVDEV-40687Change-Id: Ifec2610bc5a9c992d59f25f6d3f2dbb68e0cd46f			

Gerrit Merge Information :

ID	Project	Branch	Uploader
317141	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:Stability:MediaDevice sorting encountered pointerTC-RID: 1200-0800307IssueID: TS-R-DF-110672,IOVDEV-40687Change-Id: Ifec2610bc5a9c992d59f25f6d3f2dbb68e0cd46f(cherry picked from commit ff1b79f3af39d804f2a54bbb2f596d50f89c1f07)			