

Figure - 开发 Dev #110694

开发 Dev # 110122 (New): 【MK】管理总票
开发 Dev # 110126 (New): 【MK】【AF】管理总票
【MK】【AF】【Fota】【TC-RID: 1201-0200401】
2022-07-25 16:59 - CD FW-王伟

Status:	完成 Closed	Start date:	2022-07-25
Priority:	Normal	Due date:	
Assignee:	CD BSP 叶鹏	% Done:	90%
Category:		Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_update_20221130		
Description			
■ 需求列表: MCE: 由中控对接服务端,既有的一种方式, 参考一下VX1机型。 VC1: 通过DoIP直接对接服务端, 这个要新做。 客户那边7月底会提供接口文档, 8月份提供SDK。 07_Appendix_C3_OTA升级系统对以太网ECU的技术需求规范_V3.0.docx https://thundersoft.feishu.cn/file/boxcnH61MgFw7jutMffXX8v7FKY OTA流程参考流程图 .pdf https://thundersoft.feishu.cn/file/boxcnxQQKCAf5b3Vx8oHhcdzxFg HH_FOTA_Orch-simulator test tool-20211123.pdf https://thundersoft.feishu.cn/file/boxcn0kNtylQvHYQJVXegDrcesf ■ 提出URL : 必填 ■ 自测case : 必填 ■ 注意点 : 需要测试注意的前提条件			

History

- #1 - 2022-07-25 17:27 - CD FW-王伟
- Assignee set to CD FW-王伟
- #2 - 2022-08-04 19:42 - CD FW-王伟
- Subject changed from 【MK】【004】【Fota】【TC-RID: 0301-0200401】 to 【MK】【004】【Fota】【TC-RID: 1201-0200401】
- #3 - 2022-08-05 11:15 - CD FW-王伟
- Assignee changed from CD FW-王伟 to FW&MW2组_DLTS 刘显鹤
- #4 - 2022-09-08 08:26 - CD FW-王伟
- Subject changed from 【MK】【004】【Fota】【TC-RID: 1201-0200401】 to 【MK】【AF】【Fota】【TC-RID: 1201-0200401】
- #5 - 2022-09-08 08:36 - CD FW-王伟
- Assignee changed from FW&MW2组_DLTS 刘显鹤 to CD FW-王伟
- #6 - 2022-09-26 20:09 - CD FW-王伟
- Target version set to VX1_MCE_FSE_V3.0_update_20221130

#7 - 2022-11-08 13:43 - CD FW-王伟

- Status changed from New to 进行中 In Progress

- % Done changed from 0 to 70

#8 - 2022-12-08 17:49 - CD TPM-王祥林

- Assignee changed from CD FW-王伟 to CD BSP 叶鹏

- % Done changed from 70 to 90

#9 - 2022-12-22 20:24 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143207	general/platform/vendor/thundercomm/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:FOTA:add Mcu update test demoAdd the demo of the MCU upgrade for subsequent integrationTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I6f2b2088a436b5b69b45644b4ea2b9f02a485348			

#10 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143811	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:FOTA:Integrated mcu upgrade test demoIntegrated mcu upgrade test demoTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I73134b6b94b7594fc220f546562d044a23337536			

#11 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
144008	general/platform/vendor/thundercomm/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:FOTA:Add mcu upgrade error handlingAfter an upgrade error, the upgrade is no longer requested.And notify Mpu of the error type.TC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I3ff01338342a1b4f38d91c470052f5e98a09f11a			

#12 - 2022-12-22 20:27 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
144683	general/platform/vendor/thundercomm/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com

AF:FOTA:Add mcu reboot after upgrade1. Automatic restart after 5s after successful upgrade2. Repair file read failure causing crashTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I36fd199e73e8add2f78bee0f5febbf5d0f752686

#13 - 2022-12-22 20:27 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
144900	general/platform/vendor/thundercomm/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:FOTA:Add mcu reboot private permissionsTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I7a90245b6f29e0bb1a70f7493e6d2db4c82f4113			

#14 - 2022-12-22 20:27 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145294	general/platform/vendor/thundercomm/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:FOTA:Add check mcu version funcTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: Iae0863af65e5349609bc552dac54b866366e9b81			

#15 - 2022-12-22 20:36 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151187	general/platform/vendor/thundercomm/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
AF:FOTA:First version for SocketWrapperFirst version for SocketWrapperTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: Ibb675e2dcc1357e3c9ba312550f988bb27e70a8e			

#16 - 2022-12-22 20:36 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151322	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
AF:FOTA:First version for SocketWrapperFirst version for SocketWrapperTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id:			

#17 - 2022-12-22 20:37 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151686	general/platform/vendor/thundercomm/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	peng.wang_e@thundersoft.com
FW:FOTA: Replace the dynamic library of selfinstaller with the static library1. Replace Library File2. Modify CMakeLists.txt fileTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I9db0b15d2f23153a5e9a43ae34c9bb807c9e961b			

#18 - 2022-12-22 20:37 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152147	general/platform/vendor/thundercomm/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:FOTA: Add FOTA function by UpdateEngine.TC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: Ia1b1a69f431e4c33eca1cbfdabe75d17d5b99c0b			

#19 - 2022-12-22 20:38 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152399	general/platform/vendor/thundercomm/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:FOTA: Remove post_build property.1. Remove post_build property;2. Modfiy update logical and update.zip file dir;TC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I5d8188373eeba85c53287510b76ae200beecee71			

#20 - 2022-12-22 20:38 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152678	general/vendor/thundercomm/products/sepolicy_vnдр	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangwei0629@thundersoft.com
FW:FOTA: Add FOTA function by UpdateEngine.TC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I004d665e254e7392541607b0bc11dfe9079c00d3			

#21 - 2022-12-22 20:39 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152680	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
AF:FOTA: Add FOTA function by UpdateEngine.TC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: Ie4ed59d95fbc71622f7f2cfaaa15ff6ea280a787			

#22 - 2022-12-22 20:39 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152747	general/platform/system/core	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
AF:FOTA: Add FOTA function by UpdateEngine.TC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I98dded8b4f324eac6da4acfb13912b4e5f8dc8bf			

#23 - 2022-12-22 20:39 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152902	general/platform/system/core	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
AF:FOTA: Revert selinux rule for debug.rcThis reverts commit 6256e066c9c4aa68f589de30a5722bbf28757ecc.TC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: Ib74fc05707cfa3fbd8a4d1568811791e0afdc0a8			

#24 - 2022-12-22 20:39 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
153006	general/platform/system/update_engine	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
AF:FOTA: Add FOTA function by UpdateEngine.Add selinux role for systempropertyTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: Ieafdd9f34cbf2a205dd5f56e80f39a41d093420f			

#25 - 2022-12-22 20:39 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
153009	general/platform/vendor/thundercomm/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com

AF:FOTA: Opt ota update logical, perfect error message.TC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I20264694846dda91c930ca2fc065983f1fa5c869

#26 - 2022-12-22 20:43 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155343	general/platform/vendor/thundercomm/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:FOTA:Fix SocketWrapper pase json erroradd json file to systemadd start service when boot completemodif selfinstaller file nameTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I9f473cc1fee54851dec17a7b021edfa867105881			

#27 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155657	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:FOTA:add selfinstaller se permission AccessTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I54124703ea9660f5d132800e2b3bc9f996da06a0			

#28 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
156249	general/platform/vendor/thundercomm/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:FOTA:add log for updaterrwrapperTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: Iae4ea0613997c53814ddc5b49d3394f399a32349			

#29 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
156252	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:FOTA:modif selfinstaller se permission AccessTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I92d498fed173aebaae49ef645ac1cee7f22e7ac9			

#30 - 2022-12-22 20:47 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
158344	general/platform/vendor/thundercomm/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
AF:FOTA:Compile selfinstaller in android bp modeTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I4de193f3d5f96362830a6381dd63ab02647f9f52			

#31 - 2022-12-22 20:47 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
158468	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:FOTA:modif selfinstaller se permission AccessTC-RID: 1201-0200401IssueID: TS-R-DF-110694Change-Id: I4d26afccd7dba22ef4e9bc0a6b9c7522356bb0da			

#32 - 2023-05-19 18:14 - CD BSP 叶鹏

- Status changed from 进行中 In Progress to 完成 Closed