

Figure - 开发 Dev #110696

开发 Dev # 110122 (New): 【MK】管理总票
开发 Dev # 110126 (New): 【MK】【AF】管理总票
【MK】【AF】【Tlog】【TC-RID: 1201-0201101】
2022-07-25 17:00 - CD FW-王伟

Status:	进行中 In Progress	Start date:	2022-07-25
Priority:	Normal	Due date:	
Assignee:	CD SYSTEM-龚元祝	% Done:	50%
Category:		Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030		
Description			
■ 需求列表: 中科关于log的定制			
■ 提出URL：必填			
■ 自测case：必填			
■ 注意点：需要测试注意的前提条件			

History

#1 - 2022-08-04 19:42 - CD FW-王伟
- Subject changed from 【MK】【011】【Tlog】【TC-RID: 0301-0201101】 to 【MK】【011】【Tlog】【TC-RID: 1201-0201101】

#2 - 2022-08-05 19:14 - CD SYSTEM-胡兵
- Assignee changed from CD FW-王伟 to CD SYSTEM-胡兵

#3 - 2022-09-06 15:31 - CD SYSTEM-胡兵
- Status changed from New to 进行中 In Progress
- % Done changed from 0 to 50

已合入tlog工具：
<https://dev.thundercomm.com/gerriit/c/general/LINUX/android/vendor/qcom/proprietary/+144686>
<https://dev.thundercomm.com/gerriit/c/general/device/qcom/sepolicy/+144742>
<https://dev.thundercomm.com/gerriit/c/general/device/qcom/qssi/+144693>
<https://dev.thundercomm.com/gerriit/c/general/platform/vendor/qcom/steppe/+144691>
<https://dev.thundercomm.com/gerriit/c/general/device/thundercomm/TCDEV/+143986>
<https://dev.thundercomm.com/gerriit/c/general/device/thundercomm/TCDEV/+143772>
<https://dev.thundercomm.com/gerriit/c/general/platform/vendor/thundercomm/apps/LogSystem/+143771>

下一步计划：增加客制化功能，日志上传及相关策略

#4 - 2022-09-08 08:26 - CD FW-王伟
- Subject changed from 【MK】【011】【Tlog】【TC-RID: 1201-0201101】 to 【MK】【AF】【Tlog】【TC-RID: 1201-0201101】

#5 - 2022-09-09 09:44 - CD SYSTEM-胡兵
- Assignee changed from CD SYSTEM-胡兵 to CD SYSTEM-龚元祝

#6 - 2022-09-26 15:11 - CD SYSTEM-胡兵
- Target version set to VX1_MCE_FSE_V3.0_20221030

增加日志上传到主控功能，10月底完成

#7 - 2022-12-06 10:35 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
165823	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	hubing0803@thundersoft.com
CommitMessage	system:tlog: add boot time		

#8 - 2022-12-06 10:38 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
166439	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	hubing0803@thundersoft.com
CommitMessage	system:tlog: add boot time		

#9 - 2022-12-22 15:08 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
171658	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:LogSystem: Set bugreport checkbox disable and checked.TC-RID: 1201-0201102IssueID: TS-R-DF-110696Change-Id: I388f4a1e4ce7b57090365a76fa9773fca53a5701			

#10 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143771	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	hubing0803@thundersoft.com
system:tlog: Add tlog featureThis mechanism can collect the following logs:- Persist log- Fatal log- Manual logAfter the log compressed, it will upload tothe log server.TC-RID: 1201-0201101IssueID: TC-R-DF-110696Change-Id: I046a28d2a99acc8c318b1e143f550c4d92d0ea68			

#11 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader

143772	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hubing0803@thundersoft.com
system:tlog:add tlog feature 1. enable tlog tlog_pstore tzlog pacakages installingTC-RID: 1201-0201101IssueID: TC-R-DF-110696Change-Id: I5607b534515ba12a5dd68b5f6260d0a72123ec88			

#12 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143986	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hubing0803@thundersoft.com
system:tlog: add tlog seppolicyTC-RID: 1201-0201101IssueID: TC-R-DF-110696Change-Id: Ic7d64d7cc3604651bd2bfb54ef52fd9c95f821b0			

#13 - 2022-12-22 20:32 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
148608	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	zhaozj0108@thundersoft.com
SYSTEM: add pstore[kernel]1. add pstore defconfig and fix reset flow for panic;TC-RID: 1200-0800103IssueID: TS-R-DF-110696Change-Id: Ic4687452dfcc02ee0331a3da5afc34a7098801d			

#14 - 2022-12-22 20:32 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
148611	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	zhaozj0108@thundersoft.com
SYSTEM: add pstore[ds]1. add ramoops mem region to reserved memory;TC-RID: 1200-0800103IssueID: TS-R-DF-110696Change-Id: I2d201a22186e4b4679653a3aae01b161126db908			

#15 - 2022-12-22 20:41 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154648	general/platform/vendor/thundercomm/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com

AF:LogSystem: Add LogCollectService to package log files period.TC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I5570a37c10d6761e4e5b9257644eb56b572dd3eb

#16 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155963	general/platform/vendor/thundercomm/apps/TCHttpServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:LogSystem: Add LogFileServer project.1. First init;2. Create http server;3. Share '/data/tlog_package' folder;4. Add '/list' '/report' '/download' api;TC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: If017f3acf4cecc60653ccc597a708c20b2d72471			

#17 - 2022-12-22 20:45 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
156463	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:LogSystem: Add /data/tlog_package folder context.TC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I833e5b21aeee93a9100a175cc8d3ece51a8bf7a2			

#18 - 2022-12-22 20:45 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
156666	general/platform/vendor/thundercomm/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:LogSystem: Remove entry from launcherTC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I82b55b126ec4b80d6847cd18bb550630b23e8d04			

#19 - 2022-12-22 20:45 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
156669	general/platform/packages/apps/SettingsIntelligence	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com

AF:LogSystem: Add special code search.1. Add SpecialCodeHandler for setting search;2. Add LogClient start speical code;TC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I93a32cae2a3a3ffae054a60e83d090015ac401c3

#20 - 2022-12-22 20:54 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
165003	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangwei0629@thundersoft.com
AF:LogSystem: Add BootCount Read LogicTC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: If08dd1ea06338880138721f13e310d18d2f8adc2			

#21 - 2022-12-22 20:55 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
165127	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangwei0629@thundersoft.com
AF:LogSystem: Add BootCount Read LogicTC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I29266a2b65eb5ddda6e28b756ed1977a4936dd5a			

#22 - 2022-12-26 20:03 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
172361	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	zhaozj0108@thundersoft.com
system:tlog: rm debuggable judgetlog not rely on debuggable judge when startTC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I0170d8a92190ceb55e8de1ab2c258e19aba214d1			

#23 - 2022-12-28 19:11 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
172801	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:LogSystem: Optimize log collector app.1. Show tcp_dump checkbox on user version;2. Optimize dir /data/vendor/tlog/manual/qxdm/ file delete logical;TC-RID: 1201-0201102IssueID: TS-R-DF-110696Change-Id: I5a19e3c6349861b8830eedde0429cff42e0f15ee			

#24 - 2022-12-30 17:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
173157	general/platform/vendor/thundercomm/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:LogSystem: Optimize log collector app.1. Optimize tar command parameters;2. Optimize dir /data/tlog/manual/ file delete logical;TC-RID: 1201-0201102IssueID: TS-R-DF-110696Change-Id: Idad854cf84c12b5b0fe6caabd0cbb2a352aca604			

#25 - 2023-02-17 13:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
181413	general/platform/vendor/thundercomm/apps/TCHttpServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xu.xia@thundersoft.com
system:LogSystem: modify tlog ipmodify tlog ip to vlan4 (192.168.4.16)TC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I7f7e2656e82578f8efeb87e660c460d5373c8863			

#26 - 2023-02-17 13:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
182223	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xu.xia@thundersoft.com
system:LogSystem: add tlog app selinuxadd tlog app selinuxTC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I9534fa00d9b9cab76d966246793e0c26a2bd8132			

#27 - 2023-02-23 13:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
183417	general/platform/vendor/thundercomm/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xu.xia@thundersoft.com
system:LogSystem: tlog self-startingmodify tlog.rcTC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I0b422b06e9b8dfeda9b4c5835498994a70b5e895			

#28 - 2023-03-29 10:33 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
189779	general/platform/vendor/thundercom/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xu.xia@thundersoft.com
system:log: copy ota files to tlogmodify tlogd.shTC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I4381179409f24f0aae8dd9baaf70d7d9de8cf6b9			

#29 - 2023-03-29 10:33 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
189784	general/device/qcom/sepolicy_vndr	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xu.xia@thundersoft.com
system:log: copy ota files to tlogadd selinuxTC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I83c0aaa597296345a663f8bee783d69d41ac5e23			

#30 - 2023-03-29 10:33 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
189786	general/platform/vendor/thundercom/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xu.xia@thundersoft.com
system:log: copy ota files to tlogBoth automatic and manual packaging of tlogs requires the inclusion of ota filesTC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I28659ed5fb2934ea9f6d2ca986a210d66cc34db7			

#31 - 2023-04-12 15:11 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
193062	general/platform/vendor/thundercom/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xu.xia@thundersoft.com
SYSTEM: Tlog: Save boot count to system propertiesave boot_time to persist.sys.total_boot_countTC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I9e76a73c5894f0d3885779cb6a384f19804a89ef			

#32 - 2023-04-17 12:31 - CD TPM-王祥林

需要优化的参考这个文档。
<https://thundersoft.feishu.cn/sheets/shtcnbOMsx26TflytNNNoJonQ4nf?sheet=MWfngl>

#33 - 2023-04-27 21:24 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
195071	general/platform/vendor/thundercom/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xu.xia@thundersoft.com
SYSTEM :Tlog: modify tlog directory structuremodify persist to logcatTC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I16ae1560f8d245f61a91720b3009d7bfd676bf42			

#34 - 2023-04-27 21:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
195440	general/platform/vendor/thundercom/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xu.xia@thundersoft.com
SYSTEM :Tlog: modify tlog directory structure1. modify tlogd.sh2. modify manual directory structureTC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: Ifac6a9af41dddd9349641036dd6235fcb9e6f715			

#35 - 2023-04-27 21:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
196248	general/platform/vendor/thundercom/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
SYSTEM:Tlog:Separate auto and maunal logTC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: Id4c4bd47a9a3d8cdd57df1076db22403043e142d			

#36 - 2023-05-15 10:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
195999	general/boot_images	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xu.xia@thundersoft.com
SYSTEM :log: save UEFI logEnableLogFsSyncInRetail = 0x0 ---> EnableLogFsSyncInRetail = 0x1TC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I123a446f974f0fdc2df5803eff6e56500317aca5			

#37 - 2023-05-22 17:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
201706	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	xu.xia@thundersoft.com
SYSTEM :Tlog: Modify the number of tlog compressed packetsModify the tlog compression packet limit to 500TC-RID: 1200-0800102IssueID: TS-R-DF-110696Change-Id: I4007280077f5bc3564d15ba2d877227ea38f2838			

#38 - 2023-05-22 17:55 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
201713	general/platform/vendor/thundercom m/apps/TCHttpServer	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	xu.xia@thundersoft.com
SYSTEM :Tlog: Modify the number of tlog compressed packetsModify the number of compressed packages in the 'tlog_package/bk/' path to 500TC-RID: 1200-0800102IssueID: TS-R-DF-110696Change-Id: Ie7db6b5da09d98dc8d873f16e4c0593869aa402c			

#39 - 2023-05-27 11:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
202635	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	xu.xia@thundersoft.com
SYSTEM :Tlog: add bluetooth to manual packageOpen Bluetooth logs when using tlog to capture Bluetooth logsTC-RID: 1200-0800102IssueID: TS-R-DF-110696Change-Id: I0812181ba9bb9aca93ed781e4badd644edfac7f0			

#40 - 2023-05-27 19:04 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
203070	general/platform/vendor/thundercom m/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	xu.xia@thundersoft.com
SYSTEM :Tlog: modify tlog max file countmodify tlog max file count from 1000 to 5000TC-RID: 1200-0800102IssueID: TS-R-DF-110696Change-Id: I19c803efeae1ab3b3962b7c6908d547f148bf23f			

#41 - 2023-06-09 23:21 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
206118	general/platform/vendor/thundercomm/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
SYSTEM : Tlog: Change package time from 5s to 30s.Change package time from 5s to 30s.TC-RID: 1200-0800102IssueID: TS-R-DF-110696Change-Id: Ib2daaf668518b3ae9542c03ac330ba141fc2cb2e			

#42 - 2023-06-25 22:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209489	general/platform/vendor/thundercomm/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xu.xia@thundersoft.com
SYSTEM: TLOG: save dropbox to tlogcreate a directory, package and delete filesTC-RID: 1200-0800102IssueID: TS-R-DF-110696Change-Id: Ic420aff66345887b80864dff8b9f3bc7ca05a306			

#43 - 2023-06-25 22:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209481	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xu.xia@thundersoft.com
SYSTEM: TLOG: save dropbox to tlogmodify /data/system/dropbox to /data/tlog/fatal/dropboxChange-Id: I9ce9036e13467b176f1925ea2bc4b5bcb42bd01cTC-RID: 1200-0800102IssueID: TS-R-DF-110696			

#44 - 2023-06-25 22:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209036	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xu.xia@thundersoft.com
SYSTEM: TLOG: save dropbox to tlogadd selinux system_server for tlog_data_fileTC-RID: 1200-0800102IssueID: TS-R-DF-110696Change-Id: I4a18db0ac7b7c25b4cd061eb2be17cfd953a248a			

#45 - 2023-06-26 21:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

209955	general/platform/vendor/thundercomm/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
SYSTEM: TLOG: save dropbox to tlogcreate a directory, package and delete filesTC-RID: 1200-0800102IssueID: TS-R-DF-110696Change-Id: Ic420aff66345887b80864dff8b9f3bc7ca05a306(cherry picked from commit 6c322acf4f6276fbc1791404e06c826b88d788bd)			

#46 - 2023-06-26 21:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209956	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
SYSTEM: TLOG: save dropbox to tlogmodify /data/system/dropbox to /data/tlog/fatal/dropboxTC-RID: 1200-0800102IssueID: TS-R-DF-110696Change-Id: I9ce9036e13467b176f1925ea2bc4b5bcb42bd01c(cherry picked from commit 2424d0ba8fb37048daf903f9a5d964d9cd131bd3)			

#47 - 2023-06-26 21:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209958	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
SYSTEM: TLOG: save dropbox to tlogadd selinux system_server for tlog_data_fileTC-RID: 1200-0800102IssueID: TS-R-DF-110696Change-Id: I4a18db0ac7b7c25b4cd061eb2be17cfd953a248a(cherry picked from commit ec9c2cf12c6867ae6b24bb6a18c1b94da3d07109)			

#48 - 2023-06-27 19:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210583	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
SYSTEM:LOG: close dumpTurn off the dump function to generate a pstore fileTC-RID: 1201-0201101IssueID: TS-R-DF-110696Change-Id: I7f81dd48b5da5ea361c8bf10072c978ca468fb30			

#49 - 2023-07-19 18:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216163	general/platform/vendor/thundercom/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xu.xia@thundersoft.com

SYSTEM :Tlog: Solving the apk problem of tlogmodify LogClientFragment.java to adjust APK logicTC-RID: 1200-0800102IssueID: TS-R-DF-110696,IOVDEV-36887,IOVDEV-35584Change-Id: I88b403a780303edcf7294170ff818300c50f94c1

#50 - 2023-07-20 23:29 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216509	general/platform/vendor/thundercom/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

SYSTEM :Tlog: Solving the apk problem of tlogmodify LogClientFragment.java to adjust APK logicTC-RID: 1200-0800102IssueID:

TS-R-DF-110696,IOVDEV-36887,IOVDEV-35584Change-Id: I88b403a78030edcf7294170ff818300c50f94c1(cherry picked from commit aefa678cf35469ea3280801ab81a88e6d1f0f3a8)

#51 - 2023-07-27 12:22 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
217659	general/platform/vendor/thundercom/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xu.xia@thundersoft.com

SYSTEM :Tlog: Solving the apk problem of tlog(2)modify LogClientFragment.java to adjust APK logicTC-RID: 1200-0800102IssueID: TS-R-DF-110696,IQVDEV-38469Change-Id: I9759d569e32b8dbbed64bd54b0e2c097f5256869

#52 - 2023-07-27 23:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218244	general/platform/vendor/thundercom/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

SYSTEM :Tlog: Solving the apk problem of tlog(2)modify LogClientFragment.java to adjust APK logicTC-RID: 1200-0800102IssueID: TS-R-DF-110696,IOVDEV-38469Change-Id: I9759d569e32b8dbbed64bd54b0e2c097f5256869(cherry picked from commit 59c7067b13abcb5a7eb4ecbb3495addec063c7bc)

