

Figure - 开发 Dev #110710

开发 Dev # 110122 (New): 【MK】管理总票
开发 Dev # 110126 (New): 【MK】【AF】管理总票
【MK】【FW】【SystemOptimization】【TC-RID: 1201-0205101】
2022-07-25 17:08 - CD FW-王伟

Status:	完成 Closed	Start date:	2022-07-25
Priority:	Normal	Due date:	
Assignee:	CD FW-王伟	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_20220930		
Description			
■ 需求列表: 系统裁减，系统开机时间保证 需要保证开机时间在15秒内。 ■ 提出URL：必填 ■ 自测case：必填 ■ 注意点：需要测试注意的前提条件			

History

#1 - 2022-08-04 19:44 - CD FW-王伟
- Subject changed from 【MK】【051】【SystemOptimization】【TC-RID: 0301-0205101】 to 【MK】【051】【SystemOptimization】【TC-RID: 1201-0205101】

#2 - 2022-09-08 08:28 - CD FW-王伟
- Subject changed from 【MK】【051】【SystemOptimization】【TC-RID: 1201-0205101】 to 【MK】【FW】【SystemOptimization】【TC-RID: 1201-0205101】

#3 - 2022-09-26 20:03 - CD FW-王伟
- Status changed from New to 完成 Closed
- Target version set to VX1_MCE_FSE_V2.0_20220930

FW侧的优化，已经完成。

#4 - 2022-09-26 20:08 - CD FW-王伟
- % Done changed from 0 to 100

#5 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141090	general/platform/vendor/thundercom/apps/app_rm	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Remove unused appRemove unused appTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I1d8e833872bdddc6bbe11c35ffe25ab52f62340d			

#6 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141091	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Remove unused appRemove unused appTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I717e7dab31596001f0612fa17a0ce0950d3d5567			

#7 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141836	general/platform/vendor/thundercomm/apps/app_rm	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Remove unused appRemove unused appTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: Ib36f7d24749e77e97057e15791994d84c9c0e046			

#8 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141837	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Remove unused appRemove unused appTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I8ddae5a0fb21fb575840915bb1c93a5dc8701dd			

#9 - 2022-12-22 20:24 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143144	general/platform/vendor/thundercomm/apps/app_rm	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com

AF:SystemOptimization:crop AF app1. crop QColor DisplayCutoutEmulationCornerOverlay DisplayCutoutEmulationDoubleOverlay colorservice PresenceApp Protips SimAppDialog DisplayCutoutEmulationHoleOverlay DisplayCutoutEmulationTailOverlay Provision StatementService CarrierDefaultApp Browser2 BlockedNumberProvider ConferenceDialerTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: Id1b5db33bf063c179b36d14116db8a128569c6a4

#10 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143619	general/platform/vendor/thundercomm/apps/app_rm	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Un-Remove ProvisionProvision can't been remove,will cause quicksettings issueTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I15f47e04e3d43dfc1a64ef0055360e91a79f2819			

#11 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143633	general/platform/vendor/thundercomm/apps/app_rm	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
FW:SystemOptimization: remove app1.remove can be use app_rm app,without AF appTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: Id2a9f067f173476d551fe663fa92368523ac2ba3			

#12 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143656	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Delete Tel featureDelete Tel featureTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: Ieaccf77cf5b0a51da381025700a0c7d690089da6			

#13 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143657	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Delete Tel featureDelete Tel featureTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: Ie4b75159cf9762345f55b9e77d74f3c581dc6ee7			

#14 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143658	general/device/qcom/common	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Delete camera feature and sip featureDelete camera feature and sip featureTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I672ced614acfab675e10e63c3b106822ecd21af7			

#15 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143662	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Delete Tel featureDelete Tel featureTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I353f03be45ac1db99e2fb45c8fdf7cf2158e1403			

#16 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143682	general/platform/packages/apps/Settings	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Delete Tel featureDelete Tel featureTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I6f388c179d1000ec0586c5cf7b2ef7825ca4dd71			

#17 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143684	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Fix crash after delete tel featureFix crash after delete tel featureTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I34b0a3444d82cd65e3a734944d6f53d115140911			

#18 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143706	general/platform/frameworks/native	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Delete camera featureDelete camera featureTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I6a0be78de2049e0902386401c84d5d4047018170			

#19 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143707	general/device/qcom/vendor-commo n	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Delete camera feature and sipDelete camera feature and sipTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I0f35a8ffe8b845c948afeaa0af8bed103a1ac65			

#20 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143912	general/platform/vendor/nxp/opensou rce/halimpl	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Delete NFC featureDelete NFCTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: Idfa13aa4a894cabacf1ad12cebaa41d660011572			

#21 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
143976	general/LA.QSSI/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: remove app1.remove can be use app_rm app.without AF appTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I1bd8209120b19a8c7874c2e8e2258f0beb784ad2			

#22 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143977	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: remove fingerprint1.remove fingerprintTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I441f0f0320217deaae936599d51a67e978c6ab00			

#23 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
144117	general/platform/vendor/thundercomm/apps/app_rm	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: remove unused app1.remove unused appTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: Ic9005a6c84ac0ec50ee0d8b737a2c4cc92848d1f			

#24 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
144126	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: remove QCC-TR-UI1.remove QCC-TR-UITC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: If3fdb9703bf0e6bf6dbcaef92e54cd9b4b4d36e			

#25 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader

144129	general/platform/vendor/thundercom/apps/app_rm	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: Remove SSMEditor1.Remove SSMEditorTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I611f5d86c2df8fa1d253ab738ef4f90d0d0cc7b6			

#26 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
144130	general/platform/build	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: remove camera1.remove cameraTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I954b8b1cded595b1efa7d2af9a49bbac4930bebb			

#27 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
144131	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: remove camera1.remove cameraTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: Ida97f649476ddbaca1563939df52b5c147e99fd			

#28 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
144350	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangwei0629@thundersoft.com
FW:SystemOptimization: remove camera1.remove cameraTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I64c3d91e4482c0f4feb601e275a7e0345c8bf76e			

#29 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
144356	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangwei0629@thundersoft.com

	m/proprietary	r-dev	
FW:SystemOptimization: Drop light/step sensor features1.Drop light/step sensor featuresTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I47a4816519ee37e54ec153b4c3fdc9228258955f			

#30 - 2023-05-31 15:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
203770	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
FW:SystemOptimization: Remove full screen promptTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: Ic79cdc520eb27063d0ca9646831f80e5e4122f87			

#31 - 2023-06-12 21:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
205994	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	lukf0916@thundersoft.com
FW:SystemOptimization: set bg apps limit to 32TC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I6fd6666b7d53baf38cee547b827c79319d4f3a4d			

#32 - 2023-06-12 21:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
205805	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
FW:SystemOptimization: Keep only 3 tasksTC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I0b521026bc2136c815aba8f5f0d135984176d20e			

#33 - 2023-06-28 20:04 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210875	general/platform/frameworks/native	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
FW:SystemOptimization: Add width validation to avoid crashing and restart caused by excessive width.The solution was provided by Qualcomm.TC-RID:			

#34 - 2023-06-30 16:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210856	general/platform/frameworks/native	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: Add width validation to avoid crashing and restart caused by excessive width.The solution was provided by Qualcomm.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-35295Change-Id: Ie7c27588876249cd83373610e14aa748fc09cbbe(cherry picked from commit 402d5062fe4758ddbccc876ffdf311f8b49776ee)			

#35 - 2023-07-05 19:20 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212501	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
FW:SystemOptimization: Adding logging to print storage space information.TC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: Iff1b2c0dd91873d2f3e861ffc7039b6606c2ce3a			

#36 - 2023-07-06 19:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212794	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: Adding logging to print storage space information.TC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: Iff1b2c0dd91873d2f3e861ffc7039b6606c2ce3a(cherry picked from commit 9a7c6ab5a6f4261fe28181a8904f2dbe1758ac73)			

#37 - 2023-07-06 21:20 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212691	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lei.zheng@thundersoft.com
FW:SystemOptimization: Add timeout check for add splash screen.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-35312Change-Id: I799dcd92c5fb0d4ef0cd9dd47858a204a9fcf0a0			

#38 - 2023-07-06 21:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212963	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: Add timeout check for add splash screen.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-35312Change-Id: I799dcd92c5fb0d4ef0cd9dd47858a204a9fcf0a0(cherry picked from commit 6da14a5ce316ef23621403fa02427ef5fc1030ef)			

#39 - 2023-07-11 15:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212769	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
FW:SystemOptimization: Fixing crash exceptions encountered during Monkey testing.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-36554, IOVDEV-36556Change-Id: I5f4ff46a83404a32300aa8908e73cda1b998333d			

#40 - 2023-07-13 20:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
214562	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wujun.wang@thundersoft.com
AF: ScreenSaver: add log to analyze issueAdd logic to analyze dream。 TC-RID: 1201-0300601IssueID: TS-R-DF-110710, IOVISSUE-11573Change-Id: If1e64929a352f27601495f69dfbb592317868cc2			

#41 - 2023-07-13 21:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
214741	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: Fixing crash exceptions encountered during Monkey testing.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-36554, IOVDEV-36556Change-Id: I5f4ff46a83404a32300aa8908e73cda1b998333d(cherry picked from commit 350663df2f59837c6fccce061b314ac259702a42)			

#42 - 2023-07-13 21:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
214753	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF: ScreenSaver: add log to analyze issueAdd logic to analyze dream。 TC-RID: 1201-0300601IssueID: TS-R-DF-110710, IOVISSUE-11573Change-Id: If1e64929a352f27601495f69dfbb592317868cc2(cherry picked from commit 51f2e48065cc27a34a734f1c30060c78db400503)			

#43 - 2023-07-17 16:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
215349	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
AF: MultiWindow: add log to analyze issueAdd logic to analyze motionevent。 TC-RID: 1201-0300601IssueID: TS-R-DF-110710, IOVISSUE-12797Change-Id: I218631c52ef75cdcecf8700157fbc1fca18f976			

#44 - 2023-07-19 14:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
215975	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
FW:SystemOptimization: Disable type Rhea logs.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVISSUE-12986Change-Id: I5d9b96c6e489710d96c1b65806f6b0bed4e6860c			

#45 - 2023-07-19 16:19 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
215792	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF: MicroSettings:Hardening powermanager logsTC-RID: 1201-0206101IssueID: TS-R-DF-110710, IOVDEV-37293Change-Id: I639e4286b2c0adef0e4565586cd9958c9a374bea			

#46 - 2023-07-19 23:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

216242	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF: MultiWindow: add log to analyze issueAdd logic to analyze motionevent. TC-RID: 1201-0300601IssueID: TS-R-DF-110710, IOVISSUE-12797Change-Id: I218631c52ef75cdcecf8700157fbc1fca18f976(cherry picked from commit 37a432ccd52525e3288d2a17dbc83d5867ffc968)			

#47 - 2023-07-20 23:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216504	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: Disable type Rhea logs.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVISSUE-12986Change-Id: I5d9b96c6e489710d96c1b65806f6b0bed4e6860c(cherry picked from commit 12a89d469b18eaf0684b71d3c41aa01c96b9e808)			

#48 - 2023-07-20 23:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216507	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF: MicroSettings:Hardening powermanager logsTC-RID: 1201-0206101IssueID: TS-R-DF-110710, IOVDEV-37293Change-Id: I639e4286b2c0adef0e4565586cd9958c9a374bea(cherry picked from commit 7b45c1feb45dcd1ed5d251f9b58ff2f14bf7ff6a)			

#49 - 2023-07-25 09:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
217267	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wujun.wang@thundersoft.com
FW:SystemOptimization: add log to analyze issueAdd logic to back gesture and back task.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-36491,IOVDEV-37409Change-Id: I6f5bfeb37baca7ad890f767fec64e8e8aa4684a9			

#50 - 2023-07-25 09:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

217271	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wujun.wang@thundersoft.com
FW:SystemOptimization: add log to analyze issueAdd logic in onKeyDown to check the back task.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-36491Change-Id: If3cbf0dae683391d2812f32129370a78f77cc50a			

#51 - 2023-07-27 19:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216121	general/platform/frameworks/native	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wujun.wang@thundersoft.com
AF:MultiWindow: add intercept for douyinAdd logic to avoid check the douyin's windpause state.TC-RID: 1201-0300601IssueID: TS-R-DF-110710, IOVISSUE-12797Change-Id: I0572da17fdd3d599c7826dfd37bb375cc51cb10a			

#52 - 2023-07-27 23:41 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218206	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: add log to analyze issueAdd logic in onKeyDown to check the back task.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-36491Change-Id: If3cbf0dae683391d2812f32129370a78f77cc50a(cherry picked from commit 9a9beaed3efa9fdf9ece4af69088c282bf8b9827)			

#53 - 2023-07-27 23:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218205	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: add log to analyze issueAdd logic to back gesture and back task.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-36491,IOVDEV-37409Change-Id: I6f5bfeb37baca7ad890f767fec64e8e8aa4684a9(cherry picked from commit 0e3208b47f8ddcb606993c22d23bf830207d22c9)			

Gerrit Merge Information :

ID	Project	Branch	Uploader
216350	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
FW:SystemOptimization: cancel back gesture checkAdd logic to cancel the systemui flag check forback gesture.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-36162 IOVDEV-35744Change-Id: Iade13e6fdd898876352c215e3fb7621b525b2d78			

Gerrit Merge Information :

ID	Project	Branch	Uploader
219400	general/platform/frameworks/native	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:MultiWindow: add intercept for douyinAdd logic to avoid check the douyin's windpause state.TC-RID: 1201-0300601IssueID: TS-R-DF-110710, IOVISSUE-12797Change-Id: I0572da17fdd3d599c7826dfd37bb375cc51cb10a(cherry picked from commit 6303d755324016ed0d06d371e24cf0a18c78fa46)			

Gerrit Merge Information :

ID	Project	Branch	Uploader
219232	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
FW:SystemOptimization: add inactive time checkTC-RID: 1201-0205101IssueID: TS-R-DF-110710,IOVDEV-37783Change-Id: If2fb089d5e9c35df9030df4a1d9edf02c53f2ea8			

Gerrit Merge Information :

ID	Project	Branch	Uploader
213391	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
FW:SystemOptimization: ime no showAdd logs to analyze issue.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-37272Change-Id: Ib33db232e9c4ad296ac009fb15c528ce4851b60d			

#58 - 2023-08-04 10:08 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
300121	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: cancel back gesture checkAdd logic to cancel the systemui flag check forback gesture.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-36162 IOVDEV-35744Change-Id: Iade13e6fdd898876352c215e3fb7621b525b2d78(cherry picked from commit c47b096fdbbeac91661f434284b51056b33565215)			

#59 - 2023-08-04 16:29 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
300255	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:SystemOptimization:Close NotificationManagerService DEBUG when build as userTC-RID: 1201-0205101IssueID: TS-R-DF-110710,IOVDEV-37652Change-Id: I1bde7752cdb82202a47a3acfc272e9af1376686			

#60 - 2023-08-04 17:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
300365	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wujun.wang@thundersoft.com
FW:SystemOptimization: ime switcher no showAdd logs to analyze issue.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-33340Change-Id: I83bf6b15a6b9eb54bfbd92bc5ecff78e9149d34			

#61 - 2023-08-08 19:19 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
301388	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wujun.wang@thundersoft.com
FW:SystemOptimization: ime no show(2)Add logs to analyze issue.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-37272 IOVDEV-38384Change-Id: I0c511e0c78c1faf7391b337cb99826e09f1b10c4			

#62 - 2023-08-10 14:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302130	general/platform/development	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
FW:SystemOptimization: add packages black list for monkey.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-39378Change-Id: I9861856cdc0107ca3745d314c6313ad0ce09518e			

#63 - 2023-08-10 20:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302372	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: add inactive time checkTC-RID: 1201-0205101IssueID: TS-R-DF-110710,IOVDEV-37783Change-Id: If2fb089d5e9c35df9030df4a1d9edf02c53f2ea8(cherry picked from commit 081334c81941e5adf302632bbbb072fccb11fba0)			

#64 - 2023-08-10 20:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302381	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:SystemOptimization:Close NotificationManagerService DEBUG when build as userTC-RID: 1201-0205101IssueID: TS-R-DF-110710,IOVDEV-37652Change-Id: I1bde7752cdb82202a47a3acfc272e9af1376686(cherry picked from commit bc41bebc8a9d81d13f7bdc1b3fa458f7e3657211)			

#65 - 2023-08-10 20:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302383	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: ime switcher no showAdd logs to analyze issue.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-33340Change-Id: I83bf6b15a6b9eb54bfbd92bc5ecff78e9149d34(cherry picked from commit 762ae822ab503ae9b67c7c1514935ded89c1cbd0)			

#66 - 2023-08-10 20:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302426	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: ime no show(2)Add logs to analyze issue.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-37272 IOVDEV-38384Change-Id: I0c511e0c78c1faf7391b337cb99826e09f1b10c4(cherry picked from commit 9d104ceefcb0801e13378b39d56fefb654c42da9)			

#67 - 2023-08-14 18:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302923	general/platform/development	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: add packages black list for monkey.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-39378Change-Id: I9861856cdc0107ca3745d314c6313ad0ce09518e(cherry picked from commit 3e26ed8878a7fa930aba1efafb0fbe04f1646c68)			

#68 - 2023-08-17 15:35 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
304072	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
FW:SystemOptimization: ime no show logAdd logs to analyze issue.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-38384Change-Id: Iab1d68c2b2b90799bc8e28deab93d06095e8a17e			

#69 - 2023-08-17 19:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
304163	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: ime no show logAdd logs to analyze issue.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-38384Change-Id: Iab1d68c2b2b90799bc8e28deab93d06095e8a17e(cherry picked from commit 8645738099a1a181f21c70376ea7e76bac92f671)			

#70 - 2023-08-29 09:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
307205	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
FW:Stability: Add log to monitor free space and notificationTC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-38824Change-Id: I33c1a69cb9f68241966614cfdcbacf275fb22938			

#71 - 2023-08-31 18:22 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
308693	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
FW:SystemOptimization: Do not retain pre-installed game applications.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-40408Change-Id: I2d54bf88027daecb74dd8499ac68665a01825082			

#72 - 2023-08-31 23:55 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
308772	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:Stability: Add log to monitor free space and notificationTC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-38824Change-Id: I33c1a69cb9f68241966614cfdcbacf275fb22938(cherry picked from commit c323e50a38cc0349320e19b3d1a561468d043666)			

#73 - 2023-08-31 23:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
308779	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: Do not retain pre-installed game applications.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-40408Change-Id: I2d54bf88027daecb74dd8499ac68665a01825082(cherry picked from commit 32e4efe8c8a7eb023cfd9fa88d87c143f79c9d5e)			

#74 - 2023-09-06 10:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

309971	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
FW:SystemOptimization: Adding time setting logsAdd logs to analyze issue.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-40783Change-Id: Ib11decb4689312bce040cb164908c7e992c042a8			

#75 - 2023-09-12 16:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
312009	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
FW:SystemOptimization: Task mechanism preserves the music application.TC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I36eac8cefd0b144d82df2b76209e23e2a21996d2			

#76 - 2023-09-13 18:31 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
312468	general/platform/packages/apps/DocumentsUI	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:DocumentsUI:Remove long-press tooltip event from the toolbar.TC-RID: 1201-0300801IssueID: TS-R-DF-110710Change-Id: I7560220573cb0ed7a947b56a9520f29b2b16265e			

#77 - 2023-09-15 13:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
313022	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Music: add qqmusiccar to music app listTC-RID: 1201-0301201IssueID: TS-R-DF-110710, IOVDEV-42438Change-Id: I6e0a37ed2962cdc2fecfa30ea22d61c1643e6f38			

#78 - 2023-09-19 15:48 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
313787	general/platform/packages/apps/DocumentsUI	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com

AF:DocumentsUI:bug analysis log appendthis log use for bug analysisTC-RID: 1201-0300801IssueID: TS-R-DF-110710,IOVDEV-40758Change-Id: I8be4a62edc00cd30b52dfe25d219928b621e5f4f

#79 - 2023-09-19 20:08 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
313920	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Music: add kugou auto to music app listTC-RID: 1201-0301201IssueID: TS-R-DF-110710, IOVDEV-42282Change-Id: I95397d69125662044908f1dcd725c83449174f54			

#80 - 2023-09-21 18:04 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314956	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Theme: modify splash window background color and overview background colorTC-RID: 1201-0202101IssueID: TS-R-DF-110710Change-Id: I640f717650e793b7c8a3ca4ef2704dccbbcf6778			

#81 - 2023-09-24 12:55 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
315586	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Theme: modify splash window background color and overview background colorTC-RID: 1201-0202101IssueID: TS-R-DF-110710Change-Id: I640f717650e793b7c8a3ca4ef2704dccbbcf6778(cherry picked from commit f93964ca9c8a4989ba1704669f14d3fa88750d1e)			

#82 - 2023-09-25 19:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
315850	general/platform/packages/providers/MediaProvider	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:Document:the file with invalidate address will not show documentui appthe file with invalidate address will not show documentui appTC-RID: 1201-0300801IssueID: TS-R-DF-110710,FIR-599Change-Id: I7ddcecc2c290da8a485930acb6d544d3ea0abb47			

#83 - 2023-09-26 10:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
316001	general/platform/packages/providers/ MediaProvider	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:Document:the file with invalidate address will not show documentui appthe file with invalidate address will not show documentui appTC-RID: 1201-0300801IssueID: TS-R-DF-110710,FIR-599Change-Id: I972559f95db46d283cf10df0a5add905fdb41188			

#84 - 2023-09-26 15:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
316206	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:Music: add wangyiyun iot to music app listTC-RID: 1201-0301201IssueID: TS-R-DF-110710, PVC1-3677Change-Id: I1b65acfc6335ff5b1708f94349e3acee8d905aef			

#85 - 2023-10-07 11:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317143	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: Adding time setting logsAdd logs to analyze issue.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-40783Change-Id: Ib11decb4689312bce040cb164908c7e992c042a8(cherry picked from commit ff0e7f83fe25113f45b12f48077e75a817266bd6)			

#86 - 2023-10-07 16:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317327	general/platform/packages/apps/Docu mentsUI	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:DocumentsUI:Remove long-press tooltip event from the toolbar.TC-RID: 1201-0300801IssueID: TS-R-DF-110710Change-Id: I7560220573cb0ed7a947b56a9520f29b2b16265e(cherry picked from commit bcc85c50b3644012fead50be0c7d2d77b19b8b51)			

#87 - 2023-10-07 16:55 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317330	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Music: add qqmusiccar to music app listTC-RID: 1201-0301201IssueID: TS-R-DF-110710, IOVDEV-42438Change-Id: I6e0a37ed2962cdc2fecfa30ea22d61c1643e6f38(cherry picked from commit 3dd243ae15a2daf542b2707ff7913dd5f883c4d2)			

#88 - 2023-10-07 16:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317332	general/platform/packages/apps/DocumentsUI	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:DocumentsUI:bug analysis log appendthis log use for bug analysisTC-RID: 1201-0300801IssueID: TS-R-DF-110710,IOVDEV-40758Change-Id: I8be4a62edc00cd30b52dfe25d219928b621e5f4f(cherry picked from commit 911a64676008528fa2b021520327ee44739b0907)			

#89 - 2023-10-07 16:59 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317334	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Music: add kugou auto to music app listTC-RID: 1201-0301201IssueID: TS-R-DF-110710, IOVDEV-42282Change-Id: I95397d69125662044908f1dcd725c83449174f54(cherry picked from commit 8ff27b44f037768611396e949852d60bfa2a8529)			

#90 - 2023-10-07 17:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317341	general/platform/packages/providers/MediaProvider	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Document:the file with invalidate address will not show documentui appthe file with invalidate address will not show documentui appTC-RID: 1201-0300801IssueID: TS-R-DF-110710,FIR-599Change-Id: I7ddcecc2c290da8a485930acb6d544d3ea0abb47(cherry picked from commit b51d7c49c3cb056cf8dea05017e8a36ebde70f8d)			

#91 - 2023-10-07 17:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317342	general/platform/packages/providers/ MediaProvider	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Document:the file with invalidate address will not show documentui appthe file with invalidate address will not show documentui appTC-RID: 1201-0300801IssueID: TS-R-DF-110710,FIR-599Change-Id: I972559f95db46d283cf10df0a5add905fdb41188(cherry picked from commit 424d5ebd432b78db881b3ef38f025a23538bbe0b)			

#92 - 2023-10-07 17:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317344	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Music: add wangyiyun iot to music app listTC-RID: 1201-0301201IssueID: TS-R-DF-110710, PVC1-3677Change-Id: I1b65acfc6335ff5b1708f94349e3acee8d905aef(cherry picked from commit bc9816b534761b0f51c6a39591c428d85c157699)			

#93 - 2023-10-09 18:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317867	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:Theme: Adapt the style of the picture-in-picture exit button.TC-RID: 1201-0202101IssueID: TS-R-DF-110710, IOVDEV-45433Change-Id: I737a0b01744806584d56a2951a4490df38ddc360			

#94 - 2023-10-16 14:35 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
319616	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:Theme: modify splash window background color and overview background color for MCETC-RID: 1201-0202101IssueID: TS-R-DF-110710Change-Id: Ia229578dcb8e1f8f9084f878e986354cf312abc1			

#95 - 2023-10-16 15:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
319116	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Theme: Adapt the style of the picture-in-picture exit button.TC-RID: 1201-0202101IssueID: TS-R-DF-110710, IOVDEV-45433Change-Id: I737a0b01744806584d56a2951a4490df38ddc360(cherry picked from commit 9e6b10afebaf6933f949c0250d548dc3ba119844)			

#96 - 2023-10-17 18:06 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
320132	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
FW:SystemOptimization: Manually close unresponsive dialog.TC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I6fe0871d5bb5fcbb6b7f1fe0ae09023637a4ea37			

#97 - 2023-10-26 22:04 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323031	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: Task mechanism preserves the music application.TC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I36eac8cefd0b144d82df2b76209e23e2a21996d2(cherry picked from commit 5aca30d09adf1673cb5c61fdd1e9e08ce2037499)			

#98 - 2023-10-27 01:39 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323293	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Theme: modify splash window background color and overview background color for MCETC-RID: 1201-0202101IssueID: TS-R-DF-110710Change-Id: Ia229578dcb8e1f8f9084f878e986354cf312abc1(cherry picked from commit eddf933aa8c5ec88dc29b924746ba8eb987796f9)			

#99 - 2023-10-27 01:44 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
323300	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: Manually close unresponsive dialog.TC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I6fe0871d5bb5fcb6b7f1fe0ae09023637a4ea37(cherry picked from commit 0cc4879ee4f699e6596ec5d0ffc92e40a030e20a)			

#100 - 2023-11-02 16:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
325087	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
FW:SystemOptimization: The car-mounted device does not have a battery and is assumed to be fully charged by default.TC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I850573be7842b56b68e71fe7a143e007788f48f3			

#101 - 2023-11-03 17:41 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
325517	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: The car-mounted device does not have a battery and is assumed to be fully charged by default.TC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I850573be7842b56b68e71fe7a143e007788f48f3(cherry picked from commit a6b906f259214b0ec142208006521b44e5d42628)			

#102 - 2023-12-11 16:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
335034	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
FW:SystemOptimization: Optimize non system task remove logical.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-50629Change-Id: Ib222abf9f1a6c717369a51a7d790705e27e6fe13			

#103 - 2023-12-11 17:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
335001	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

FW:SystemOptimization: Optimize non system task remove logical.TC-RID: 1201-0205101IssueID: TS-R-DF-110710, IOVDEV-50629Change-Id: Ib222abf9f1a6c717369a51a7d790705e27e6fe13(cherry picked from commit 2deaf80f21b827e18ce6ed21b43ce828c9c5163d)

#104 - 2023-12-14 11:31 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
336125	general/platform/development	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
FW:SystemOptimization: Add special packages to monkey black list.TC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I5b174b8a1484e9b69df436315e083c204a99e36c			

#105 - 2023-12-15 14:23 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
336607	general/platform/development	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:SystemOptimization: Add special packages to monkey black list.TC-RID: 1201-0205101IssueID: TS-R-DF-110710Change-Id: I5b174b8a1484e9b69df436315e083c204a99e36c(cherry picked from commit 9fb57151957db1d24c9c1f26bd64236be9470abc)			