

Figure - 开发 Dev #110715

开发 Dev # 110122 (New): 【MK】管理总票
开发 Dev # 110126 (New): 【MK】【AF】管理总票
【MK】【FW】【VehicleDataControl】【TC-RID: 1201-0206101】
2022-07-25 17:11 - CD FW-王伟

Status:	完成 Closed	Start date:	2022-09-29
Priority:	Normal	Due date:	2022-12-23
Assignee:	CD FW-程天颖	% Done:	94%
Category:		Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030		
Description			
■ 需求列表: 中控与副屏之间的连携控制： 主副屏联动接口feedback -> https://thundersoft.feishu.cn/sheets/shtcnPwA7kTXSx1MDZunmEb5sle MCE-主副屏需求接口定义&联调计划_20220608.xlsx -> https://thundersoft.feishu.cn/file/boxcn2bXInLfPv1XW446a3XqKDe ■ 提出URL：必填 ■ 自测case：必填 ■ 注意点：需要测试注意的前提条件 通过接口，实现，中控与副屏的联动 4.1 功能描述及定义 4.1.1 通信方式 1. 采用socket方式连接，以短连接为主 2. 中控与副屏之间通信采用绑定地址与端口的方式(ip:port)，中控的地址为VLAN_04网段，端口号为9999 3. 中控与副屏，在启动完成之后，各自启动一个socket服务端监听对手件的消息 4. 中控与副屏之间通信需要有握手机制，以确定对端合法性，握手消息不加密 5. 中控与副屏的控制通信数据，需要加密，具体加密方式，待中控同步 4.1.2 首次激活 激活操作在中控侧进行，中控会下发激活指令给到副屏，具体功能需求如下： 1. 未激活状态：副屏不可使用，且播放由华人运通侧提供的动画资源，进行播放，动画格式为:MP4 2. 接收到激活信号后，副屏为激活状态，接收信号后，启动【开机引导】，开机引导文件由副屏设计，主要包含的内容如下： 1. 手势引导动画 2. 小窗操作动画，包含多任务界面的介绍 3. 屏保操作动画 4. 动画格式为MP4 张跃洧 3. 首次激活动画，在首次激活后，进行展示，展示结束后，进入launcher界面，后面再次启动副屏，无需激活动画展示 4. 激活动画展示完毕后，同步保存在设置中，可保存的位置路径为：设置-系统-手势说明（对原有手势部分进行改造）张跃洧 4.1.3 系统语言切换 1. 路径如下：中控通过以太网下发语言切换指令--->副屏接收指令--->副屏切换语言--->反馈结果 2. 语言范围：中文/英文 3. 副屏不支持自己本地单独切换语言 4.1.4 多屏联动			

- 1. 服务范围：包括car show，沉浸模式，洗车模式
- 2. 实现方式：以APK的形式内置，在底层运行，并且调用时注册相关服务
- 4.1.5 hiph play功能联动
 - 1. 中控侧通过语音输入，获取用户是否要熄屏和唤醒屏幕的行为
 - 2. 中控获取语音后，解析语音内容，然后通过以太网指令传送到副屏，副屏侧完成熄屏，和亮屏的操作

- 4.1.6 恢复出厂设置
 - 1. 中控下发恢复出厂设置的指令，副屏接收后，只对数据进行删除
 - 2. 清除范围：【删除data分区】
 - 3. 副屏本身的恢复出厂设置功能保留

- 4.1.7 开机动画（For AF）
 - 1. 在第一阶段开机logo展示完毕后，进入第二阶段：开机动画，开机动画视频由客户侧提供
 - 2. 开机动画的视频格式为MP4，时长约为30s
 - 3. 在开机动画启动的同时，launcher需要完成启动，及launcher的启动需要在15s内完成
 - 4. 开机动画完成后：
 - 1. 待激活状态：launcher不可用，展示客户提供的待激活画面的动画，具体参考4.1.2
 - 2. 已激活状态：进入launcher界面的首页，用户可正常使用

4.2 其他接口相关功能提示

音量调节，背光调节，深色模式，屏保同步，网络信号同步具体需求，请参考《launcher UI需求PRD》4.1.8章节

具体接口内容参考：副本MCE-主副屏需求接口定义&联调计划_20220923

具体PRD链接如下：
<https://thundersoft.feishu.cn/docx/doxcnpJynqMqC5C5fLwWif6fewh>

Subtasks:			
开发 Dev # 112251: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			取消 Canceled
开发 Dev # 112252: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			完成 Closed
开发 Dev # 112253: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			取消 Canceled
开发 Dev # 112254: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			完成 Closed
开发 Dev # 112255: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			完成 Closed
开发 Dev # 112256: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			完成 Closed
开发 Dev # 112257: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			完成 Closed
开发 Dev # 112258: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			完成 Closed
开发 Dev # 112260: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			取消 Canceled
开发 Dev # 112261: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			取消 Canceled
开发 Dev # 112262: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			取消 Canceled
开发 Dev # 112264: 【MK】 【019】 【StatusBar】 【TC-RID: 0301-0201801】 副驾屏...			New
开发 Dev # 112265: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			取消 Canceled
开发 Dev # 112267: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			完成 Closed
开发 Dev # 112287: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			完成 Closed
开发 Dev # 112289: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			取消 Canceled
开发 Dev # 112528: 【MK】 【FW】 【InitialSetting】 【TC-RID: 1201-0200701...			取消 Canceled
开发 Dev # 115370: 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-020...			完成 Closed
Related issues:			
Related to Figure - 需求 Requirement # 112376: 【Locked需求】 中控...	完成 Closed	2022-10-08	2022-10-28

- Assignee changed from CD FW-王伟 to CD- FW-石豪

#2 - 2022-08-04 19:44 - CD FW-王伟

- Subject changed from 【MK】 【061】 【VehicleDataControl】 【TC-RID: 0301-0206101】 to 【MK】 【061】 【VehicleDataControl】 【TC-RID: 1201-0206101】

#3 - 2022-09-08 08:32 - CD FW-王伟

- Subject changed from 【MK】 【061】 【VehicleDataControl】 【TC-RID: 1201-0206101】 to 【MK】 【FW】 【VehicleDataControl】 【TC-RID: 1201-0206101】

#4 - 2022-09-26 18:43 - CD FW-王伟

- Target version set to VX1_MCE_FSE_V3.0_20221030

#5 - 2022-10-08 15:35 - CD FW-王伟

- Description updated

- Assignee changed from CD- FW-石豪 to CD FW-程天颖

#6 - 2022-12-13 11:11 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
169040	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:MicroService:Use Ethernet communicationTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I4c57afa47df423808823ce3d0ab2751ff1379d17			

#7 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141102	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	shihao0506@thundersoft.com
AF:MicroService: add original codeadd base codeTC-RID: 0301-0206101IssueID: TS-R-DF-110715Change-Id: I1f0048f7203fe7c28934960948a622ba6910ca55			

#8 - 2022-12-22 20:23 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142644	general/platform/build/soong	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	shihao0506@thundersoft.com
AF:MircoService:Allow adding micro APIAn api package that allows adding micro servicesTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: If5c8a53f3cc5d5753aed74d850ebecd4a11c1462			

#9 - 2022-12-22 20:23 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142646	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:MircoService:Add MicroServiceManager1. Register the micro service and configure it to start at boot2. Integrate the microservice_release packageTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ic2f25d6c55f56e07aea780364a947dfe48152402			

#10 - 2022-12-22 20:27 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145364	general/platform/vendor/thundercomm/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:VehicleDataControl:add settings base codeTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: If1302b25ba20748e2c78f426436a318cb6182782			

#11 - 2022-12-22 20:27 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145406	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
AF:MicroService: add original codeadd micro service selinux policyTC-RID: 0301-0206101IssueID: TS-R-DF-110715Change-Id: I57faa0f04979ebc13fcfbec0f8914b3cee25bb5d			

#12 - 2022-12-22 20:27 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145677	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
AF:MicroService:Replace NLog to SlogReplace NLog to SlogTC-RID: 0301-0206101IssueID: TS-R-DF-110715Change-Id: Ib601bfaa2912a1c731fb1815f38a4161478d5b70			

#13 - 2022-12-22 20:28 - CD FW-王伟

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
145679	general/platform/vendor/thundercom/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
AF:MicroService:Replace NLog to TLogReplace NLog to TLogTC-RID: 0301-0206101IssueID: TS-R-DF-110715Change-Id: I9ec2b1450396583aa55be4e2c04ce7a0cd598a50			

#14 - 2022-12-22 20:28 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145744	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:modify package name string1.modify package name string "tc" to "thundersoft" TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I4b35fd471a907bd92103be5610c0ea4c3495457d			

#15 - 2022-12-22 20:28 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145753	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:GetBrightnessMode1.GetBrightnessMode is okTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I82820605054afdb01da774d33b0a865d382eab5c			

#16 - 2022-12-22 20:28 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
146474	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:get brightness1.get brightness valueTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I19f18120c72277b1d60bcf17471d2eebeb3727fd			

#17 - 2022-12-22 20:28 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader

146931	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:fixed when shat down MicroSettings auto bringht is closed1.fixed when shat down MicroSettings auto bringht is closedTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I8688b19ed390da68217932a556e7fca9fd657a67			

#18 - 2022-12-22 20:29 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147027	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:set night mode1.set night modeTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ib1fa4a509070739684fdc71c71101ef6f4d3373a			

#19 - 2022-12-22 20:29 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147041	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangwei0629@thundersoft.com
AF:VehicleDataControl:Delete no used codeDelete no used codeTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I07f2dbdcb12a1c0f7009e6d24ae329541d051c9a			

#20 - 2022-12-22 20:30 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147981	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	shihao0506@thundersoft.com
AF:VehicleDataControl:Repair permissions file formatTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I776b3752bbb67993d5b8fbfa16e396991f072aa			

#21 - 2022-12-22 20:32 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
148601	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com

AF:MicroService: New MicroService use socket.TC-RID: 0301-0206101IssueID: TS-R-DF-110715Change-Id: Ib3c1f7a9997e3152e8e88a4a4abab40f639b0a96

#22 - 2022-12-22 20:33 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
149427	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:VehicleDataControl: Remove not use function and aidl file.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Id5503e3c984515d02f95ce73457fe47bc6b056a2			

#23 - 2022-12-22 20:33 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
149846	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:MicroService framework base: New MicroService use socket.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I58d4a86825dd902e872f0f3c95d1b9058391b392			

#24 - 2022-12-22 20:34 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150128	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:VehicleDataControl: Remove time sync func, update microservices.aar.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ic22db1a069c886027f8ce5a07ed591deb782a482			

#25 - 2022-12-22 20:34 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150131	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:MicroService framework base: Add const value, modify method name.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I55d52ef36289f4d3db6713f76e3c88292c0cd885			

#26 - 2022-12-22 20:34 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150132	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroService: Complete demo, add report operation support.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: If04c5413c63a6f5554ff005e4f6fc2c547962be3			

#27 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150374	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:VehicleDataControl: Modify application config.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ic0387787f58b224d95586938cdd2704626f1f805			

#28 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150385	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroService: Modify application config, Add compile project MicroSettings.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Iad78d1f870b8b29c2ec6deff65cdcce82da14801			

#29 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150473	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:VehicleDataControl: Add SoundManager, Add multimedia callback.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Iebd6dfe846309ecebc0957fef54f9b3422103ec1			

#30 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150474	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com

AF:MicroService: Add multimedia callback, add FSEM to IDCM request support.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I57ff34de49c1225b1891082ac74973135699376a

#31 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150604	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:MicroService framework base: Add multimedia callback, add FSEM to IDCM request support.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: If54cdace8c8966b5f79f7f96edda0b976e7918c6			

#32 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150733	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:MicroService: Start sub module services.1. Start sub module services;2. Remove app demo const value, and use const value of microservice project;3. Remove microservice launch icon from Launcher;TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ib6941f6e10257e8fd0e898b07bb003d1878d84d4			

#33 - 2022-12-22 20:36 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151098	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:MicroService: Add audio volume action method.1. Add audio volume action method;2. Add ITCMicroCommonCallback aidl;TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I198ddfa118d34fdd40a6acf0691022a2ab483059			

#34 - 2022-12-22 20:36 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151100	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com

AF:MicroService framework base: Add audio volume action method.1. Add audio volume action method;2. Add ITCMicroCommonCallback aidl;TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: l4a50e2272f21e1e52b52773a50677a45b81c18a6

#35 - 2022-12-22 20:36 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151190	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:Add Audio about interface method.1.Add Audio about interface method.2.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I998288eab93441d653748e8e62e3a51ac4906783			

#36 - 2022-12-22 20:36 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151301	general/platform/vendor/thundercom m/apps/MicroService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroService: Opt MicroServiceManager bind logical.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ia5618f6feed47eab91a0339cd9a2cae18ecb167a			

#37 - 2022-12-22 20:36 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151555	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroService framework base: Opt MicroServiceManager bind logical.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ifbe14d407fc7abfea297f1400de8fcb2e8a815			

#38 - 2022-12-22 20:37 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151914	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:VehicleDataControl: Opt MicroServiceManager bind logical.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I779b3aa391c808fd51f58d478ce7f4c2e874b71f			

#39 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
153888	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroService: Fit interface to new.1. Modify interface name and parameters;2. Remove special callback, change common callback;3. Fit demo to new structure;TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: lc322ccf8dd5497afe9229847fd7179bbedd2617b			

#40 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
153889	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroService: Fit interface to new.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: l1f5e7ad88a05b4a4902fd3fbc150754958e85a05			

#41 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154132	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:move parsing parameters from MircoService to MicroSettings1.move parsing parameters from MircoService to MicroSettingsTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: l734ac14e9349ae022d9e18ee65b712afeb2db7ad			

#42 - 2022-12-22 20:41 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154391	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:Wash car mode and set volume1.into Wash car Mode2.set volume level and muteTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: l0acd130d9838cae6e62849b51e49446e37b12464			

#43 - 2022-12-22 20:41 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154467	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:Allow Wash Car Mode use "gesture_enable" 1.Allow Wash Car Mode use "gesture_enable" TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I11cf4f39c8eb521fdb701431e54fb9670c8a5202			

#44 - 2022-12-22 20:41 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154605	general/platform/vendor/thundercomm/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:Sync dark mode switch1.when Sync dark mode switch off, can change dark mode2.Modify some object nameingTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I4ee350da7dc4f8e6691f0b524ec00e75ac7c92a4			

#45 - 2022-12-22 20:42 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154682	general/platform/vendor/thundercomm/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:set brightness and sync net status1.set brightness level and mode2.sync net status3.catch set volume exceptionTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I808ddbc8043f75e0e4ba4df3463b030df5091bc8			

#46 - 2022-12-22 20:49 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
159982	general/platform/vendor/thundercomm/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:MicroService: Modify socket message structure.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I99a71b53e13f1ad9d4664e3612088b5cf923fff7			

#47 - 2022-12-22 20:49 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160248	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:MicroService:add micro service selinux policyTC-RID: 0301-0206101IssueID: TS-R-DF-110715Change-Id: Id944f745ef80029255c082c9ca1594ea157e7595			

#48 - 2022-12-22 20:49 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160252	general/platform/vendor/thundercomm/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:MicroService: Combine handshake operation.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I82a7e8d1988bba6c321a4a1929491053bd3bffa7			

#49 - 2022-12-22 20:51 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
161166	general/platform/vendor/thundercomm/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:Audio intermodulation1.Modify the JSON parsing2.Block sound settingsTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I7beb24e038d5fab08c67b0f794d8b049f7dd6369			

#50 - 2022-12-22 20:53 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
163196	general/platform/vendor/thundercomm/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:MicroService: Handle startup message from ICDM.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I8a681ce9acb16f5b43cb6bd0bf7a59cb84b9acb8			

#51 - 2023-02-03 16:03 - CD FW-程天颖

在中控给副屏发送指令过后，子模块没有回复中控，服务端会回复无结果消息，中控那边不希望收到该信消息，需要把消息发送改为log提示

#52 - 2023-02-07 20:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
179275	general/platform/vendor/thundercomm/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:MicroService:Remove RESULT_NOT_SUPPORT message1.when have no response,dont response message to central controlTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: laa5e2eddf09081f41aecc58ca75d5d2c2d5c10b			

#53 - 2023-02-17 18:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
181953	general/platform/vendor/thundercomm/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:Connect Test Change1.reconstitution2.Modify the intermodulation interfaceTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: lf306b00f6d28576c67b9c4a311a73230902eab8c			

#54 - 2023-02-17 18:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
182577	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl: Clearn Car Mode add VC1 screenTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I9b901369e4a5c9f9c918223ecbc57c9104a5f80d			

#55 - 2023-02-24 19:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
183870	general/platform/vendor/thundercomm/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:MicroService:Increase handshake failure round robinTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I41d5ca57a0a739b86e2fccf904a1db9f6f2486ff			

#56 - 2023-02-27 18:41 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
184482	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:MicroService:Modify handshake retry interval timeTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I3377ffeab949b911aa7cfeaeabfa5838ab936eb4			

#57 - 2023-03-02 15:10 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
182912	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:MicroSettongs: Crop don't need fileTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I1c39d439a7a009673e6c468b7b53e5975469b2c8			

#58 - 2023-03-02 17:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
185420	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:MicroSettongs: Remove aidl from android.bpTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I0c55311dd11041897d5d27f495e0f40d487dbc03			

#59 - 2023-03-02 19:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
185258	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:Factory reset Method name modifyTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I69bc03dc00eb388d449bf4c97f225204f5cad4eb			

#60 - 2023-03-08 14:31 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
185957	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:MicroService:Modify handshake retry interval timeTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I0fd4f2476a09f4fd7ed72810f929d5a75c2af9fc			

#61 - 2023-03-14 20:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
187434	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:MicroService:Add Send Message LogTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I83fc631d2324392b26a279fe03bfa00cc7bd683e			

#62 - 2023-03-23 20:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
188634	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:Time 24_12 mode sync and maping timezoneTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ie425630f3eb918cb4f678820cf7bfb7cb650d261			

#63 - 2023-03-31 10:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
186848	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:MicroSettongs: Tbox and wifi status syncTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I50d9b38626974419e25e7443d60a4d1266c7c58c			

#64 - 2023-04-18 19:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
193522	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:When device start, init the time as last saveTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I953971faef81925764035451152acc6c2d2807c1			

#65 - 2023-04-21 09:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194962	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com

AF:MicroService:When microservice restart have no callbackTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I56ecd4244b9a70631b946f6404710655b8b2055d

#66 - 2023-04-21 10:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
195079	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:Net change, Screen on/off1.Change wifi and tbox net2.Screen DisplayTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ib18d60cec8a7a1d6f4f3cb0226505909572ea2fc			

#67 - 2023-04-24 11:00 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194701	general/platform/vendor/thundercom/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:MicroService:Add heartbeat and simplify logTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I2b742ca133c544bc7d23c6b18dbcb088c87e0c0f			

#68 - 2023-05-09 20:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
198464	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl:Change the order of Net SwitchTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I41cac114418fa8646e11c78996139221a555240a			

#69 - 2023-06-14 15:48 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
207114	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:MicroSettings: When start init netTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I9fa7a773c6eae24591ab9b261cc814ce7e3bfc65			

#70 - 2023-06-14 15:48 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
207158	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: When start init netTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I9fa7a773c6eae24591ab9b261cc814ce7e3bfc65(cherry picked from commit 193a73725358fc6220a2f1ef6c736d7c6fa5ce4f)			

#71 - 2023-06-15 20:31 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
207821	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
Revert AF:MicroSettings: When start init netTC-RID: 1201-0206101IssueID: TS-R-DF-110715This reverts commit e9fd5d14e978521f2879754f3bc06785a2f90312.Reason for revert: <Cannot access network>Change-Id: I6c763ef66a2c6c1b64ecafa43531e458026c94c7			

#72 - 2023-06-15 22:06 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
207855	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroService: Use thread pool to manager threads.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I27fd44e0a9e7f2ee8381499b90ece3c79b391a93			

#73 - 2023-06-15 22:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
207831	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroService: Use thread pool to manager threads.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I27fd44e0a9e7f2ee8381499b90ece3c79b391a93			

#74 - 2023-06-16 15:27 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
207915	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:VehicleDataControl: Use thread pool to manager threads.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I02dcc99c0e00bd4397f8263e6d79840e3359671d			

#75 - 2023-06-16 15:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208000	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:VehicleDataControl: Use thread pool to manager threads.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I02dcc99c0e00bd4397f8263e6d79840e3359671d			

#76 - 2023-06-16 15:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208005	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroService: Optimize thread pool.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I11399cc05ec1f4c7403b7bf56ec2e3f455fce26f			

#77 - 2023-06-16 15:31 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
207916	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroService: Optimize thread pool.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I11399cc05ec1f4c7403b7bf56ec2e3f455fce26f			

#78 - 2023-06-16 16:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
207919	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangxl0510@thundersoft.com

Revert AF:MicroSettings: When start init netTC-RID: 1201-0206101IssueID: TS-R-DF-110715This reverts commit 193a73725358fc6220a2f1ef6c736d7c6fa5ce4f.Reason for revert: <Cannot access network>Change-Id: Ida4c20de8c0324f4a57db8e97807549b83da5459

#79 - 2023-06-20 16:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208641	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroSettings: Add ap info sync and connect function.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: le5526d377e78582351588898bfb7e419a8e7326f			

#80 - 2023-06-20 19:06 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208738	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroSettings: Init SerialNo text for Lebo license.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I309a4579ba104269be06d9bba274e167e3e7577d			

#81 - 2023-06-24 15:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209400	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroService: Optimize sub module bind logical.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-35659Change-Id: Iabe4e784e658eb0fb81885be2c8c0f5e816641aa			

#82 - 2023-06-24 15:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209397	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroService: Optimize sub module bind logical.MicroService send handshake requet after MicroSettings and AudioService module binded.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-35659Change-Id: Ib29485cc02450eaa77ddf300e3150eb03d74d541			

#83 - 2023-06-24 15:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209398	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:MicroService: Optimize sub module bind logical.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-35659Change-Id: I660c208de1b542de73170bfa66a10358cc93e21e			

#84 - 2023-06-24 15:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209396	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:MicroService: Optimize sub module bind logical.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-35659Change-Id: I0016a71493dea19ccc1f513acc78a2c92c79a785			

#85 - 2023-06-24 15:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209399	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:MicroService: Optimize sub module bind logical.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-35659Change-Id: I96514f33eabff59712f25257df500249305e10c2			

#86 - 2023-06-25 20:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209620	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:MicroService: Remove audio module ready check.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-35659Change-Id: Ia7a8ef8e5076663793f622c20c8cf9cb210ae7ad			

#87 - 2023-06-25 21:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209663	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

AF:MicroSettings: Add ap info sync and connect function.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ie5526d377e78582351588898bfb7e419a8e7326f(cherry picked from commit 2de6f370c51eed3b6c458e082c016131d3952253)

#88 - 2023-06-25 21:35 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209665	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Init SerialNo text for Lebo license.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I309a4579ba104269be06d9bba274e167e3e7577d(cherry picked from commit 9512239ea73cb2d1b8363404e32013e80de441f6)			

#89 - 2023-06-25 21:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209673	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:MicroService: Optimize sub module bind logical.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-35659Change-Id: Iabe4e784e658eb0fb81885be2c8c0f5e816641aa(cherry picked from commit 0b5ca5a4bd569cc6a922a3517b3e4507fe1b8dd9)			

#90 - 2023-06-25 21:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209674	general/platform/vendor/thundercom/apps/Mircoservice	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:MicroService: Optimize sub module bind logical.MicroService send handshake requet after MicroSettings and AudioService module binded.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-35659Change-Id: Ib29485cc02450eaa77ddf300e3150eb03d74d541(cherry picked from commit aec75800fa005f7d710209c8c230acb178aac81f)			

#91 - 2023-06-25 21:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209675	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

AF:MicroService: Optimize sub module bind logical.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-35659Change-Id: I660c208de1b542de73170bfa66a10358cc93e21e(cherry picked from commit c7e07e54254c4c2505c9c01eacfe7f02e52f6f1)

#92 - 2023-06-25 21:44 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209676	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroService: Optimize sub module bind logical.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-35659Change-Id: I0016a71493dea19ccc1f513acc78a2c92c79a785(cherry picked from commit cd473289264ff5e6034fd1aff2874dbd944311c9)			

#93 - 2023-06-25 21:44 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209677	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroService: Optimize sub module bind logical.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-35659Change-Id: I96514f33eabff59712f25257df500249305e10c2(cherry picked from commit 5967f3053285d2be8b933e872756c766dce771ef)			

#94 - 2023-06-25 21:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209686	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroService: Remove audio module ready check.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-35659Change-Id: Ia7a8ef8e5076663793f622c20c8cf9cb210ae7ad(cherry picked from commit ea0d1ec9531b3c99ee3ca1c9ab53ff8add3d67f9)			

#95 - 2023-06-30 11:11 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
211443	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com

AF:MicroService: Optimize send hand shark message when receive startup message.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: la07d31b14d191c1d7f9936c255750b4820201d4d

#96 - 2023-06-30 11:41 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
211466	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF: ScreenSaver: Replace system screensaver resources and change the default screensaver.TC-RID: 0301-0300603IssueID: TS-R-DF-110715Change-Id: l4d73ebef04838a541a5b406326f2299a59147094			

#97 - 2023-06-30 16:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
211565	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroService: Optimize send hand shark message when receive startup message.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: la07d31b14d191c1d7f9936c255750b4820201d4d(cherry picked from commit 0550a49a4f98cb628ab235cff49ac6b5c3a2856d)			

#98 - 2023-06-30 16:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
211567	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF: ScreenSaver: Replace system screensaver resources and change the default screensaver.TC-RID: 0301-0300603IssueID: TS-R-DF-110715Change-Id: l4d73ebef04838a541a5b406326f2299a59147094(cherry picked from commit 8d9baf5472f41c60b1a08dfe43caf42c458c4c5f)			

#99 - 2023-07-05 19:38 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212499	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroSettings: Optimize status bar icon set.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: l2db6b71372c2a4ea3a86762ba855d27e1243a2d7			

#100 - 2023-07-06 11:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
211604	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroSettings: Add brightness level update function.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-33499Change-Id: I4ad43063c1993759aec8169e12fba1d3cc07210b			

#101 - 2023-07-06 19:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212795	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Optimize status bar icon set.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I2db6b71372c2a4ea3a86762ba855d27e1243a2d7(cherry picked from commit a4cb8f13d1513865ed8f0dd262a8c0ed77c3e7ca)			

#102 - 2023-07-07 16:20 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212980	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Don't set prop when sys.network.wifi is not changed.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I8ce955fd6d5c7dae2de004963e1744f13c79d52f			

#103 - 2023-07-07 16:21 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213134	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroSettings: Don't set prop when sys.network.wifi is not changed.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I8ce955fd6d5c7dae2de004963e1744f13c79d52f			

#104 - 2023-07-10 10:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213373	general/platform/vendor/thundercom	Pre_figure_turbox-c2130c-la1.1-qssi12	tao.liao@thundersoft.com

	m/apps/VehicleControl	-dev	
AF:MicroSettings: Set default net and wifi statusbar icon when init.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I9a1c2445336aabf8ced87dd5a9e27d83115bfda6			

#105 - 2023-07-10 17:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213601	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Add brightness level update function.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-33499Change-Id: I4ad43063c1993759aec8169e12fba1d3cc07210b(cherry picked from commit 5fcbc0a7c8bdb981e9d708fd4c85065624a0d579)			

#106 - 2023-07-11 20:20 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
214033	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroSettings: Request WifiInfo when init.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I28d6a38f893bbcd51a9163870f5a699b653eb18b			

#107 - 2023-07-11 21:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213993	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Set default net and wifi statusbar icon when init.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I9a1c2445336aabf8ced87dd5a9e27d83115bfda6(cherry picked from commit d027fcc37579aac7fd0ca8aab638dd8e8a338a)			

#108 - 2023-07-13 21:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
214744	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com

AF:MicroSettings: Request WifiInfo when init.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I28d6a38f893bbcd51a9163870f5a699b653eb18b(cherry picked from commit f70c973eca68b16a1615416f9d9599ea1f043788)

#109 - 2023-07-27 20:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212485	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroSettings: Optimize time set action.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I99ead5ff0c1d6c8304711e009892829852ece59b			

#110 - 2023-07-27 23:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218314	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Optimize time set action.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I99ead5ff0c1d6c8304711e009892829852ece59b(cherry picked from commit 158a1d5a5f0dc8d9eb1cb53edd4278f98940daf3)			

#111 - 2023-08-01 10:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218963	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:MicroSettings: Fixed 5g icon.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I4541e81827822cc47baa8a9f65a5f482952d896e			

#112 - 2023-08-01 21:39 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216142	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroSettings: Add WifiInfo dns prop function.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ia40b1e748b07bff6fc5bc7637be34bd9f0d6272e			

#113 - 2023-08-02 09:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

219124	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:MicroSettings: When screen on, brightness level update.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-37912Change-Id: I48fb04dd145bb92729af278d8156ea9c37afa4d4			

#114 - 2023-08-04 10:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
300120	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Fixed 5g icon.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I4541e81827822cc47baa8a9f65a5f482952d896e(cherry picked from commit 03ac653febc907e5705cdf6d36e079d1579c6e3)			

#115 - 2023-08-04 10:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
300131	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: When screen on, brightness level update.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-37912Change-Id: I48fb04dd145bb92729af278d8156ea9c37afa4d4(cherry picked from commit d3a5045015a9f19be4e478c28920507cf551c80b)			

#116 - 2023-08-04 14:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212271	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroService: Encrypt message content.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ie73298cb5cf2da081f65db33dda65beca230e2a1			

#117 - 2023-08-04 17:59 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
300478	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com

AF:MicroSettings: Add wifi default dns value and modify tbox dns value.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I157f99ce9c9327de92a11e4821182f02950e19b9

#118 - 2023-08-09 13:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
300959	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:MicroSettings: Standard Time Synchronization InterfaceTC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-37255Change-Id: I0d47deec48e85c7222f02f3aad875e4d2018c87e			

#119 - 2023-08-10 20:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302368	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Add WifiInfo dns prop function.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ia40b1e748b07bff6fc5bc7637be34bd9f0d6272e(cherry picked from commit ae5467487894e572a2321f300a9308e5aed39a0d)			

#120 - 2023-08-10 20:48 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302379	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroService: Encrypt message content.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ie73298cb5cf2da081f65db33dda65beca230e2a1(cherry picked from commit 53031c916eb423dbaaa7253420fad7e87291718b)			

#121 - 2023-08-10 20:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302384	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Add wifi default dns value and modify tbox dns value.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I157f99ce9c9327de92a11e4821182f02950e19b9(cherry picked from commit f35ea38d03a234d2217a78ad06cb0a61574cf0a5)			

#122 - 2023-08-10 20:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302428	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Standard Time Synchronization InterfaceTC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-37255Change-Id: I0d47deec48e85c7222f02f3aad875e4d2018c87e(cherry picked from commit ac8977ada9d28388be263f5c35cc1233a6400b7a)			

#123 - 2023-08-14 15:39 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302514	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:MicroSettings: Request Actavete StatusTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ib0e6985cedcd7681be57b55869af8dc1dec38df4			

#124 - 2023-08-14 18:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
303210	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Request Actavete StatusTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Ib0e6985cedcd7681be57b55869af8dc1dec38df4(cherry picked from commit 65c01a94a58e2cbd90dc4d450f529856399dc3ee)			

#125 - 2023-08-16 19:23 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
303494	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:MicroSettings: Change get activate status logicTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I3e25d47598b01ccbc4c4db08900c6d30fe97071a			

#126 - 2023-08-17 19:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
304162	general/platform/vendor/thundercom	Pre_figure_turbox-c2130c-la1.1-qssi12	wangxl0510@thundersoft.com

	m/apps/VehicleControl	-release_sorp	
AF:MicroSettings: Change get activate status logicTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I3e25d47598b01ccbc4c4db08900c6d30fe97071a(cherry picked from commit 02c681744e4dd0e9aba3f8a7f71aae047610b8ef)			

#127 - 2023-08-22 18:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
305500	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:MicroSettings: Delete wifi icon and tbox icon.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: If1c3991a59bef24995f519187e9730a8d4b38ddb			

#128 - 2023-08-22 18:39 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
305335	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Delete wifi icon and tbox icon.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: If1c3991a59bef24995f519187e9730a8d4b38ddb(cherry picked from commit ea11e364434e77bf009a79c973db8dded96ccdd4)			

#129 - 2023-08-23 12:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
305632	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:MicroSettings: Delete wifi icon and tbox icon.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Iddf6baa4c174394f044e7bff900133c204be6241			

#130 - 2023-08-23 12:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
305646	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com

AF:MicroSettings: Delete wifi icon and tbbox icon.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Iddf6baa4c174394f044e7bff900133c204be6241(cherry picked from commit 3fcef89f558db5bcafbcb34d63de5ee762f58351)

#131 - 2023-09-06 14:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
310168	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroService: Fix message encrypt status problem.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-40704Change-Id: Iebb8b311fac0aa86449950ecdc1d572d2439b37a			

#132 - 2023-10-07 11:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317144	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroService: Fix message encrypt status problem.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-40704Change-Id: Iebb8b311fac0aa86449950ecdc1d572d2439b37a(cherry picked from commit a89ddb7840043ff1332aa41b40ca27a922880710)			

#133 - 2023-10-09 11:48 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317637	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroService: Fix message encrypt PKCS7Padding problem.Use custom padding implement.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, PVC1-3486Change-Id: I339ed670d5bbe578ea5250b85f3b7ffbb1e97f8b			

#134 - 2023-10-12 22:23 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
319115	general/platform/vendor/thundercom m/apps/MircoService	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroService: Fix message encrypt PKCS7Padding problem.Use custom padding implement.TC-RID: 1201-0206101IssueID: TS-R-DF-110715,			

#135 - 2023-10-17 10:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
320018	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:MicroSettings: Optimize the time and frequency of hotspot connections.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-46044Change-Id: I11d37231534732ec776e9bca1979ba71fd7ca791			

#136 - 2023-10-19 16:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
320464	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:MicroSettings:Disable time recordTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I24caff85b906535aa0763af2832d7b815cd71fa7			

#137 - 2023-10-25 11:14 - CD FW-程天颖

- Status changed from New to 完成 Closed

#138 - 2023-10-27 01:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323297	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Optimize the time and frequency of hotspot connections.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-46044Change-Id: I11d37231534732ec776e9bca1979ba71fd7ca791(cherry picked from commit f02ff9d8fcf5e627ecea28c679d46dd01a4fd0b2)			

#139 - 2023-10-27 01:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323314	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings:Disable time recordTC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: I24caff85b906535aa0763af2832d7b815cd71fa7(cherry picked from commit 3104880401ed577b400cfb78a19573b2f78a3e7e)			

#140 - 2023-11-08 18:23 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
326674	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:ScreenSaver:replace system screensaver picture for MCETC-RID: 1201-0300603IssueID: TS-R-DF-110715Change-Id: I26012cc0e7a75ce8cd3fbcfd658fd2129c3dbdfe			

#141 - 2023-11-08 22:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
326552	general/platform/vendor/thundercom m/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:ScreenSaver:replace system screensaver picture for MCETC-RID: 1201-0300603IssueID: TS-R-DF-110715Change-Id: I26012cc0e7a75ce8cd3fbcfd658fd2129c3dbdfe(cherry picked from commit 080502e9b99d98e6631633ccd4ced8867f5af0d9)			

#142 - 2023-11-20 11:08 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
325748	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroSettings: Add IDCM mac address disable function.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Icd985564e531afbfdaddc622bfc17537cc173146			

#143 - 2023-11-20 13:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329433	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Add IDCM mac address disable function.TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: Icd985564e531afbfdaddc622bfc17537cc173146(cherry picked from commit 60cfa9415bc50214da31cd1df166517e835ff653)			

#144 - 2023-11-20 14:53 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
329387	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroSettings: Fix not update time display problem after time set.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, QMV-1016Change-Id: Ib91d60872e095dcb103549ce430c78dc92440bd9			

#145 - 2023-11-23 20:10 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
330683	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Fix not update time display problem after time set.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, QMV-1016Change-Id: Ib91d60872e095dcb103549ce430c78dc92440bd9(cherry picked from commit 825b245a115f791f28f262aa14f95bd76dc590b2)			

#146 - 2023-12-18 15:35 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
336803	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroSettings: Fix screen display status set failed problem.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-51121Change-Id: If94cbff46177fcdc6770e9117e823eaa0e1d83ab			

#147 - 2023-12-19 11:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
337415	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:MicroSettings: Fix screen display status set failed problem.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-51121Change-Id: If94cbff46177fcdc6770e9117e823eaa0e1d83ab(cherry picked from commit 57d97a1598172e0f3cb1a797f7c5c691e665f869)			

#148 - 2023-12-19 11:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
337417	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev_vx1	wangxl0510@thundersoft.com

AF:MicroSettings: Fix screen display status set failed problem.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-51121Change-Id: If94cbff46177fcdc6770e9117e823eaa0e1d83ab(cherry picked from commit 57d97a1598172e0f3cb1a797f7c5c691e665f869)

#149 - 2023-12-19 11:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
337416	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp_vx1	wangxl0510@thundersoft.com
AF:MicroSettings: Fix screen display status set failed problem.TC-RID: 1201-0206101IssueID: TS-R-DF-110715, IOVDEV-51121Change-Id: If94cbff46177fcdc6770e9117e823eaa0e1d83ab(cherry picked from commit 57d97a1598172e0f3cb1a797f7c5c691e665f869)			

#150 - 2024-01-03 18:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
341940	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:MicroSettings: Report screen status 1 second after SetScreenDisplayAction.1. Change logical to check display status;TC-RID: 1201-0206101IssueID: TS-R-DF-110715, QMV-2787Change-Id: I781b5f171d209757d1dc6bfeaf01ccf98da792d9			

#151 - 2024-01-04 09:29 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
342004	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev_vx1	wangxl0510@thundersoft.com
AF:MicroSettings: Report screen status 1 second after SetScreenDisplayAction.1. Change logical to check display status;TC-RID: 1201-0206101IssueID: TS-R-DF-110715, QMV-2787Change-Id: I781b5f171d209757d1dc6bfeaf01ccf98da792d9(cherry picked from commit 01edb56754af3b373ac4f28bc28d98f1a5901236)			

#152 - 2024-01-04 09:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
342005	general/platform/vendor/thundercom m/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com

AF:MicroSettings: Report screen status 1 second after SetScreenDisplayAction.1. Change logical to check display status;TC-RID: 1201-0206101IssueID: TS-R-DF-110715, QMV-2787Change-Id: l781b5f171d209757d1dc6bfeaf01ccf98da792d9(cherry picked from commit 01edb56754af3b373ac4f28bc28d98f1a5901236)

#153 - 2024-01-04 09:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
342007	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp_vx1	wangxl0510@thundersoft.com
AF:MicroSettings: Report screen status 1 second after SetScreenDisplayAction.1. Change logical to check display status;TC-RID: 1201-0206101IssueID: TS-R-DF-110715, QMV-2787Change-Id: l781b5f171d209757d1dc6bfeaf01ccf98da792d9(cherry picked from commit 01edb56754af3b373ac4f28bc28d98f1a5901236)(cherry picked from commit a446d16eb9cb9ead36d5e5b542be329e6056b3f1)			

#154 - 2024-02-01 14:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
345915	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:MicroSettings: ThreadPoolExecutor optimize and fix ap connect lock problem.1. Add log for ThreadPoolExecutor;2. Modify ExecutorService.submit to ExecutorService.execute;3. Fix ap connect lock problem;TC-RID: 1201-0206101IssueID: TS-R-DF-110715, QMV-3638Change-Id: l1bb5c9a376843b770c7d6487d9e48f593bf17a0f			

#155 - 2024-02-02 18:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
350525	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:MicroSettings: Check network connect status by PING.1. Check network connect status by PING;TC-RID: 1201-0206101IssueID: TS-R-DF-110715Change-Id: l9d4135fca609b17434d9e1acf7c150498a5c2275			

