

Figure - 开发 Dev #110717

开发 Dev # 110122 (New): 【MK】 管理总票

开发 Dev # 110126 (New): 【MK】 【AF】 管理总票

【MK】 【FW】 【RemoteControl】 【TC-RID: 1201-0206001】 遥控器服务端

2022-07-25 17:15 - CD FW-王伟

Status:	完成 Closed	Start date:	2023-01-16
Priority:	Normal	Due date:	
Assignee:	CD FW-廖涛	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_20220930		
Description			
■需求列表: 副驾遥控器、后排遥控器 熄屏操作 屏保持机操作 关机操作 返回HOME页接口 实时调整音量 全局返回操作 所有的APPlist同步更新 方向指令下发接口 确认/取消指令下发接口 模拟鼠标 快捷中心的list PRD:手势交互及SDK需求文档 -> https://thundersoft.feishu.cn/docs/doccno15mUUqtUaQl8hGajlZOnc ■提出URL：必填 ■自测case：必填 ■注意点：需要测试注意的前提条件			
Subtasks:			
开发 Dev # 115371: 【MK】 【FW】 【RemoteControl】 【TC-RID: 1201-0206001】 ...			完成 Closed

History

- #1 - 2022-07-25 19:46 - CD FW-王伟
- Assignee changed from CD FW-王伟 to CD FW-程天颖
- #2 - 2022-08-04 19:44 - CD FW-王伟
- Subject changed from 【MK】 【005】 【RemoteControl】 【TC-RID: 0301-0206001】 遥控器服务端 to 【MK】 【005】 【RemoteControl】 【TC-RID: 1201-0206001】 遥控器服务端
- #3 - 2022-08-05 11:24 - CD FW-王伟
- Assignee changed from CD FW-程天颖 to CD FW-廖涛
- #4 - 2022-09-08 08:32 - CD FW-王伟
- Subject changed from 【MK】 【005】 【RemoteControl】 【TC-RID: 1201-0206001】 遥控器服务端 to 【MK】 【FW】 【RemoteControl】 【TC-RID: 1201-0206001】 遥控器服务端
- #5 - 2022-09-26 13:46 - CD FW-王伟

- Target version set to VXL_MCE_FSE_V2.0_20220930

#6 - 2022-09-26 20:28 - CD FW-王伟

- Status changed from New to 完成 Closed
- % Done changed from 0 to 100

此需求，已经入库并且功能已经提测。

#7 - 2022-12-22 20:19 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
138837	general/platform/vendor/thundercom/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
AF:RemoteControl:add service code1. first add project codeTC-RID: 0300-0300501IssueID: TS-R-DF-110717Change-Id: Ica477d535a40ec30b7212889a711b9190875c556			

#8 - 2022-12-22 20:19 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
139462	general/platform/vendor/thundercom/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hao.liu_d@thundersoft.com
AF:RemoteControl:Support compilation under source code1. Support compilation under source code2. Delete some useless codesTC-RID: 0300-0206001IssueID: TS-R-DF-110717Change-Id: Ife590c0ba6ec5396742496763bd13234763790cf			

#9 - 2022-12-22 20:19 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
139651	general/platform/vendor/thundercom/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl:Modify server code.1. Remote key command done.2. Add Applist and Applaunch command.3. Add QuickSettingList and QuickSettingClick command.4. Optimize code structure.TC-RID: 0301-0206001IssueID: TS-R-DF-110717Change-Id: Ief095721dc90dd35e11c88d2c3e04604cee0103f			

#10 - 2022-12-22 20:20 - CD FW-王伟**Gerrit Merge Information :**

ID	Project	Branch	Uploader
140503	general/platform/vendor/thundercom/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Controll1. Optimize socket server structure;2. Complete applist info and launch;3. Delete unused class and function;TC-RID: 0301-0206001IssueID: TS-R-DF-110717Change-Id: I14b63496bb28283f3d443ce09b3578392a66c887			

#11 - 2022-12-22 20:21 - CD FW-王伟**Gerrit Merge Information :**

ID	Project	Branch	Uploader
140900	general/platform/vendor/thundercom/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Service1. Modify socket message structure, support large data transform;2. Support app icon transform;3. Complete QuickSetting List & Action command function;TC-RID: 0301-0206001IssueID: TS-R-DF-110717Change-Id: I9ec91242f1e7a8d087adee55b1e0c161076d9ed5			

#12 - 2022-12-22 20:21 - CD FW-王伟**Gerrit Merge Information :**

ID	Project	Branch	Uploader
140976	general/platform/vendor/qcom/kona	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangwei0629@thundersoft.com
AF:SystemProperties: Modify the lcd density through systemproperty1.Modify the lcd density through systempropertyTC-RID: 1201-0202001IssueID: TS-R-DF-110717Change-Id: I21284a3c03c65dbf81e89a4612ac6ffb3c1eb260			

#13 - 2022-12-22 20:21 - CD FW-王伟**Gerrit Merge Information :**

ID	Project	Branch	Uploader
141006	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: ServiceAdd get QSTile list and QSTile switch functionTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id:			

#14 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141482	general/platform/vendor/thundercomm/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Service1. Fix app icon transfer problem;2. Add app icon transfer interface;3. Support get app list without app icon;4. Start control service with device real ip address;5. Support get quick setting icon;TC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: I522a3fc07ba51aada73034bf9344eaae20b7ce09			

#15 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141547	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: ServiceSupport get quick setting icon;TC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: Id550597486689ed935803553da6c46cc51fbbe18			

#16 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142062	general/platform/vendor/thundercomm/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Server mouse control1. Add mouse control function;2. Remove code not used;TC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: I37c03da02e8a67ece49e699e6ea19f515de43344			

#17 - 2022-12-22 20:23 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142141	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com

FW:RemoteControl: Add module into systemAdd RemoteControl module into systemTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: I8717ef01c5ae886a001e1a3c46e3f107b268aa79

#18 - 2022-12-22 20:23 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142650	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Server - Add RemoteControlService to startup.TC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: Ia84187cddda1a2600b998752ba5ef7cae420513b			

#19 - 2022-12-22 20:23 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142740	general/platform/vendor/thundercomm/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Service - Remove activity and launcher icon, remove resources files.TC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: Ic3565e1d8b4ec0d60edf231d2344ab72ce0416d0			

#20 - 2022-12-22 20:24 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142937	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
FW:RemoteControl: Add libremoteservice into deviceAdd libremoteservice into deviceTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: I946883d47f9b1a921bb485fdbb173106902e9b6a			

#21 - 2022-12-22 20:24 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142938	general/platform/system/core	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com

AF:RemoteControl: Add permission for uinput1. Add permission for uinputTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: I2ad6494836fd4a9d4738a0e5422199312ef00b11

#22 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143712	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:RemoteControl:add selinux permissionadd uhid_device write open ioctl permissionTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: I24390cfccd2d5271803c370755aa18c69282e79e			

#23 - 2022-12-22 20:26 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
144626	general/platform/vendor/thundercomm/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Service - Fix restart server logic problem.TC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: I96f5856b4d63a55e1960f4614396d2750355c857			

#24 - 2022-12-22 20:27 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145012	general/platform/vendor/thundercomm/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Service - Add swipe function.TC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: Ibbf44e1356413a4e8829807b7c43aa0fe7549492			

#25 - 2022-12-22 20:28 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145746	general/platform/vendor/thundercomm/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Service - Rename NLog to TLog.TC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: If81524dbed4a7f9cd7ec2260fb9892cf9ed973dc			

#26 - 2022-12-22 20:37 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152193	general/platform/vendor/thundercom/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Service - Opt mouse control and swipe control request.TC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: Ib2aa7ce817bbd11af7443ae929f8687c3ca88aa5			

#27 - 2022-12-29 15:54 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
172407	general/platform/vendor/thundercom/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Service - Allows listening on VLAN NICs1. Allows listening on VLAN NICs2.The swipe feature occasionally crashes issuesTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: Ie49d30404d66fe38cb15d092502f92dd1c1c3697			

#28 - 2022-12-30 18:00 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
173087	general/platform/vendor/thundercom/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Service - Show volume when set volumeTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: I327a9b9e92094b2c08b1b2615cfd21466eb861f2			

#29 - 2023-02-01 20:52 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
178425	general/platform/vendor/thundercom/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Service - Add response response time testTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: If43cbbb1db052ca60ac460ac2efbfcd02e5b6a70			

#30 - 2023-02-22 17:49 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
183306	general/platform/vendor/thundercom	Pre_figure_turbox-c2130c-la1.1-qssi12	tianying.cheng@thundersoft.com

	m/apps/RemoteControlServer	-dev	
AF:RemoteControl: Server - Add Mouse Press move actionTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: I8a3f5cbf891c0b89860824afff2836079ba41380			

#31 - 2023-03-02 16:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
185190	general/platform/vendor/thundercom m/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Server - Add query screen status actionTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: Id93866a264d6edcfba3da209e88b11f434b1aca3			

#32 - 2023-03-09 15:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
185877	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Server - Add query point postion api into InputManagerTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: I61335936914528509656afda9b0af3c860cb21fd			

#33 - 2023-03-09 15:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
185947	general/platform/vendor/thundercom m/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Server - Add query muse point position actionTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: I3db7572b1f6a9f7fef4f500fc1641c7f9c0712a8			

#34 - 2023-03-09 18:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
184846	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Server - Mouse view dismiss timeTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id:			

#35 - 2023-04-10 10:19 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
192233	general/platform/vendor/thundercom/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Server - User mouse point as Swipe start pointTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: I2aeba63fcf7d3a4eb2664b3d733918baed08e3c4			

#36 - 2023-04-20 13:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194839	general/platform/vendor/thundercom/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Server - Improves heartbeat stabilityTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: Ic474ace795c4182d39095275edc3d22031c6d449			

#37 - 2023-04-20 13:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194840	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client(Android) - Improves heartbeat stabilityTC-RID: 1201-0206002IssueID: TS-R-DF-110717Change-Id: Ief469a80ab3ab5b75000b1fb52e59b03b3c2c92b			

#38 - 2023-04-21 16:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
195317	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(iOS) - Improves heartbeat stabilityoptimize send boardcast logical.TC-RID: 1201-0206002IssueID: TS-R-DF-110717Change-Id: Ibf8aa441e5f7985a6f8c600046cbd5c7563165			

#39 - 2023-04-24 15:33 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
195740	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client(Android) - Optimize get server ip function.TC-RID: 1201-0206002IssueID: TS-R-DF-110717Change-Id: Ib84c4b7755fad760b2e473c6944065c9e905caea			

#40 - 2023-04-24 17:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
195744	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(iOS) - Fix get app list crash when a mass of apps.Other:1. Improves heartbeat stability;2. Deal send keycode error;TC-RID: 1201-0206002IssueID: TS-R-DF-110717Change-Id: Ib1a7919392ae001486993619a4d23720ccbea095			

#41 - 2023-04-24 20:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
195865	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client(Android) - When Screen off key command have right resultTC-RID: 1201-0206002IssueID: TS-R-DF-110717Change-Id: Ic0ce94f9efd155874ba737190cd2bf5405dd26db			

#42 - 2023-04-24 20:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
195866	general/platform/vendor/thundercom/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Server - When screen off key command have no right resultTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: Ib5bc69f3326ef430d2aae44930cbdeaf31295c65			

#43 - 2023-04-28 18:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

197150	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(iOS) - Fix get server ip list problem.TC-RID: 1201-0206002IssueID: TS-R-DF-110717Change-Id: Id2917fc9ab2bb37d736920121e87225ee5837afd			

#44 - 2023-05-04 17:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
197417	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(iOS) - Update version to V1.8TC-RID: 1201-0206002IssueID: TS-R-DF-110717Change-Id: I27a7f4b7ed7484d14257d7d232eb6ce851a7dd02			

#45 - 2023-05-10 16:08 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
199004	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client(Android) - Use TrafficStats to track all network usageTC-RID: 1201-0206002IssueID: TS-R-DF-110717Change-Id: I0b208c126ef4ee1c9072c3dac55d212794ee45c0			

#46 - 2023-05-23 22:11 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
201819	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(iOS) - Add callback unregister method.TC-RID: 1201-0206003IssueID: TS-R-DF-110717Change-Id: I2ceaaf6ebcf7af7649997d3e0c13549067f75cdd			

#47 - 2023-05-23 22:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
202090	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com

AF:RemoteControl: Client(Android) - Add clear callback methondTC-RID: 1201-0206002IssueID: TS-R-DF-110717Change-Id: I3b43a8269c369c0edaf95ac2f4a9f744ad96f191

#48 - 2023-05-24 14:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
202194	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(iOS) - Update version to V2.0TC-RID: 1201-0206003IssueID: TS-R-DF-110717Change-Id: I6b680dae1cd859e290bfd44ae924ba2a9d24c91d			

#49 - 2023-05-24 14:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
202193	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client(Android) - Update sdk versionTC-RID: 1201-0206002IssueID: TS-R-DF-110717Change-Id: I35e3385d3659260876802320a5a0e159c4eaf00			

#50 - 2023-05-26 15:00 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
202816	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client(Android) - Update version to V2.1TC-RID: 1201-0206002IssueID: TS-R-DF-110717Change-Id: I432308cdd636dce0499c6f96bcea3de6443726f			

#51 - 2023-05-27 16:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
203053	general/platform/vendor/thundercom m/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Server - Error codes that are frequently masked are blockedTC-RID: 1201-0206001IssueID: TS-R-DF-110717Change-Id: I7042b6f53861bfb59f434eafdeba1fd92dc353c			

#52 - 2023-07-06 11:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
211605	general/platform/vendor/thundercom m/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Server - Optimze thread create and Add brightness level update function.TC-RID: 1201-0206001IssueID: TS-R-DF-110717, IOVDEV-33499Change-Id: Icdaffd42ca0b91d2816c7e3596886b2f22805203			

#53 - 2023-07-10 17:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213602	general/platform/vendor/thundercom m/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:RemoteControl: Server - Optimze thread create and Add brightness level update function.TC-RID: 1201-0206001IssueID: TS-R-DF-110717, IOVDEV-33499Change-Id: Icdaffd42ca0b91d2816c7e3596886b2f22805203(cherry picked from commit 8d356b55ff1bc94c22fcf258d9ba0b062087cd83)			

#54 - 2023-08-02 09:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
219249	general/platform/vendor/thundercom m/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Server: remoe brightness keppTC-RID: 1201-0206001IssueID: TS-R-DF-110717, IOVDEV-37912Change-Id: I872ade8952ae239e2ce54b0633a5a7f836c7b806			

#55 - 2023-08-04 10:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
300130	general/platform/vendor/thundercom m/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:RemoteControl: Server: remoe brightness keppTC-RID: 1201-0206001IssueID: TS-R-DF-110717, IOVDEV-37912Change-Id: I872ade8952ae239e2ce54b0633a5a7f836c7b806(cherry picked from commit cd3694642ce6f74bdcf977c281d28c0dac8ffd5f)			