

Figure - 开发 Dev #110718

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110126 (New): 【MK】【AF】管理总票

【MK】【FW】【RemoteControl】【TC-RID: 1201-0206002】Android 客户端SDK

2022-07-25 17:16 - CD FW-王伟

Status:	完成 Closed	Start date:	2022-07-25
Priority:	Normal	Due date:	
Assignee:	CD FW-廖涛	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_20220930		
Description			
■ 需求列表: 遥控器 Android 客户端SDK			
■ 提出URL：必填			
■ 自测case：必填			
■ 注意点：需要测试注意的前提条件			

History

- #1 - 2022-07-25 19:46 - CD FW-王伟
- Assignee changed from CD FW-王伟 to CD FW-程天颖
- #2 - 2022-08-04 19:44 - CD FW-王伟
- Subject changed from 【MK】【005】【RemoteControl】【TC-RID: 0301-0206002】Android 客户端SDK to 【MK】【005】【RemoteControl】【TC-RID: 1201-0206002】Android 客户端SDK
- #3 - 2022-08-29 18:38 - CD FW-廖涛
- Assignee changed from CD FW-程天颖 to CD FW-廖涛
- #4 - 2022-09-08 08:33 - CD FW-王伟
- Subject changed from 【MK】【005】【RemoteControl】【TC-RID: 1201-0206002】Android 客户端SDK to 【MK】【FW】【RemoteControl】【TC-RID: 1201-0206002】Android 客户端SDK
- #5 - 2022-09-26 13:46 - CD FW-王伟
- Target version set to VX1_MCE_FSE_V2.0_20220930
- #6 - 2022-09-26 20:28 - CD FW-王伟
- Status changed from New to 完成 Closed
- % Done changed from 0 to 100

此需求，已经入库并且功能已经提测。

#7 - 2022-12-22 20:19 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
138475	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hao.liu_d@thundersoft.com

AF:RemoteControl:add proiect code1. first add project codeTC-RID: 0301-0206002IssueID: TS-R-DF-110718Change-Id: I1ded7ce7705c0eb2e7293814b2f6e1bc1205e46b

#8 - 2022-12-22 20:19 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
139470	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl:Modify client code, add volume controllerTC-RID: 0301-0206002IssueID: TS-R-DF-110718Change-Id: I3207b668e0833fb625e062d5d2d316741320ee5d			

#9 - 2022-12-22 20:19 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
139609	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl:Modify client code, add volume controller1.add callback methode2.add applist3.add start app4.when connected get the token5.input ipaddress and device type to connectTC-RID: 0301-0206002IssueID: TS-R-DF-110718Change-Id: Ie8123c92eec022ef378a40d16ecbbb675e9caeb9			

#10 - 2022-12-22 20:20 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
140607	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl:Modify client code, add volume controller1.Connection status management2.Detail optimization3.Structural optimizationTC-RID: 0301-0206002IssueID: TS-R-DF-110718Change-Id: I7d92c25502f18801b2dbf20ad72fd92f102afc91			

#11 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader

140804	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client1. Modify socket message structure;2. Optimize socket send & receive message module;3. Add app icon;TC-RID: 0301-0206002IssueID: TS-R-DF-110718Change-Id: I891aca7144fd2e2e6d80db89a6248c6abb73b518			

#12 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
140811	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client1. add quick stting:TC-RID: 0301-0206002IssueID: TS-R-DF-110718Change-Id: Iecaa6d71d6c5b13ef3e0a9dc352466908971c74e			

#13 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141220	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client1. Connect status bug fixes2.Use RadioButton select connect device sourceTC-RID: 0301-0206002IssueID: TS-R-DF-110718Change-Id: I1e056490aa7fc35957c35bdd9464dd37b874c1fd			

#14 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141268	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client1.Data detection2.RegisterInfo optimizeTC-RID: 1201-0206002IssueID: TS-R-DF-110718Change-Id: I766f5a47309b980b5bef14a781f7d1511b902dee			

#15 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141452	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client1.Parse sockt data fixedTC-RID: 1201-0206002IssueID: TS-R-DF-110718Change-Id: I3e1cda2572472f24f0c9a4071d93fee329f7c4a2			

#16 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141503	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client1.Load app images in batchesTC-RID: 1201-0206002IssueID: TS-R-DF-110718Change-Id: I607428f9013d66854498d1ec7668ddeade592a83			

#17 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141549	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client1.Show quick settings iconTC-RID: 1201-0206002IssueID: TS-R-DF-110718Change-Id: I5ae56d05df2dd339a7deed18d94d338c3bcb8115			

#18 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142071	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Client mouse control, refact code structure.1. Add mouse control function;2. Refact code structure;3. Opt socket request & response;TC-RID: 1201-0206001IssueID: TS-R-DF-110718Change-Id: I12275baf920e071b96b13190a52685bacdbe6445			

#19 - 2022-12-22 20:27 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145242	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client - Add swipe control function.TC-RID: 1201-0206001IssueID: TS-R-DF-110718Change-Id: I1fd6aaa7fce4afa71d671dd2be153bdffe665ed5			

#20 - 2022-12-22 20:27 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145243	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client - Opt demo page.TC-RID: 1201-0206001IssueID: TS-R-DF-110718Change-Id: I1cc0fee56789ea016dcd90141e35b7f5d17eaede			

#21 - 2022-12-22 20:27 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145401	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client - General android sdk aar.TC-RID: 1201-0206002IssueID: TS-R-DF-110718Change-Id: I46fee931787aed8ff352c71d1e447daa42332ea8			

#22 - 2022-12-22 20:27 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145674	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client - Remove fastjson library, using org.json library.TC-RID: 1201-0206002IssueID: TS-R-DF-110718Change-Id: I34b0179f41d6ef586cf0abad9ebce4c6aae7ef0d			

#23 - 2022-12-22 20:28 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145751	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com

AF:RemoteControl: Client - Rename NLog to TLog.TC-RID: 1201-0206002IssueID: TS-R-DF-110718Change-Id:
Ia012e529b4604f82c4bc7cd60d4d60d63b1413fd

#24 - 2022-12-22 20:32 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
149035	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-Ia1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client - Modify callback name, opt code.TC-RID: 1201-0206002IssueID: TS-R-DF-110718Change-Id: I789b405bcbf445b7b4933691e9d4384cae7f196a			

#25 - 2022-12-22 20:33 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
149709	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-Ia1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client - Add direction control function.TC-RID: 1201-0206002IssueID: TS-R-DF-110718Change-Id: Ia84510d5a75903d5593e3f6bcf178bc72179f9cd			

#26 - 2022-12-22 20:37 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152195	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-Ia1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client - Opt mouse control and swipe control request.1. Opt mouse control and swipe control request;2. Perfect error message handle;TC-RID: 1201-0206002IssueID: TS-R-DF-110718Change-Id: Ia0c4baf703f7e1909860d84d74fd313b8788ad9b			

#27 - 2022-12-22 20:45 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
157112	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-Ia1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client - Fix iOS SDK Swipe action bug.TC-RID: 1201-0206002IssueID: TS-R-DF-110718Change-Id: Ifad61ddc164c8b62b3770e6b2dc442d532123105			

#28 - 2022-12-29 15:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
172408	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client(Android) - The central control uses VLAN communicationTC-RID: 1201-0206002IssueID: TS-R-DF-110718Change-Id: I0166738041417bb4d07991f84998a5dbea442107			

#29 - 2022-12-30 18:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
172815	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client(Android) - Add set volume methodTC-RID: 1201-0206002IssueID: TS-R-DF-110718Change-Id: I093f7003e77ec44758278bc6ae6899f795d9dcb9			

#30 - 2023-02-22 17:48 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
183477	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(iOS) - Add mouse press move action.TC-RID: 1201-0206003IssueID: TS-R-DF-110718Change-Id: I77781f717378594b587354e9930ea66d3a9b7711			

#31 - 2023-02-22 17:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
183310	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client(Android) - Add Mouse Press move actionTC-RID: 1201-0206003IssueID: TS-R-DF-110718Change-Id: Ide98803a1100a664e992c5ba381a65588a93570c			

#32 - 2023-03-02 16:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
185192	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com

AF:RemoteControl: Client(Android) - Add query screen status action.TC-RID: 1201-0206003IssueID: TS-R-DF-110718Change-Id:
I3a3c34f1dbf5f78e7dada0f1ad3e6f16cd17a1e0

#33 - 2023-03-02 16:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
185394	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(iOS) - Add query screen status action.TC-RID: 1201-0206003IssueID: TS-R-DF-110718Change-Id: I7c7d46eca6ada2dd8bf7c0337d5c727da456d0a3			

#34 - 2023-03-08 14:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
186118	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(iOS) - Add query point position action.TC-RID: 1201-0206003IssueID: TS-R-DF-110718Change-Id: I40cf248b86cc4399124c744b674f16f7ac83967f			

#35 - 2023-03-09 15:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
185948	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client(Android) - Add query point position action.TC-RID: 1201-0206003IssueID: TS-R-DF-110718Change-Id: Ic5ed3365512682f99e39696b6825dbeb888d8c41			

#36 - 2023-03-21 19:22 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
188865	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client(Android) - Modify minSdkTC-RID: 1201-0206003IssueID: TS-R-DF-110718Change-Id: I76cc818e7c859ceb534ae707a30b5002e4d6014b			

#37 - 2023-04-10 19:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
192737	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(iOS) - Adjust iPhone devices which version gather than 14.0TC-RID: 1201-0206003IssueID: TS-R-DF-110718Change-Id: If81aa210ba86534bc685edf28e97cef4bb99493c			

#38 - 2023-04-13 20:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
193621	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(iOS) - Optimize Demo MyTouchView for swipe command.TC-RID: 1201-0206003IssueID: TS-R-DF-110718Change-Id: I5d0cbe3d29f24991d8b53b0c51cae1bdf42cc5dc			

#39 - 2023-04-15 16:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194060	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(iOS) - Add version print and log output.1. Add output current sdk version;2. Add log output callback;3. Add screen status - dream on;TC-RID: 1201-0206003IssueID: TS-R-DF-110718Change-Id: I95e1b6e7d3fd3da947d6016bfa017f877c0ae9bc			

#40 - 2023-04-19 11:38 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194570	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client(Android) - add TLog call backTC-RID: 1201-0206002IssueID: TS-R-DF-110718Change-Id: Icd0ee20b4e6ed5d85687672eb8beb89ee5eea408			

#41 - 2023-04-19 19:23 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
194739	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(iOS) - Optimize get server ip function.TC-RID: 1201-0206003IssueID: TS-R-DF-110718Change-Id: I9bf44ac7377bce31cea5ff5b068df3558ae0641d			