

Figure - 开发 Dev #110743

开发 Dev # 110122 (New): 【MK】管理总票
开发 Dev # 110126 (New): 【MK】【AF】管理总票
【MK】【FW】【Notification】【TC-RID: 1201-0201902】
2022-07-25 20:06 - CD FW-程天颖

Status:	进行中 In Progress	Start date:	2022-07-25
Priority:	Normal	Due date:	
Assignee:	CD FW 曹覃刚	% Done:	70%
Category:		Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030		
Description			
■ 需求列表: "从左边状态栏下拉，显示通知，右边状态栏下拉显示控制中心，在通知列表或者控制中通过左滑或者右滑，进行切换显示通知与控制中心。查看通知详情，支持单条，及批量删除" ■ 提出URL：必填 ■ 自测case：必填 ■ 注意点：需要测试注意的前提条件			

History

- #1 - 2022-08-04 19:47 - CD FW-王伟
- Subject changed from 【MK】【019】【Notification】【TC-RID: 0301-0201802】 to 【MK】【019】【Notification】【TC-RID: 1201-0201802】
- #2 - 2022-08-05 11:13 - CD FW-王伟
- Assignee set to FW&MW2组_DLTS 刘显鹤
- #3 - 2022-09-08 08:34 - CD FW-王伟
- Subject changed from 【MK】【019】【Notification】【TC-RID: 1201-0201802】 to 【MK】【FW】【Notification】【TC-RID: 1201-0201802】
- Assignee changed from FW&MW2组_DLTS 刘显鹤 to CD FW-鲁凯峰
- #4 - 2022-09-22 20:07 - CD FW-王伟
- Subject changed from 【MK】【FW】【Notification】【TC-RID: 1201-0201802】 to 【MK】【FW】【Notification】【TC-RID: 1201-0201902】
- #5 - 2022-09-26 20:07 - CD FW-王伟
- Assignee changed from CD FW-鲁凯峰 to CD FW 曹覃刚
- Target version set to VX1_MCE_FSE_V2.0_20220930
- #6 - 2022-10-10 20:16 - CD FW-王伟
- Status changed from New to 进行中 In Progress
- Target version changed from VX1_MCE_FSE_V2.0_20220930 to VX1_MCE_FSE_V3.0_20221030
- % Done changed from 0 to 70

通知栏开发已经完成，带后续UI适配

#7 - 2023-06-20 19:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208733	general/platform/packages/modules/Wifi	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lei.zheng@thundersoft.com

FW:Notification: Hide wifi related notificationsTC-RID: 1201-0201902IssueID: TS-R-DF-110743Change-Id: Ib40a25cbc88e58b52ed9412978e0c857c80efc8d

#8 - 2023-06-25 21:32 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209208	general/platform/packages/modules/Wifi	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:Notification: Hide wifi related notificationsTC-RID: 1201-0201902IssueID: TS-R-DF-110743Change-Id: Ib40a25cbc88e58b52ed9412978e0c857c80efc8d(cherry picked from commit 4b2482dc5519e5ecd78bc385fb5edcf85febed77)			

#9 - 2023-07-10 17:31 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213607	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Notification: Fix silent header view display problem.TC-RID: 1201-0201902IssueID: TS-R-DF-110743, IOVDEV-35777Change-Id: I66f29f5ff48eb981d5acec82d0b975543a4ef913(cherry picked from commit a7dc4af421b6f4107eefdf3fe0c18e654a54dcb7)			

#10 - 2023-07-11 14:59 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213816	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Notification: Fix silent header view height problem.TC-RID: 1201-0201902IssueID: TS-R-DF-110743, IOVDEV-35777Change-Id: Ie987369dd597dfb8a5b01763546a21952a127620			

#11 - 2023-07-12 20:20 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
214369	general/platform/packages/modules/Wifi	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
FW:Notification: change the attribute name of the debugging mode.TC-RID: 1201-0201902IssueID: TS-R-DF-110743Change-Id: I6e8939dd541b72cead7c04c42b987f3bc1535920			

#12 - 2023-07-13 21:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
214540	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Notification: Fix silent header view height problem.TC-RID: 1201-0201902IssueID: TS-R-DF-110743, IOVDEV-35777Change-Id: le987369dd597dfb8a5b01763546a21952a127620(cherry picked from commit 36df121f1d45e72d2c62744f1596f954bb70033d)			

#13 - 2023-07-13 21:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
214749	general/platform/packages/modules/ Wifi	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
FW:Notification: change the attribute name of the debugging mode.TC-RID: 1201-0201902IssueID: TS-R-DF-110743Change-Id: l6e8939dd541b72cead7c04c42b987f3bc1535920(cherry picked from commit dfd753bdc3b9c7d15ecd6dac036388bcb322d5aa)			

#14 - 2023-07-18 19:23 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
215788	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:Notification: add log for IOVDEV-36323.TC-RID: 1201-0201902IssueID: TS-R-DF-110743, IOVDEV-36323Change-Id: Id0dc94d54410da97df48cf57abf3b37432fc3b82			

#15 - 2023-07-19 19:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216143	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	lukf0916@thundersoft.com
AF:Notification: fix heads up show as fullscreenTC-RID: 1201-0201902IssueID: TS-R-DF-110743, IOVDEV-37498Change-Id: l43642d3a79e4fe439ca1d8bd1297aca0afcaa76b			

#16 - 2023-07-19 23:54 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
216243	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Notification: add log for IOVDEV-36323.TC-RID: 1201-0201902IssueID: TS-R-DF-110743, IOVDEV-36323Change-Id: Id0dc94d54410da97df48cf57abf3b37432fc3b82(cherry picked from commit d828f536cc21f49c9e43b0fc00e756baffe68b67)			

#17 - 2023-07-20 23:29 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216510	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Notification: fix headsup show as fullscreenTC-RID: 1201-0201902IssueID: TS-R-DF-110743, IOVDEV-37498Change-Id: I43642d3a79e4fe439ca1d8bd1297aca0afcaa76b(cherry picked from commit eb349c0231595aa17fc13589795e82e392e9e9f4)			

#18 - 2023-07-24 11:32 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216811	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
AF:Notification: update headsup notification animationTC-RID: 1201-0201902IssueID: TS-R-DF-110743,IOVDEV-35406Change-Id: Ib66cfbf0d088f10bfe5f071ffc7130bb229dd018			

#19 - 2023-07-25 15:21 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
217402	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Swiping notifications is disabled when the quick settings are not expanded.TC-RID: 1201-0201902IssueID: TS-R-DF-110743, IOVDEV-35405Change-Id: Id7bb6f0a032ed4f82071900a85e15fdc66b132e1			

#20 - 2023-07-26 16:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
217550	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com

AF:Notification: update headsup animationupdate headsup notification clip when scroll in launcherTC-RID: 1201-0201902IssueID:
TS-R-DF-110743,IOVDEV-35406Change-Id: leed3f9d7525e25132272cbf3c042e1c08873c61a

#21 - 2023-07-27 23:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218210	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Notification: Swiping notifications is disabled when the quick settings are not expanded.TC-RID: 1201-0201902IssueID: TS-R-DF-110743, IOVDEV-35405Change-Id: Id7bb6f0a032ed4f82071900a85e15fdc66b132e1(cherry picked from commit 3b50485e1382d190767ae0d018825f814c7958dd)			

#22 - 2023-07-27 23:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218307	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Notification: update headsup notification animationTC-RID: 1201-0201902IssueID: TS-R-DF-110743,IOVDEV-35406Change-Id: Ib66cfbf0d088f10bfe5f071ffc7130bb229dd018(cherry picked from commit eb448d38f158127553f8e6c7b73f666df3bd202c)			

#23 - 2023-07-31 18:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218910	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	lukf0916@thundersoft.com
AF:Notification: unpin headsup when expanding startedTC-RID: 1201-0201902IssueID: TS-R-DF-110743,IOVDEV-35406Change-Id: I240107e23d109e841fa13bebec46f8b43299ac7d			

#24 - 2023-08-01 22:23 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
219408	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com

AF:Notification: unpin headsup when expanding startedTC-RID: 1201-0201902IssueID: TS-R-DF-110743,IOVDEV-35406Change-Id: I240107e23d109e841fa13bebec46f8b43299ac7d(cherry picked from commit 3b59674fa4382852cdec8ee031b8ae1df00058e)

#25 - 2023-08-30 15:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
307849	general/platform/packages/modules/Wifi	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
FW:Notification: Limite hotspot time out notificatonTC-RID: 1201-0201902IssueID: TS-R-DF-110743Change-Id: Ic991083915961967da419ab4c13a01b8618bc7d5			

#26 - 2023-08-31 23:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
308777	general/platform/packages/modules/Wifi	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:Notification: Limite hotspot time out notificatonTC-RID: 1201-0201902IssueID: TS-R-DF-110743Change-Id: Ic991083915961967da419ab4c13a01b8618bc7d5(cherry picked from commit aa53ab9d1595fe86f18a7a49fb9a05243df90256)			

#27 - 2023-09-12 13:41 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
311819	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Force the notification to be dismissible.TC-RID: 1201-0201902IssueID: TS-R-DF-110743Change-Id: I7f3bce5a0956d32a5fef22439ec870412b228f68			

#28 - 2023-09-13 16:39 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
312442	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:SystemUI:resolve the gesture conflict between expansion systemui panelview and system global gestureTC-RID: 0012-0201902IssueID: TS-R-DF-110743 , IOVDEV-41281 , IOVDEV-41123Change-Id: Ibd64543fb67dfd7de550f98fa520cf9bcf344dc4			

Gerrit Merge Information :

ID	Project	Branch	Uploader
317232	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Notification: Force the notification to be dismissible.TC-RID: 1201-0201902IssueID: TS-R-DF-110743Change-Id: I7f3bce5a0956d32a5fef22439ec870412b228f68(cherry picked from commit 950866b8e46209714e6d9729e5222153fa0839c5)			

Gerrit Merge Information :

ID	Project	Branch	Uploader
317326	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:SystemUI:resolve the gesture conflict between expansion systemui panelview and system global gestureTC-RID: 0012-0201902IssueID: TS-R-DF-110743 , IOVDEV-41281 , IOVDEV-41123Change-Id: Ibd64543fb67dfd7de550f98fa520cf9bcf344dc4(cherry picked from commit 29722d9b1db25ccd9b7f9b4b694345fa12bf1186)			